6TL096J8Z3

19-02393

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Overric	de Primary Crash	Document #	Agency 19-023	Crash Number 93	Investigating			NBERGER			
23 Z	Crash Date 02/27/2019	Crash Time 12:07 AM			Date Arrived 02/27/2019		Time Arrived 12:21 AM					
	Date Notified 02/27/2019	Time Notified 12:09 AM		Total U 01	nits	Total Injured		Total Kille 00	d			
6TL096J8Z3	On Emergency	Hit and Run	Lane Clos	ure	Work Zone		r or To	owed	Reporting			
6TL	Government Property	Active S	chool Zone	School NO	Bus Related	Tags						
	Reportable	Crash Type DT4000 (ST	ANDARD CRASH	H)		Amen	ded		Secondary Crash			
	Description Diagram											
		not to	scale		unit 1		Photo	os By				
	↓ I, a sworn law enfo											

6TL096J8Z3

19-02393

2

UNIT

5

UNIT

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

LOC	ation									
ON TERRYTOWN RD					Latitude		Longitude			
519 FT W					43.485537281		-89.769318031			
	OF OLDE SAWMILL RD					X Coordinate		Y Coordinate		
	IN THE VILLAGE OF WEST BARABOO IN SAUK COUNTY					276058.1875 4818461				
	IN SAUK COUNTY					Structure Type				
Cra	sh Scene 📃									
First	Harmful Event			First Har	nful Event	Location				
DIT	СН			SHOUL	SHOULDER RIGHT					
Man	ner of Collision			Light Cor	Light Condition					
NO	COLLISION W/VEHIC	LE IN TRANSPORT		DARK/U	DARK/UNLIT					
Roa	d Surface Condition(s)			Roadway	Factor(s)					
SNO	w									
Envi	ronment Factor(s)									
	. ,	ANIMAL (S) IN ROADWA	v		SURFACE		I (WET, IC	CY, SNOW, SLUSH,		
				ETC)						
Wea	ther Condition(s)									
SNO	W									
Anim	nal Type			Relation	Relation To Trafficway					
				TRAFF	CWAY - Q	ON ROAD				
	h Classification - Location					- Jurisdiction				
	BLIC PROPERTY				NO SPECIAL JURISDICTION					
Triba	al Land			Access Control		Special Study		Special Study		
					NO CONTROL					
NO NO	in Interchange Area	Junction Location NON-JUNCTION		Intersection Type NOT AN INTERS						
_				NOT AN INTERS						
	Unit Summary									
111-0-14			Vahiele One	rating As Classificatio	2	11 X T				
	Status			rating As Classificatio	n	Unit Type				
IN T	Status RANSIT		Vehicle Ope	rating As Classificatio	n	AUTOMO		ments		
IN T Vehi	Status RANSIT cle Type	E		rating As Classificatio	n			ments		
IN T Vehi (SP	Status RANSIT	.E Train/Bus # Recorded			n Total Tra	AUTOMO Operating A	s Endorse	ments Mat Types		
IN T Vehi (SP	Status RANSIT cle Type ORT) UTILITY VEHICL		D CLASS			AUTOMO Operating A	s Endorse			
IN T Vehi (SP Tota 1	Status RANSIT cle Type ORT) UTILITY VEHICL		D CLASS Total # Citat 1		Total Tra	AUTOMO Operating A ailers	As Endorse	Mat Types		
IN T Vehi (SP Tota 1	Status TRANSIT Cle Type ORT) UTILITY VEHICL I Occs	Train/Bus # Recorded	D CLASS	ions Issued	Total Tra	AUTOMO Operating A ailers imit	Total Haz 0 7 Total Lan	Mat Types es		
IN T Vehi (SP Tota 1 Insu NO	Status (RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? t Harmful Event: Collision \	Train/Bus # Recorded Direction Of Travel WESTBOUND	D CLASS	ions Issued CrashTire Mark ction	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency	s Endorser Total Haz 0 Total Lan 2 Motor Veh	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos ^o	Status (RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? : Harmful Event: Collision 1 CH	Train/Bus # Recorded Direction Of Travel WESTBOUND	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP	s Endorser Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Most DIT Traff	Status (RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? : Harmful Event: Collision 1 CH ic Way	Train/Bus # Recorded Direction Of Travel WESTBOUND	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION	Total Tra 0 Speed L	AUTOMO Operating / ailers imit Emergency NOT APP Traffic Con	s Endorser Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Most DITO Traff	Status (RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? : Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel WESTBOUND	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL	Total Tra 0 Speed L	AUTOMO Operating / aillers imit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos ^o DIT Traff TWC Surfa	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? I Harmful Event: Collision ¹ CH ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos ^s DIT Traff TW(Surfa BLA	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture	Total Tra 0 Speed L	AUTOMO Operating / aillers imit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos ^s DIT Traff TW(Surfa BLA	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? I Harmful Event: Collision ¹ CH ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos DIT Traff TWC Surfa BL/ Truc NO	Status (RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? t Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos DIT Traff TWC Surfa BL/ Truc NO	Status (RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? I Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture T	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos DIT Traff TWC Surfa BL/ Truc NO	Status (RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? t Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture T	Total Tra 0 Speed L 25	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Most DIT Traff TW(Surfr BL/ Truc NO	Status (RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel WESTBOUND With S)	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture T	Total Tra 0 Speed L 25	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos DIT Traff TWC Surfa BL/ Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? I Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ABW3717	Train/Bus # Recorded Direction Of Travel WESTBOUND With S)	D CLASS	ions Issued CrashTire Mark ction IAL FUNCTION rol ROL ture T T	Total Tra 0 Speed L 25 St WI	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grad LEVEL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera ssuance TATES	Mat Types es icle Use		
IN T Vehii (SP Tota 1 Insu NO Most DIT(Traff Tw(Surfr BL/ Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICL OCCS rance? Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type CKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ABW3717 Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel WESTBOUND With S)	D CLASS	ions Issued CrashTire Mark Ction IAL FUNCTION rol ROL ture T T TOMOBILE LET	Total Tra 0 Speed L 25 St WI Year 2015	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model TRAX LTZ Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera ssuance TATES A	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos DITU Traff BL/ Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICL OCCS Tance? E Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ABW3717 Vehicle Identification Nur KL7CJTSB4FB16807 Color	Train/Bus # Recorded Direction Of Travel WESTBOUND With S)	D CLASS Total # Citat 1 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style UT - SPO	ions Issued CrashTire Mark Ction IAL FUNCTION rol ROL ture T ITOMOBILE LET RT UTILITY VEHIC	Total Tra 0 Speed L 25 St WI Year 2015	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grad LEVEL Country of Is UNITED S Model TRAX LTZ	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera ssuance TATES A	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos DITU Traff BL/ Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICL OCCS Tance? Tharmful Event: Collision N CH TCH TCH TCH TCH TCH TCH TCH CKTOP (BITUMINOU TCH	Train/Bus # Recorded Direction Of Travel WESTBOUND With S)	D CLASS	ions Issued CrashTire Mark Ction IAL FUNCTION rol ROL ture T ITOMOBILE LET RT UTILITY VEHIC	Total Tra 0 Speed L 25 St WI Year 2015	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model TRAX LTZ Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera ssuance TATES A	Mat Types es icle Use		
IN T Vehi (SP Tota 1 Insu NO Mos DITU Traff BL/ Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICL OCCS rance? t Harmful Event: Collision \ CH ic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ABW3717 Vehicle Identification Nur KL7CJTSB4FB16807 Color Initial Contact Point NON-COLLISION	Train/Bus # Recorded Direction Of Travel WESTBOUND With S)	D CLASS Total # Citat 1 Pre 0 Special Fun NO SPEC Traffic Contt NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style UT - SPO Vehicle Da	ions Issued CrashTire Mark Ction IAL FUNCTION rol ROL ture T T TOMOBILE LET RT UTILITY VEHIC mage	Total Tra 0 Speed L 25 St WI Year 2015	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model TRAX LTZ Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera ssuance TATES A	Mat Types es icle Use		
IN T Vehii (SP Tota 1 Insu NO Most DIT(Traff Tw(Surfr BL/ Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICL OCCS Tance? Tance? THARMful Event: Collision N CH TCH TCH TCH TCH TCH CKTOP (BITUMINOU TCH CKTOP (BITUMINOU TCH License Plate Number ABW3717 Vehicle Identification Nur KL7CJTSB4FB16807 Color TInitial Contact Point	Train/Bus # Recorded Direction Of Travel WESTBOUND With S)	D CLASS Total # Citat 1 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style UT - SPO	ions Issued CrashTire Mark Ction IAL FUNCTION rol ROL ture T T TOMOBILE LET RT UTILITY VEHIC mage	Total Tra 0 Speed L 25 St WI Year 2015	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model TRAX LTZ Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera ssuance TATES A	Mat Types es icle Use		

19-02393

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage	Vehicle Removed By						
		NOT TOWED	OPERATOR						
		What Driver Was Doing	Vehicle Factors						
		GOING STRAIGHT	NOT APPLICABLE						
		Driver Prior Action Other							
		Driver Actions							
	ш	Driver Actions SWERVED OR AVOIDED DUE TO WIND, SLIPPERY SURFACE, MOTOR VEHICLE, OBJECT, NON-MOTORIST IN ROADWAY, ETC.							
E	СГ	,, ,, , , ,							
UNIT	VEHICLE								
_	×Ε								
		-							
		Owner Name ALANA MARY DLASK	Owner Address 1201 CONNIE RD # 4						
2	01	(608) 477-2646	BARABOO, WI 53913 , US						
	ļ	Sequence Of Events							
	01	Event							
	0	DITCH							
	02	Event							
	03	Event							
	4	Event							
	04								
	I	Individual							
			Citations Issued	Sex					
	٦L	ALANA MARY DLASK (608) 477-2646	1	FEMALE					
Ŀ	INDIVIDUAL		Date of Birth	Race WHITE					
UNIT		Address 1201 CONNIE RD # 4	Driver License Number						
	Z	BARABOO, WI 53913 , US	STATE: WISCONSIN COUNTRY: UNITED STATES						
		On Duty Crash	Safety Equipment						
	Sat	fety Equipment							
		Seat Position	SHOULDER & LAP BELT						
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Halmat Compliance					
	E	Helmet Use	Helmet Compliance						
		Eye Protection	Tint Compliance						
-		Injury Severity	Airbag						
6	001	Injury NO APPARENT INJURY	NON DEPLOYED						
		Ejected Ejection Path	Trapped/Extricated						
		NOT EJECTED NOT EJECTED/NOT APP Medical Transport							
		NOT TRANSPORTED	EMS Agency Identifier	EMS Run #					
		Hospital	Date of Death	Time of Death					
	Distracted By Source NOT APPLICABLE (NOT DISTRACTED)								
		Distracted By Action NOT DISTRACTED							
		Non Motorist Striking Unit # Location							

6TL096J8Z3

19-02393

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action						
		Action						
	AL							
UNIT	INDIVIDUAL							
5	DIV							
	Z							
		Action Other						To/From School
	L	Drug & Alcohol	Suspected Alco	hol Use	Suspected Drug Use			
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results	
		TEST NOT GIVEN Drug Test Given		Drug Test Type		Drug Test Results		
		TEST NOT GIVEN		Drug rest rype		Drug Test Results		
2	001	Drug Type						
•	0							
		Individual Condition						
		APPEARED NORM						
		Violations						
	01	UTC Number BB954527	Issue To? 001	Statute Number 344.62(1)	Description OPERATE MOTOR	VEHICLE W/O IN	SURANCE	