

6TL092T5N5

19-02508

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

| | | |
|--|---------------------------------------|-----------------------------------|
| ON TOWER RD 1.12 MI W OF DURWARD GLENN RD IN THE TOWN OF GREENFIELD IN SAUK COUNTY | Latitude 43.43129249 | Longitude -89.606194828 |
| | X Coordinate 289061.0625 | Y Coordinate 4812010.5 |
| | Structure Type NO STRUCTURE | |

Crash Scene

| | | |
|---|---|---|
| First Harmful Event DITCH | First Harmful Event Location ROADSIDE | |
| Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT | Light Condition DARK/UNLIT | |
| Road Surface Condition(s) SNOW, ICE | Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC) | |
| Environment Factor(s) WEATHER CONDITIONS | | |
| Weather Condition(s) SNOW | | |
| Animal Type | Relation To Trafficway TRAFFICWAY - ON ROAD | |
| Crash Classification - Location PUBLIC PROPERTY | Crash Classification - Jurisdiction NO SPECIAL JURISDICTION | |
| Tribal Land | Access Control NO CONTROL | Special Study |
| Within Interchange Area NO | Junction Location NON-JUNCTION | Intersection Type NOT AN INTERSECTION |

Unit Summary

| | | | | | | |
|-------------|---|---|--|--|--------------------------------|--|
| UNIT | Unit Status IN TRANSIT | Vehicle Operating As Classification B CLASS | | Unit Type BUS | | |
| | Vehicle Type PASSENGER BUS/TRANSIT BUS | Operating As Endorsements | | | | |
| | Total Occs 1 | Train/Bus # Recorded 1 | Total # Citations Issued 0 | Total Trailers 0 | Total HazMat Types 0 | |
| | Insurance? UNKNOWN | Direction Of Travel WESTBOUND | <input type="checkbox"/> Pre Crash Tire Mark | Speed Limit 45 | Total Lanes 2 | |
| | Most Harmful Event: Collision With DITCH | Special Function VEHICLE USED AS OTHER BUS | | Emergency Motor Vehicle Use NOT APPLICABLE | | |
| | Traffic Way TWO-WAY, NOT DIVIDED | Traffic Control NO CONTROL | | Traffic Control Inoperative/Missing NO | | |
| | Surface Type CONCRETE | Road Curvature CURVE RIGHT | | Road Grade UPHILL | | |
| | Truck Bus or HazMat VEHICLE DESIGNED TO CARRY 9 OR MORE PPL, INCLUDING DRIVER | | | | | |

| | | | | | |
|-------------|----------------|---|--------------------------------|---------------------|---|
| UNIT | VEHICLE | Vehicle | | | |
| | | License Plate Number P897211 | Plate Type BUS - BUS | St IL | Country of Issuance UNITED STATES |
| | | Vehicle Identification Number 1M83JMPA63P061964 | Make MCI | Year 2003 | Model J4500 |
| | | Color WHI - WHITE | Body Style BU - BUS | | Bus Use CHARTER/TOUR |
| | | Initial Contact Point 7--LEFT REAR CORNER | Vehicle Damage | | |
| | | Extent Of Damage NO DAMAGE | NO DAMAGE | | |

6TL092T5N5

19-02508

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

| | | | | | |
|---|---|---|--|--|----------------------|
| UNIT VEHICLE | Towed Due To Damage NOT TOWED | | Vehicle Removed By BLYSTONES TOWING | | |
| | What Driver Was Doing NEGOTIATING CURVE | | Vehicle Factors | | |
| | Driver Prior Action Other | | NOT APPLICABLE | | |
| | Driver Actions NO CONTRIBUTING ACTION | | | | |
| 01 01 | Owner Name SPIRIT TOURS GLOBAL INC (773) 731-1400 | | Owner Address 7953 S BENNETT CHICAGO, IL 60617 , US | | |
| | Sequence Of Events | | | | |
| 01 01 | 01 | Event DITCH | | | |
| | 02 | Event | | | |
| | 03 | Event | | | |
| | 04 | Event | | | |
| UNIT INDIVIDUAL | Individual | | | | |
| | 01 001 | Driver DAMARI I GIBSON (708) 238-4084 | | Citations Issued 0 | Sex MALE |
| | | Address 7953 S BENNETT AVE CHICAGO, IL 60617 , US | | Date of Birth | Race BLACK |
| | On Duty Crash | | Driver License Number STATE: ILLINOIS COUNTRY: UNITED STATES | | |
| Safety Equipment | | Safety Equipment SHOULDER & LAP BELT | | | |
| 01 001 | Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY | | Helmet Compliance | | |
| | Helmet Use | | Tint Compliance | | |
| | Eye Protection | | Airbag NON DEPLOYED | | |
| | Injury | | Injury Severity NO APPARENT INJURY | Trapped/Extricated NOT TRAPPED | |
| Ejected NOT EJECTED | | Ejection Path NOT EJECTED/NOT APPLICABLE | | EMS Agency Identifier | |
| Medical Transport NOT TRANSPORTED | | Hospital | | EMS Run # | |
| Distracted By NOT DISTRACTED | | Date of Death | | Time of Death | |
| Distracted By | | Distracted By Source NOT APPLICABLE (NOT DISTRACTED) | | | |
| Distracted By Action NOT DISTRACTED | | Striking Unit # | | | |
| Non Motorist | | Location | | | |

6TL092T5N5

19-02508

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

| | | | | | | |
|---|----------------------------|--|---|--|--|---|
| UNIT | INDIVIDUAL | Prior Action | | | | |
| | | Action | | | | |
| | | Action Other | | | To/From School | |
| | 01 | 001 | Drug & Alcohol | | Suspected Alcohol Use NO | Suspected Drug Use NO |
| | | | Alcohol Test Given TEST NOT GIVEN | Alcohol Test Type | Alcohol Test Results | |
| | | | Drug Test Given TEST NOT GIVEN | Drug Test Type | Drug Test Results | |
| | | | Drug Type | | | |
| | | | Individual Condition APPEARED NORMAL | | | |
| | UNIT | TRUCK BUS | Carrier | | | |
| | | | <input checked="" type="checkbox"/> Use Vehicle Owner Same as Carrier | Source VEHICLE-SIDE | | |
| Name SPIRIT TOURS GLOBAL INC USDOT# 1048314 | | | Address 7953 S BENNETT CHICAGO, IL 60617 , US | | | |
| GVWR MORE THAN 26,000 LB | | | Vehicle Configuration SINGLE UNIT TRUCK (3 OR MORE AXLES) | Cargo Body Type BUS (SEATS FOR MORE THAN 15 OCCUPAN | | |
| US DOT # 1048314 | | | Carrier Type INTERSTATE CARRIER | Permitted Load NOT APPLICABLE | | |
| <input type="checkbox"/> OS/OW Load | | | WI Permit Number | <input type="checkbox"/> Permitted Vehicle On Permitted Route | <input type="checkbox"/> Escort Vehicle Required By Permit | <input type="checkbox"/> Escort Vehicle Present |
| Measured Height | | | Measured Length | Measured Width | Measured Weight | |
| PROP OWNER | 01 | Government TOWNSHIP OF GREENFIELD (608) 355-3040 | | Address S4285 MANMOUND RD BARABOO, WI 53913 , US | | |
| | | Fixed Objects Struck | | | | |
| 01 | Striking Unit 01 | Struck Object DITCH | Structure Number | Damage Tag Number 0000 | | |