

6TL0BJ1GHV
19-02430

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON CTHBD SB 188 FT N OF COOP LN IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.525670682	Longitude -89.777905107
	X Coordinate 275512.65625	Y Coordinate 4822941.5
	Structure Type	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/UNLIT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification A CLASS	Unit Type TRUCK		
	Vehicle Type TRUCK TRACTOR (SEMI ATTACHED)	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 1	Total HazMat Types 0
	Insurance? YES	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With DITCH	Special Function		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat TRUCK OR TRUCK COMBINATION > 10,000LBS GVWR/GCWR				

UNIT 01 VEHICLE	Vehicle			
	License Plate Number P971020	Plate Type APO - APPORTIONED	St IL	Country of Issuance UNITED STATES
	Vehicle Identification Number 3AKJGLD54FSFP6754	Make	Year 2015	Model
	Color	Body Style		Bus Use NOT A BUS
	Initial Contact Point NON-COLLISION	Vehicle Damage		
Extent Of Damage NO DAMAGE	NO DAMAGE			

6TL0BJ1GHV

19-02430

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By BILLS TOWING		
	What Driver Was Doing U TURN		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions IMPROPER TURN				
01	01	Owner Name MG LOGISTICS INC (847) 621-3399		Owner Address 10900 BELMONT AVE SUITE 400 FRANKLIN PARK, IL 60131 , US	
Sequence Of Events					
	01	Event DITCH			
	02	Event			
	03	Event			
	04	Event			
UNIT	Policy Holder				
	Insurance Company MILWAUKEE CASUALTY INSURANCE			Organization/Company MG LOGISTICS INC	
UNIT TRAILER/ TOWED	Trailer/Towed				
	Trailer Plate # 662780ST	Plate Type TRL - TRAI	Make	State IL	Country of Issuance UNITED STATES
	Unit Type UTILITY TRAILER	Organization/Company MG LOGISTICS INC (847) 621-3399			Address 10900 BELMONT AVE SUITE 400 FRANKLIN PARK, IL 60131 , US
	Vehicle Identification Number 1UYVS2538K2591024				
UNIT INDIVIDUAL	Individual				
	Driver DJIBRILLA HASSANE (336) 803-5467		Citations Issued 0		Sex MALE
	Address 334 BURLINGATE DR APT B GREENSBORO, NC 27407 1265, US		Date of Birth Race BLACK		
Driver License Number STATE: NORTH CAROLINA COUNTRY: UNITED STATES					
UNIT 001	Safety Equipment		On Duty Crash		
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	

6TL0BJ1GHV

19-02430

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
	Hospital		Date of Death	Time of Death	
	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
	Distracted By Action NOT DISTRACTED				
	Non Motorist		Striking Unit #	Location	
	Prior Action				
	Action				
	Action Other			To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results		
01	Drug Type				
	Individual Condition APPEARED NORMAL				
	Carrier				
	<input checked="" type="checkbox"/> Use Vehicle Owner Same as Carrier		Source DRIVER		
01	Name MG LOGISTICS INC USDOT# 1346846		Address 10900 BELMONT AVE SUITE 400 FRANKLIN PARK, IL 60131 , US		
	GVWR MORE THAN 26,000 LB		Vehicle Configuration TRUCK TRACTOR/SEMI-TRAILER	Cargo Body Type	
UNIT	US DOT # 1346846		Carrier Type INTERSTATE CARRIER	Permitted Load	
	<input type="checkbox"/> OS/OW Load	WI Permit Number	<input type="checkbox"/> Permitted Vehicle On Permitted Route	<input type="checkbox"/> Escort Vehicle Required By Permit	<input type="checkbox"/> Escort Vehicle Present
	Measured Height		Measured Length	Measured Width	Measured Weight