

6TL0BNZLZ9

19-02788

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0BNZLZ9

Document Number Override		Primary Crash Document #		Agency Crash Number 19-02788		Investigating Officer/Deputy DEPUTY A. BREUNIG	
Crash Date 03/09/2019		Crash Time 03:30 PM		Date Arrived 03/09/2019		Time Arrived 03:32 PM	
Date Notified 03/09/2019		Time Notified 03:32 PM		Total Units 02		Total Injured 02	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p> <p>DRIVEWAY TO E9905</p> <p>STH 33</p> <p>02 1</p> <p>1</p> <p>2</p> <p>NOT TO SCALE</p>	Reconstruction By
	Photos By B SCHLOUGH
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT WAS TRAVELING WESTBOUND ON STH 33. UNIT 2 WAS TRAVELING WESTBOUND BEHIND UNIT 1. UNIT 1 WAS DELIVERING MAIL AND WAS MAKING A STOP AT E9905 STH 33. UNIT 1 WAS SLOWING TO MAKE A LEFT TURN INTO THE DRIVEWAY. UNIT 2 REAR ENDED UNIT 1. UNIT 1 WAS ABLE TO DIVE FORWARD AND STOP ON THE SHOULDER. UNIT 2 TRAVELED OFF THE ROAD INTO THE DITCH. THE OPERATOR OF UNIT 1 STATED THAT HE WAS BRAKING AND HAD HIS LEFT TURN SIGNAL ON. HE STATED THAT HE SAW UNIT 2 NOW SLOWING. UNIT 1 OPERATOR STATED HE ACCELERATED QUICKLY TO AVOID GETTING REAR ENDED. UNIT 2 OPERATOR STATED THAT SHE DID NOT SEE THE BRAKE LIGHTS OR TURN SIGNAL. SHE DENIED USING HER PHONE AT THE TIME. UNIT 1'S BRAKE AND TURN SIGNALS WERE OPERATIONAL WHEN I CHECKED THEM.

6TL0BNZLZ9

19-02788

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON E9905 STH33 WB 0.54 MI E OF MIRROR LAKE RD (FIRE E9905) IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.5218187	Longitude -89.827578706
	X Coordinate 271483.71875	Y Coordinate 4822649
	Structure Type FIRE	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ON ROADWAY	
Manner of Collision 02--FRONT TO REAR	Light Condition DAYLIGHT	
Road Surface Condition(s) WET	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) RAIN		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE			Operating As Endorsements		
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

UNIT 01 VEHICLE	Vehicle				
	License Plate Number 548ZWW	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
	Vehicle Identification Number 1J4BZ3H14BL614719	Make JEEP	Year 2011	Model WRANGLER U	
	Color WHI - WHITE	Body Style UT - SPORT UTILITY VEHICLE		Bus Use NOT A BUS	
	Initial Contact Point 6--REAR	Vehicle Damage 6--REAR			
Extent Of Damage FUNCTIONAL DAMAGE					

6TL0BNZLZ9

19-02788

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OWNER		
	What Driver Was Doing SLOW/STOPPING		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
01	01	Owner Name CHAD ENNIS (608) 393-5675		Owner Address 323 LYNN AVE BARABOO, WI 53913 , US	
Sequence Of Events					
01	01	Event MOTOR VEH IN TRANSPORT			
02	02	Event			
03	03	Event			
04	04	Event			
UNIT	Policy Holder				
	Insurance Company PROGRESSIVE-CLASSIC-INS-CO		Individual CHAD ENNIS		
UNIT INDIVIDUAL	Individual				
	Driver CHAD ENNIS (608) 393-5675		Citations Issued 0	Sex MALE	
	Address 323 LYNN AVE BARABOO, WI 53913 , US		Date of Birth	Race WHITE	
	Driver License Number		STATE: WISCONSIN COUNTRY: UNITED STATES		
UNIT INDIVIDUAL	Safety Equipment		On Duty Crash		
	Seat Position 3--FRONT SEAT-RIGHT SIDE (TRAIN ENGINEER		Safety Equipment SHOULDER & LAP BELT		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
	01	001	Injury		Airbag
			Injury Severity POSSIBLE INJURY	NON DEPLOYED	
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action NOT DISTRACTED					

6TLOBNZLZ9

19-02788

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT INDIVIDUAL 01 001	Non Motorist	Striking Unit #	Location		
	Prior Action				
	Action				
	Action Other			To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
	Drug Type				
	Individual Condition APPEARED NORMAL				

Unit Summary

UNIT 02 02 VEHICLE	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 2	Total Trailers 0	Total HazMat Types 0	
	Insurance? UNKNOWN	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					
	Vehicle					
	License Plate Number ADZ5040		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
Vehicle Identification Number 4T1BG12K7TU935274		Make TOYOTA	Year 1996	Model CAMRY DX/L		
Color GRN - GREEN		Body Style 4D - 4DR		Bus Use NOT A BUS		
Initial Contact Point 12--FRONT		Vehicle Damage 1--RIGHT FRONT CORNER, 11--LEFT FRONT CORNER, 12--FRONT				
Extent Of Damage DISABLING DAMAGE						
Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By BILLS TOWING				

6TL0BNZLZ9

19-02788

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	What Driver Was Doing GOING STRAIGHT	Vehicle Factors	
	Driver Prior Action Other	NOT APPLICABLE	
	Driver Actions FAILURE TO CONTROL, OPERATED MOTOR VEHICLE IN INATTENTIVE, CARELESS OR ERRATIC MANNER		
02 02	Owner Name CAROLE GIBSON (608) 415-7804	Owner Address 400 LAVALLE ST REEDSBURG, WI 53959 , US	
	Sequence Of Events		
01 02 03 04	Event MOTOR VEH IN TRANSPORT		
	Event RUN OFF ROADWAY RIGHT		
	Event		
	Event		
UNIT INDIVIDUAL	Individual		
	Driver DEIDRA GIBSON (608) 415-7804	Citations Issued 2	Sex FEMALE
	Address 400 LAVALLE ST REEDSBURG, WI 53959 , US	Date of Birth	Race WHITE
	Driver License Number	STATE: WISCONSIN COUNTRY: UNITED STATES	
02 002	Safety Equipment	On Duty Crash	Safety Equipment
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY	SHOULDER & LAP BELT	
	Helmet Use	Helmet Compliance	
	Eye Protection	Tint Compliance	
	Injury	Injury Severity SUSPECTED MINOR INJURY	Airbag DEPLOYED-FRONT
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
	Medical Transport OTHER	EMS Agency Identifier	EMS Run #
	Hospital REEDSBURG AREA MED CTR	Date of Death	Time of Death
	Distracted By	Distracted By Source	
	Distracted By Action UNKNOWN		
	Non Motorist	Striking Unit #	Location
	Prior Action		

6TL0BNZLZ9

19-02788

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	INDIVIDUAL	Action				
		Action Other			To/From School	
	02	002	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
			Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results
			Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results
			Drug Type			
			Individual Condition APPEARED NORMAL			
			Violations			
	02	01	UTC Number AE753161	Issue To? 002	Statute Number 346.89(1)	Description INATTENTIVE DRIVING
			UTC Number AE753162	Issue To? 002	Statute Number 344.62(1)	Description OPERATE MOTOR VEHICLE W/O INSURANCE