6TL09T1TN5 19-02805

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override			Agency Crash Number 19-02805		Investigating Officer/Deputy DEPUTY J. BODDEN			
S	Crash Date 03/09/2019	Crash Time 05:30 PM			rived 2019	Time Arrived 06:27 PM Total Injured 00 Total Killed 00			
CNILIENTIO	Date Notified 03/09/2019				nits			ed	
80-	On Emergency	it and Run	Lane Close	ure	☐ Work Zone	Trailer	or Towed	Reporting Threshold	
110	Government Property	Active So	hool Zone	School NO	Bus Related	Tags			
	Reportable	Crash Type DT4000 (STA	Crash Type DT4000 (STANDARD CRASH)				Amended Second		
İ	Description	•							
	Diagram						Reconstruction	тву	
							Photos By		
							Additional Info	rmation	
	✓ I, a sworn law enforcement	ent officer, agre	ee that I have no	ot added	d any CJIS data in th	nis report.			
•	NON-REPORTABLE ACCIDENT								

6TL09T1TN5 19-02805

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 03/09/2019

Crash Time 05:30 PM

I	Loc	ation								
·	PAF	KING LOT		Latitude			Longitude			
	8TH	AVE/ STH33 EB LOT			43.475569679			-89.759294995		
		HE VILLAGE OF WES	ST BARABOO		X Coordinate 276832				Y Coordinate	
	IN S	SAUK COUNTY						4817327		
							Structure Type			
(Cra	sh Scene				•				
Ī	First	Harmful Event				First Harm	ful Event L	ocation		
	OTH	IER POST, POLE OR	SUPPORT			IN PARK	ING LAN	E OR ZONE		
-	Manı	ner of Collision				Light Condition				
	NO	COLLISION W/VEHIC	LE IN TRANSPORT			DARK/LIGHTED				
-							Factor(s)			
	WET, SNOW, ICE						()			
-	Envi	ronment Factor(s)								
	WE	ATHER CONDITIONS				NONE				
}	Wea	ther Condition(s)								
	SNC	DW .								
ļ	Anim	nal Type			Relation To Trafficway					
-	Cras	h Classification - Location			NON TRAFFICWAY - PARKING LOT Crash Classification - Jurisdiction					
		VATE PROPERTY			PRIVATE PROPERTY					
Ī	Tribal Land							Access Control Special Study NO CONTROL		
-	\//ith	in Interchange Δrea	lunction Location		Intersection					
	Within Interchange Area NO Junction Location NON-JUNCTION Intersection NOT AN I					I INTERSECTION				
	NO		NON-JUNCTION		NOT AN	INTERSE	CTION			
		t Summary	NON-JUNCTION		NOT AN	INTERSE	CTION			
_ 	Jni	t Summary Status	NON-JUNCTION	Vehicle One				Linit Type		
Į	Uni t	Status	NON-JUNCTION	Vehicle Ope	erating As C			Unit Type	BII F	
<u>[</u>	Unit Unit	Status RANSIT	NON-JUNCTION	Vehicle Ope	erating As C			AUTOMOI		
	Unit Unit IN T	Status FRANSIT cle Type			erating As C			AUTOMOI	BILE s Endorsements	
	Unit Unit IN T Vehic	Status RANSIT cle Type ORT) UTILITY VEHIC	LE	D CLASS	erating As C	lassification		AUTOMOI Operating A	s Endorsements	
	Unit Unit IN T Vehic	Status FRANSIT cle Type		D CLASS	erating As C	lassification		AUTOMOI Operating A		
	Unit Unit IN T Vehic (SPC) Total	Status RANSIT cle Type ORT) UTILITY VEHIC	LE	Total # Cita	erating As C	lassification	Total Tra	AUTOMOI Operating A	s Endorsements	
10	Unit Unit IN T Vehic (SPC) Total	Status RANSIT cle Type ORT) UTILITY VEHIC	LE Train/Bus # Recorded	Total # Cita	erating As C	lassification	Total Tra	AUTOMOI Operating A	s Endorsements Total HazMat Types	
10	Unit Unit IN T Vehic (SPC Total 1 Insur NO	Status RANSIT cle Type ORT) UTILITY VEHIC	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND	Total # Cita	erating As C tions Issued CrashTire Mark	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A illers mit Emergency	Total HazMat Types Total Lanes 0 Motor Vehicle Use	
10	Unit Unit IN T Vehic (SPC Total 1 Insur NO	Status RANSIT cle Type ORT) UTILITY VEHIC I Occs rance?	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun	erating As C tions Issued CrashTire Mark	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A	Total HazMat Types Total Lanes 0 Motor Vehicle Use	
I.O.	Unit Unit Vehic (SPC Total 1 Insur NO Most	Status RANSIT cle Type ORT) UTILITY VEHIC! I Occs rance?	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun	crating As C tions Issued CrashTire Mark action	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A silers mit Emergency NOT APPI	Total HazMat Types Total Lanes 0 Motor Vehicle Use	
5	Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff	Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance? Harmful Event: Collision HER POST, POLE OR ic Way RKING LOT OR PRIVA	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT	Total # Cita 0 Pre Special Fun	tions Issued CrashTire Mark action EIAL FUNC	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A silers mit Emergency NOT APPI	Total HazMat Types Total Lanes 0 Motor Vehicle Use LICABLE	
5	Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff	Status RANSIT cle Type ORT) UTILITY VEHIC! I Occs rance? t Harmful Event: Collision HER POST, POLE OR ic Way	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	crating As C tions Issued CrashTire Mark iction CIAL FUNC	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Control	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE fol Inoperative/Missing	
5	Unit Unit Unit Vehi (SPC Total 1 Insur NO Most OTH Traff PAR Surfa	Status RANSIT cle Type ORT) UTILITY VEHIC Cle Type LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT	crating As C tions Issued CrashTire Mark iction CIAL FUNC	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE fol Inoperative/Missing		
5	Unit Unit Unit Vehi (SPC Total 1 Insur NO Most OTH Traff PAR Surfa	Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance? t Harmful Event: Collision HER POST, POLE OR ic Way KKING LOT OR PRIVA	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT	crating As C tions Issued CrashTire Mark iction CIAL FUNC	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE fol Inoperative/Missing	
10	Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff PAR Surfa BLA Truck	Status RANSIT cle Type ORT) UTILITY VEHIC Cle Type LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT	crating As C tions Issued CrashTire Mark iction CIAL FUNC	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE fol Inoperative/Missing		
5	Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff PAR Surfa BLA Truck	Status RANSIT Cle Type ORT) UTILITY VEHIC! I Occs rance? I Harmful Event: Collision HER POST, POLE OR IC Way RKING LOT OR PRIVA CACKTOP (BITUMINOU IK Bus or HazMat	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT	crashTire Mark Inction ISIAL FUNC ITAL TROL Ature	lassification	Total Tra 0 Speed Lii	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr	Total HazMat Types Total Lanes Motor Vehicle Use LICABLE Tol Inoperative/Missing	
5	Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff PAR Surfa BLA Truck	Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance? I Harmful Event: Collision HER POST, POLE OR ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crashTire Mark Inction ISIAL FUNC ITAL TROL Ature	assification	Total Tra 0 Speed Lii N/A	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE Tol Inoperative/Missing	
	Unit Unit Unit IN T Vehic (SPC Total 1 Insur NO OTH Traff PAR Surfa BLA Truck NO	Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance? I Harmful Event: Collision HER POST, POLE OR ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT ATE PROPERTY US)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crating As C tions Issued CrashTire Mark citions CIAL FUNC crol ROL ature	assification	Total Tra 0 Speed Lii N/A	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE Tol Inoperative/Missing	
	Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff PAR Surfa BLA Truck	Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance? I Harmful Event: Collision HER POST, POLE OR ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ACX9301	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT ATE PROPERTY US)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva Plate Type AUT - AU Make	crating As C tions Issued CrashTire Mark citions CIAL FUNC crol ROL ature		Total Tra 0 Speed Liu N/A St	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade Country of Is: UNITED ST	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE Tol Inoperative/Missing	
	Unit Unit Unit IN T Vehic (SPC Total 1 Insur NO OTH Traff PAR Surfa BLA Truck NO	Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance? I Harmful Event: Collision HER POST, POLE OR ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number ACX9301 Vehicle Identification Nu	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT ATE PROPERTY US)	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva Plate Type AUT - AU Make KIA MOT Body Style	crashTire Mark Mark Mark Mark Martion Marun Maru	TION E PORA	Total Tra 0 Speed Lii N/A St WI Year 2003	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade Country of Is: UNITED ST Model SORENTO Bus Use	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Jnii Unit Unit IN T Vehic (SPC Total 1 Insum NO OTH Trafff PAR Surfa BLA Truck NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? HARMFUL Event: Collision HER POST, POLE OR IC Way RKING LOT OR PRIVA ACKTOP (BITUMINOU IK Bus or HazMat Vehicle License Plate Number ACX9301 Vehicle Identification Nu KNDJC733X3503272 Color	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT ATE PROPERTY US)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva Plate Type AUT - AU Make KIA MOT Body Style UT - SPO	tions Issued CrashTire Mark Inction IAL FUNC ITOI ITOMOBIL ITOMOB	TION E PORA	Total Tra 0 Speed Lii N/A St WI Year 2003	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr NO Road Grade Country of Is: UNITED ST Model SORENTO	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Jnii Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff BLA Truck NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? HARMIL Event: Collision HER POST, POLE OR IC Way RKING LOT OR PRIVA CACTOP (BITUMINOU IK Bus or HazMat Vehicle License Plate Number ACX9301 Vehicle Identification Nu KNDJC733X3503272 Color Initial Contact Point	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT ATE PROPERTY US)	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva Plate Type AUT - AU Make KIA MOT Body Style	tions Issued CrashTire Mark Inction IAL FUNC ITOI ITOMOBIL ITOMOB	TION E PORA	Total Tra 0 Speed Lii N/A St WI Year 2003	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade Country of Is: UNITED ST Model SORENTO Bus Use	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE rol Inoperative/Missing	
U1 011	Jnii Unit Unit IN T Vehic (SPC Total 1 Insur NO Most OTH Traff BLA Truck NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? Harmful Event: Collision HER POST, POLE OR ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ACX9301 Vehicle Identification Nu KNDJC733X3503272 Color Initial Contact Point 12FRONT	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With SUPPORT ATE PROPERTY US)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva Plate Type AUT - AU Make KIA MOT Body Style UT - SPO Vehicle Da	tions Issued CrashTire Mark Crol FROL STOMOBIL FORS COR CRT UTILIT	TION E PORA	Total Tra 0 Speed Lii N/A St WI Year 2003	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade Country of Is: UNITED ST Model SORENTO Bus Use	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE rol Inoperative/Missing	
UNIT 01 01 01 01 01 01 01 01 01 01 01 01 01	Jnii Unit Unit IN T Vehic (SPC Total 1 Insum NO OTH Trafff PAR Surfa BLA Truck NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? HARMIL Event: Collision HER POST, POLE OR IC Way RKING LOT OR PRIVA CACTOP (BITUMINOU IK Bus or HazMat Vehicle License Plate Number ACX9301 Vehicle Identification Nu KNDJC733X3503272 Color Initial Contact Point	Direction Of Travel SOUTHBOUND With SUPPORT ATE PROPERTY US)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva Plate Type AUT - AU Make KIA MOT Body Style UT - SPO	tions Issued CrashTire Mark Crol FROL STOMOBIL FORS COR CRT UTILIT	TION E PORA	Total Tra 0 Speed Lii N/A St WI Year 2003	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade Country of Is: UNITED ST Model SORENTO Bus Use	Total HazMat Types Total Lanes O Motor Vehicle Use LICABLE rol Inoperative/Missing	

6TL09T1TN5 19-02805

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage		V	ehicle Removed By				
N					OPERATOR				
		What Driver Was Doing		V	Vehicle Factors				
		LEAVING A PARKED POS	A PARKED POSITION						
		Driver Prior Action Other			NOT APPLICABLE				
		Driver Actions							
	ш	SPEED TOO FAST/COND)						
╘	占								
L	VEHICL								
	VE								
		Owner Name			Owner Address				
2	01	SAMANTHA L LUMBY (608) 474-4138			251 E MAIN ST ADAMS, WI 53910 , US				
		(,			, , , , , , , , , , , , , , , , , , , ,				
		Sequence Of Events							
	01	Event OTHER POST, POLE OR	SLIDDODT						
		Event	3011 0111						
	02								
	03	Event							
	4	Event							
	04								
	ı	Individual							
		Driver JOHN H LUMBY JR (920) 891-6709 Address 251 E MAY ST ADAMS, WI 53910 , US			Citations Issued	Sex			
	إ				0	MALE			
_	INDIVIDUAL				Date of Birth	Race WHITE			
L N N	Σ				Driver License Number				
ا ر					STATE: WISCONSIN COUNTRY: UNITED STATES				
		On Duty	Crach		Cofety Favinment				
	Saf	ety Equipment	Clasii		Safety Equipment				
		Seat Position			SHOULDER & LAP BELT				
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use			Helmet Compliance				
		Eye Protection			Tint Compliance				
	_	Injury Se	everity.		Airbag				
5	90		PARENT II	NJURY	NON DEPLOYED				
		Ejected	Ejection Pa			Trapped/Extricated			
		NOT EJECTED	NOT EJE	CTED/NOT APPL	CABLE	NOT TRAPPED			
		Medical Transport			EMS Agency Identifier	EMS Run #			
		NOT TRANSPORTED							
	Hospital			Date of Death	Time of Death				
		Distracted By NOT A	ed By Source	F (NOT DISTRAC	ACTED)				
		Distracted By Action		_ (1101 2011)	/				
		NOT DISTRACTED							
		Non Motorist Striking	Unit #	Location					
				l .					

6TL09T1TN5 19-02805

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 03/09/2019

Crash Time 05:30 PM

		Prior Action					
 		Action					
TIND	INDIVIDUAL						
		Action Other					To/From School
	L	Drug & Alcohol NO	ol Use	Suspected Drug Use NO			
		Alcohol Test Given	Alcohol Test Type	•		Alcohol Test Results	
ļ		TEST NOT GIVEN	D T (T				
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	S	
2	001	Drug Type	•				
		Individual Condition				_	
		APPEARED NORMAL					