

6TL0B3P3F6

19-04100

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON CTHF EB 706 FT W OF ST PAUL RD IN THE TOWN OF LA VALLE IN SAUK COUNTY	Latitude 43.63421209	Longitude -90.097521927
	X Coordinate 250132.328125	Y Coordinate 4835910
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ROADSIDE	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) SNOW	Roadway Factor(s) NONE	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - NOT ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 2	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types	
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With DITCH		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE LEFT		Road Grade SAG(BOTTOM)	
	Truck Bus or HazMat NO					

UNIT 01	Vehicle						
	VEHICLE 01	License Plate Number ACM9832		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number JHMFA36256S024629		Make HONDA	Year 2006	Model CIVIC HYBR	
		Color GRY - GRAY		Body Style 4D - 4DR		Bus Use NOT A BUS	
		Initial Contact Point NON-COLLISION		Vehicle Damage			
Extent Of Damage NO DAMAGE		NO DAMAGE					

6TL0B3P3F6

19-04100

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OWNER	
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions SPEED TOO FAST/COND			
01 01	Owner Name KYLE ROSS EWING		Owner Address S1116 HOPI CT LA VALLE, WI 53941 , US	
	Sequence Of Events			
01 02 03 04	Event DITCH			
	Event			
	Event			
	Event			
UNIT POLICY HOLDER	Policy Holder			
	Insurance Company MT-MORRIS-MUTUAL-INS-CO		Individual KYLE EWING	
UNIT INDIVIDUAL	Individual			
	Driver KYLE ROSS EWING		Citations Issued 0	Sex MALE
	Address S1116 HOPI CT LA VALLE, WI 53941 , US		Date of Birth	Race WHITE
	Driver License Number		STATE: WISCONSIN COUNTRY: UNITED STATES	
01 001	Safety Equipment		On Duty Crash	
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Non Motorist		Striking Unit #	Location		
	Prior Action					
	Action					
	Action Other			To/From School		
01	001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
		Drug Type				
		Individual Condition APPEARED NORMAL				
		Individual				
		Passenger ABIGAIL J EWING		Citations Issued 0	Sex FEMALE	
				Date of Birth	Race WHITE	
		Address S1116 HOPI CT LA VALLE, WI 53941 , US		Driver License Number		
		UNIT	002	Safety Equipment		On Duty Crash
Seat Position 3--FRONT SEAT-RIGHT SIDE (TRAIN ENGINEER				SHOULDER & LAP BELT		
Helmet Use				Helmet Compliance		
Eye Protection				Tint Compliance		
Injury				Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
Ejected NOT EJECTED				Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED				EMS Agency Identifier	EMS Run #	
Hospital				Date of Death	Time of Death	
Distracted By		Distracted By Source				
Distracted By Action						
Non Motorist		Striking Unit #	Location			

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT	Prior Action				
	Action				
	Action Other		To/From School		
	Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO		
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results		
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results		
	Drug Type				
	Individual Condition APPEARED NORMAL				
	01	002			