6TL0BGSFDF

19-03962

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document #	Agency Crash Number Investigating DEPUTY E		g Officer/Deputy B. LUBER		
DF	Crash Date 04/08/2019	Crash Time 07:19 AM	Date Arrived 04/08/2019	Time Arrived 07:35 AM			
SSE	Date Notified 04/08/2019	Time Notified 07:23 AM	Total Units 02	Total Injured 01	Total Killed 00		
	On Emergency Hi	t and Run Lane Clo	sure Work Zone	Trailer or	Towed Reporting Threshold		
6TL0BGSFD	Government Property	Active School Zone	School Bus Related NO	Tags			
	✓ Reportable	Crash Type DT4000 (STANDARD CRAS	SH)	Amended	Secondary Crash		
	Description						
	Diagram			Re	construction By		
	🏡 🗓 u	병다					
				Ph	otos By		
	U1			Ad	ditional Information DNE		
		758	CTH DL				
		U1					
	HWY 113		TTO SCALE				
		NO	T TO SCALE				

U1 WAS SOUTH ON HWY 113. OPERATOR U1 SAID SHE WAS SLOWING DOWN TO MAKE A LEFT TURN ONTO LOWER DL, TURNED, AND SAID DUE TO FOG, DID NOT SEE U2, AND WAS STRUCK BY U2. OPERATOR U2 SAID HE WAS NORTH ON HWY 113 AND U1 MADE A LEFT HAND TURN IN FRONT OF HIM AND THEY COLLIDED. FOG WAS OBSERVED IN THE AREA DURING THE TIME OF THE CRASH. OPERATOR OF U1 SAID NECK SNAPPED SIDEWAYS FROM THE CRASH.

6TL0BGSFDF 19-03962

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Crash Date 04/08/2019

Crash Time 07:19 AM

	Loc	ation							
		STH113 NB			Latitude			Longitud	le
	6 F				43.403866394				187682
		CTHDL WB	***		X Coordi	nate		Y Coord	inate
		THE TOWN OF MERRI	WAC		283378	283378.90625 Structure Type		480914	1.5
		ACK COOK!!			Structure			1	
	Cra	sh Scene							
	First	: Harmful Event			First Har	mful Event L	ocation		
	MO	TOR VEH IN TRANSP	ORT		ON RO	ON ROADWAY			
	Man	ner of Collision			Light Cor	ndition			
		FRONT TO SIDE			DAYLIG				
	Roa	d Surface Condition(s)			Roadway	Factor(s)			
	DR	Y							
	Envi	ronment Factor(s)							
	WE	ATHER CONDITIONS			NONE				
	Wea	ather Condition(s)							
	FO	. ,							
	Anin	nal Type				To Trafficwa	=		
	0	-h Olifiti Iti				CWAY - C			
		sh Classification - Location BLIC PROPERTY					- Jurisdiction		
		al Land			Access C		(IODIOTION		Special Study
					NO CONTROL		oposia. Study		operation of the state of the s
		in Interchange Area	Junction Location		Intersection Type	_			
	NO		INTERSECTION		I T INITEDSECTION	All .			
			INTEROLOTION		T-INTERSECTION	'			
	Uni	t Summary =	INTEROLOTION						
	Uni Unit	Status	INTEROESTION		erating As Classification		Unit Type	-	
	Uni Unit IN T	Status FRANSIT	INTEROCOTION	Vehicle Ope D CLASS			AUTOMO		ments
	Unit Unit IN T	Status FRANSIT icle Type							nents
07	Unit Unit IN T Vehi (SP	Status RANSIT icle Type ORT) UTILITY VEHICL		D CLASS	I erating As Classificatio		AUTOMO Operating A	s Endorser	
	Unit Unit IN T Vehi (SP	Status FRANSIT icle Type	E	D CLASS		n	AUTOMO Operating A	s Endorser	ments Mat Types
	Unit Unit IN 7 Vehi (SP Tota 1	Status RANSIT icle Type ORT) UTILITY VEHICL	E	D CLASS Total # Cita 1	erating As Classificatio	n Total Tra	AUTOMO Operating A	s Endorser	Mat Types
10	Unit Unit IN 7 Vehi (SP Tota 1	Status FRANSIT icle Type ORT) UTILITY VEHICL Il Occs rance?	_E Train/Bus # Recorded	D CLASS Total # Cita 1	I erating As Classificatio	n Total Tra	AUTOMO Operating A	Total Haz	Mat Types
10	Unit IN T Vehi (SP Tota 1 Insu YES	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? S t Harmful Event: Collision V	E Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 1 Pre Special Fun	erating As Classification tions Issued CrashTire Mark	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency	Total Haz 0 Total Land 2 Motor Vehi	Mat Types es
	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOS	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St t Harmful Event: Collision V TOR VEH IN TRANSP	E Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 1 Pre Special Fun	erating As Classification tions Issued CrashTire Mark ection	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	Total Haz 0 Total Land 2 Motor Vehi	Mat Types es cle Use
10	Unit Unit IN T Vehi (SP Tota 1 Insu YES Mos MO	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St t Harmful Event: Collision of the top of the to	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont	erating As Classifications Issued CrashTire Mark Inction EIAL FUNCTION	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont	Total Haz 0 Total Land 2 Motor Vehi	Mat Types es cle Use
01	Unit Unit IN T Vehi (SP Tota 1 Insu YES MOS MO Traff	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St t Harmful Event: Collision of the top of the	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT	erating As Classification tions Issued CrashTire Mark iction CIAL FUNCTION TOI	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
01	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOS MO Traft TWO	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? S It Harmful Event: Collision of the collis	_E Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont	erating As Classification tions Issued CrashTire Mark inction CIAL FUNCTION TOI CROL ature	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
01	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES Mos MO Traff TWO Surf BLA	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St t Harmful Event: Collision of the top of the	_E Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	erating As Classification tions Issued CrashTire Mark inction CIAL FUNCTION TOI CROL ature	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
01	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES Mos MO Traff TWO Surf BLA	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	_E Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	erating As Classification tions Issued CrashTire Mark inction CIAL FUNCTION TOI CROL ature	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
10	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOS MO Traff TWO Surfa BLA Truc NO	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	_E Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	erating As Classification tions Issued CrashTire Mark inction CIAL FUNCTION TOI CROL ature	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
10	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOS MO Traff TWO Surfa BLA Truc NO	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the total occurrence of the total occurrence occu	_E Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	crating As Classifications Issued CrashTire Mark Inction ICIAL FUNCTION ICIAL FUNCTION ICIAL TO THE INCTION ICIAL TO THE INCTION ISSUED IN THE INCTION IN THE INCIDENT IN THE INCIDE	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz O Total Land Z Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
10	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOS MO Traff TWO Surfa BLA Truc NO	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT S)	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	erating As Classification tions Issued CrashTire Mark ection IIAL FUNCTION errol ROL ature T	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S	Total Haz O Total Land Z Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
UNIT 01	Unit Unit Unit Unit Unit Unit Unit Unit	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs Tance? St Harmful Event: Collision of the collision	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT S)	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make	erating As Classifications Issued CrashTire Mark Incition IslAL FUNCTION IslAL F	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
10	Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOS MO Traff TWO Surfa BLA Truc NO	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs Tance? St Harmful Event: Collision of the collision	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT S)	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO	erating As Classification tions Issued CrashTire Mark election EIAL FUNCTION erol EROL ature T	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model TRAVERS	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
UNIT 01	Unit Unit Unit Unit Unit Unit Unit Unit	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT S)	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style	erating As Classification tions Issued CrashTire Mark election EIAL FUNCTION erol EROL ature T	Total Tra 0 Speed Li 55 St WI Year 2015	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
UNIT 01	Unii Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOO Trafit TWO Surfi BLA Truc	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs Tance? St Harmful Event: Collision of the collision	LE Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT S)	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style	crating As Classification tions Issued CrashTire Mark totion CIAL FUNCTION TOI CROL atture T JTOMOBILE DET	Total Tra 0 Speed Li 55 St WI Year 2015	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model TRAVERS Bus Use	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
10 UNIT 01	Unii Unit Unit IN 1 Vehi (SP Tota 1 Insu YES MOO Trafit TWO Surfi BLA Truc	Status TRANSIT Icide Type ORT) UTILITY VEHICL II Occs Trance? St Harmful Event: Collision Note TOR VEH IN TRANSPORT ICIDE ACKTOP (BITUMINOU Ick Bus or HazMat Vehicle License Plate Number 668YFD Vehicle Identification Nur 1GNKVGKD9FJ3154 Color BLU - BLUE	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT S)	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AL Make CHEVRO Body Style UT - SPC	crating As Classification tions Issued CrashTire Mark totion CIAL FUNCTION TOI CROL atture T JTOMOBILE DET	Total Tra 0 Speed Li 55 St WI Year 2015	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model TRAVERS Bus Use	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
UNIT 01	Unit Unit IN 1 Vehic (SP Tota 1 Insu YES MOO Traff TWO Surfs BLA Truck NO	Status TRANSIT Icle Type ORT) UTILITY VEHICL I Occs Tance? St Harmful Event: Collision Note TOR VEH IN TRANSPORT ICLE ACKTOP (BITUMINOU Ick Bus or HazMat Vehicle License Plate Number 668YFD Vehicle Identification Num 1GNKVGKD9FJ3154 Color BLU - BLUE Initial Contact Point	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With ORT S)	Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style UT - SPC Vehicle Da	crating As Classification tions Issued CrashTire Mark totion CIAL FUNCTION TOI CROL atture T JTOMOBILE DET	Total Tra 0 Speed Li 55 St WI Year 2015	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S' Model TRAVERS Bus Use NOT A BU	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperate L Suance FATES E L S	Mat Types es cle Use tive/Missing

6TL0BGSFDF

19-03962

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage		Vehicle Removed By				
		TOWED DUE TO DISAE	BLING DAMAGE	EVERETTS TOWING				
		What Driver Was Doing		Vehicle Factors				
		LEFT TURN						
		Driver Prior Action Other		NOT APPLICABLE				
		Driver Actions						
	ш	FAILED TO YIELD RIGH	IT-OF-WAY					
⊨	VEHICL							
E N	Ĭ							
_	Ä							
		Owner Name		Owner Address				
_	_	CATHERINE ANNE BAI	DER	S7235 BLUFF RD				
6	2	(608) 493-2594		MERRIMAC, WI 53561 , US				
	,	Sequence Of Events	S					
		Event	-					
	5	LEFT TURN						
	7	Event						
	02	MOTOR VEH IN TRANS	SPORT					
	03	Event						
		_						
	9	Event						
╘		Policy Holder						
UNIT		Insurance Company		Individual				
_		AMERICAN-FAMILY-INS-CO		CATHERINE BADER				
	1	Individual						
		Driver CATHERINE ANNE BADER (608) 493-2594		Citations Issued	Sex			
	ب			1	FEMALE			
	Ā			Date of Birth	Race			
╘	INDIVIDUAL				WHITE			
	\geq	Address S7235 BLUFF RD		Driver License Number				
	Ż	MERRIMAC, WI 53561	. us	STATE: WISCONSIN COUNTRY: UNITED STATES				
		MERRIMAG, WI 33301 , US						
		LO ₂ D						
	Sat	fety Equipment	uty Crash	Safety Equipment				
				CHOIL DED & LAD BELT				
		Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		SHOULDER & LAP BELT				
				Helmet Compliance				
		Helmet Use		Treithet Compilance				
		Eye Protection		Tint Compliance				
		I Eve Protection		Till Compilatioe				
		Eye Protection						
_	_	Injury	Severity	Airbag				
0	001	Injury	Severity SIBLE INJURY					
5	100	Injury	Severity SIBLE INJURY Ejection Path	Airbag	Trapped/Extricated			
6	001	Injury POS	SIBLE INJURY	Airbag DEPLOYED-COMBINATION	Trapped/Extricated NOT TRAPPED			
01	001	Injury POS Ejected NOT EJECTED Medical Transport	SIBLE INJURY Ejection Path	Airbag DEPLOYED-COMBINATION				
10	001	Injury POS Ejected NOT EJECTED Medical Transport NOT TRANSPORTED	SIBLE INJURY Ejection Path	Airbag DEPLOYED-COMBINATION PLICABLE EMS Agency Identifier	NOT TRAPPED EMS Run #			
01	100	Injury POS Ejected NOT EJECTED Medical Transport	SIBLE INJURY Ejection Path	Airbag DEPLOYED-COMBINATION PLICABLE	NOT TRAPPED			
10	100	Injury POS. Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	SIBLE INJURY Ejection Path NOT EJECTED/NOT APP	Airbag DEPLOYED-COMBINATION PLICABLE EMS Agency Identifier	NOT TRAPPED EMS Run #			
01	001	Injury POS Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	SIBLE INJURY Ejection Path NOT EJECTED/NOT APF	Airbag DEPLOYED-COMBINATION PLICABLE EMS Agency Identifier Date of Death	NOT TRAPPED EMS Run #			
01	001	Injury POS Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital Distracted By	SIBLE INJURY Ejection Path NOT EJECTED/NOT APP	Airbag DEPLOYED-COMBINATION PLICABLE EMS Agency Identifier Date of Death	NOT TRAPPED EMS Run #			
10	001	Injury POS Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	SIBLE INJURY Ejection Path NOT EJECTED/NOT APF	Airbag DEPLOYED-COMBINATION PLICABLE EMS Agency Identifier Date of Death	NOT TRAPPED EMS Run #			

6TL0BGSFDF 19-03962

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

									_
		Non Motorist	Striking Unit #	Location					
		Prior Action							_
		Action							_
	INDIVIDUAL								
╘	2								
UNIT	≥								
	$\bar{\mathbf{g}}$								
	=								
		Action Other						To/From School	
		Drug & Alcohol	Suspected Alcoho NO	ol Use	Suspected Drug Use NO				
		Alcohol Test Given		Alcohol Test Ty			Alcohol Tes	et Poculte	_
		TEST NOT GIVEN		Alcohol rest ry	ρe		Alcohol Tes	st iveanita	
		Drug Test Given		Drug Test Type		Drug Test Resu	lts		_
		TEŠT NOT GIVEN							
01	001	Drug Type		<u>'</u>		•			
0	ŏ								
		Individual Condition							_
		APPEARED NORI	APPEARED NORMAL						
		Violations							
		Violations							
		UTC Number		Statute Number	Description				
	2			Statute Number 846.18(2)	Description FAIL/YIELD WHILE	MAKING LEFT	TURN		
	5	UTC Number			Description FAIL/YIELD WHILE	MAKING LEFT	TURN		
	ح Uni	UTC Number AE139869 t Summary Status		346.18(2)	Vehicle Operating As Class		Unit Type		
	Uni Unit Unit	UTC Number AE139869 t Summary Status RANSIT		346.18(2)	FAIL/YIELD WHILE		Unit Type TRUCK		
	Unit Unit IN T	UTC Number AE139869 t Summary Status RANSIT cle Type	001 3	346.18(2)	Vehicle Operating As Class		Unit Type TRUCK	As Endorsements	_
02	Unit Unit IN 1 Vehi	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU	JP TRUCK	446.18(2)	Vehicle Operating As Class D CLASS	sification	Unit Type TRUCK Operating		
	Unit Unit IN 1 Vehi	UTC Number AE139869 t Summary Status RANSIT cle Type	001 3	446.18(2)	Vehicle Operating As Class D CLASS Total # Citations Issued	sification Total Tra	Unit Type TRUCK Operating	Total HazMat Types	
	Unit Unit IN T Vehi UTI Tota 1	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU	JP TRUCK	Recorded	Vehicle Operating As Class D CLASS Total # Citations Issued 0	sification	Unit Type TRUCK Operating A		
02	Unit Unit IN T Vehi UTI Tota 1	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs	JP TRUCK Train/Bus # I	Recorded Travel	Vehicle Operating As Class D CLASS Total # Citations Issued	Sification Total Tra	Unit Type TRUCK Operating A	Total HazMat Types 0 Total Lanes 2	
NIT 02	Unit IN T Vehi UTI Tota 1 Insu YES	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? Status t Harmful Event: Collision	JP TRUCK Train/Bus # I Direction Of NORTHBO	Recorded Travel	Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function	Total Tra 0 Speed L 55	Unit Type TRUCK Operating A ailers imit	Total HazMat Types 0 Total Lanes 2	
IT 02	Unit IN T Vehi UTI Tota 1 Insu YES MOS	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? t Harmful Event: Collisis TOR VEH IN TRANS	JP TRUCK Train/Bus # I Direction Of NORTHBO	Recorded Travel	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION	Total Tra 0 Speed L 55	Unit Type TRUCK Operating A ailers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YES MOO Traft	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? t Harmful Event: Collision TOR VEH IN TRANSIT ic Way	JP TRUCK Train/Bus # I Direction Of NORTHBO on With SPORT	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control	Total Tra 0 Speed L 55	Unit Type TRUCK Operating / ailers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2	
NIT 02	Unit Unit Unit Unit UTI Tota 1 Insu YES MOS	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? St Harmful Event: Collision TOR VEH IN TRANSIT ic Way D-WAY, NOT DIVID	JP TRUCK Train/Bus # I Direction Of NORTHBO on With SPORT	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL	Total Tra 0 Speed L 55	Unit Type TRUCK Operating A ailers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YES MOO Traff	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? t Harmful Event: Collision TOR VEH IN TRANSIT ic Way	JP TRUCK Train/Bus # I Direction Of NORTHBO on With SPORT	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control	Total Tra 0 Speed L 55	Unit Type TRUCK Operating / ailers imit Emergency NOT APP Traffic Con	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YESS MOO Traff TWO Surf. BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? t Harmful Event: Collision TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type	JP TRUCK Train/Bus # I Direction Of NORTHBO on With SPORT	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature	Total Tra 0 Speed L 55	Unit Type TRUCK Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YESS MOO Traff TWO Surf. BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type ACKTOP (BITUMING	JP TRUCK Train/Bus # I Direction Of NORTHBO on With SPORT	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature	Total Tra 0 Speed L 55	Unit Type TRUCK Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YES MOO Traff TWO Surfs BLA	UTC Number AE139869 t Summary Status FRANSIT cle Type LITY TRUCK/PICKU I Occs rance? St Harmful Event: Collisin TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type ACKTOP (BITUMING ik Bus or HazMat	JP TRUCK Train/Bus # I Direction Of NORTHBO ON With SPORT ED DUS)	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature	Total Tra 0 Speed L 55	Unit Type TRUCK Operating / ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YES MOO Traff TWO Surfs BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? S t Harmful Event: Collising TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type ACKTOP (BITUMING ik Bus or HazMat Vehicle License Plate Numbe	JP TRUCK Train/Bus # I Direction Of NORTHBO ON With SPORT ED DUS)	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type	Total Tra 0 Speed L 55	Unit Type TRUCK Operating / ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YES MOO Traff TWO Surfs BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type ACKTOP (BITUMING & Bus or HazMat Vehicle License Plate Numbe KK4817	JP TRUCK Train/Bus # I Direction Of NORTHBO On With SPORT ED DUS)	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUCK	Total Tra 0 Speed L 55 St WI	Unit Type TRUCK Operating / ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e	
UNIT 02	Unit Unit IN 1 Vehi UTI Total 1 Insu YES MOO Traff TWO Surf BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type ACKTOP (BITUMING k Bus or HazMat Vehicle License Plate Numbe KK4817 Vehicle Identification	JP TRUCK Train/Bus # I Direction Of NORTHBO On With SPORT ED DUS)	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUCK Make	Total Tra 0 Speed L 55 DN St WI Year	Unit Type TRUCK Operating / Operating / Simit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e	
NIT 02	Unit Unit IN 1 Vehi UTI Tota 1 Insu YES MOO Traff TWO Surfs BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? Status TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type ACKTOP (BITUMING k Bus or HazMat Vehicle License Plate Numbe KK4817 Vehicle Identification 1GCEC14T14Z262	JP TRUCK Train/Bus # I Direction Of NORTHBO On With SPORT ED DUS)	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUCK Make CHEVROLET	Total Tra 0 Speed L 55 St WI	Unit Type TRUCK Operating A ailers imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model SILVERAL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e	
UNIT 02	Unit Unit IN 1 Vehi UTI Total 1 Insu YES MOO Traff TWO Surf BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANS fic Way D-WAY, NOT DIVID ace Type ACKTOP (BITUMING k Bus or HazMat Vehicle License Plate Numbe KK4817 Vehicle Identification	JP TRUCK Train/Bus # I Direction Of NORTHBO On With SPORT ED DUS)	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUCK Make	Total Tra 0 Speed L 55 DN St WI Year	Unit Type TRUCK Operating / Operating / Simit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e ssuance TATES	
UNIT 02	Unit Unit IN 1 Vehi UTI Total 1 Insu YES MOO Traff TWO Surf BLA	UTC Number AE139869 t Summary Status RANSIT cle Type LITY TRUCK/PICKU I Occs rance? Status TOR VEH IN TRANS fic Way D-WAY, NOT DIVID fic Way C-WAY, NOT DIVID fic Way C-WAY BITUMING Status REMANSIT Color TOR VEH IN TRANS FIC Way C-WAY, NOT DIVID fic Way C-WAY C-W	JP TRUCK Train/Bus # I Direction Of NORTHBO On With SPORT ED DUS)	Recorded Travel DUND	FAIL/YIELD WHILE Vehicle Operating As Class D CLASS Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUCK Make CHEVROLET Body Style	Total Tra 0 Speed L 55 DN St WI Year	Unit Type TRUCK Operating // Operating // imit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model SILVERAL Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e ssuance TATES	

6TL0BGSFDF

19-03962

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Щ		V	ehicle Damage		
UNIT	VEHICLE					
5	표	9		12FRONT		
	VE	DISABLING DAMAGE				
		Towed Due To Damage		ehicle Removed By		
		TOWED DUE TO DISABL		MIKES TOWING		
		What Driver Was Doing GOING STRAIGHT		ehicle Factors		
				IOT APPLICABLE		
		Driver Actions				
	щ	NO CONTRIBUTING ACT	ON			
UNIT	<u>C</u>					
5	VEHICL					
	7					
		Ourser Name		Ours or Address		
		Owner Name CATHERINE M BALLWEO	ì	Owner Address S8259 INSPIRATION DR		
02	02	(608) 643-4997		MERRIMAC, WI 53561, US		
	9	Sequence Of Events				
		Event				
	01	MOTOR VEH IN TRANSPO	ORT			
	02	Event				
	0					
	03	Event				
		Event				
	04	Lvent				
		Policy Holder				
UNIT		Insurance Company		Individual		
n		MOTORISTS-MUTUAL-IN	s-co	JOHN BALLWEG		
		Individual				
		Driver		Citations Issued	Sex	
	7	JOHN LEO BALLWEG		0	MALE	
	JA	(608) 643-4997		Date of Birth	Race	
╘	DIVIDUAL			WHITE		
UNIT	\leq	Address		Driver License Number		
	Z	S8259 INSPIRATION DR MERRIMAC, WI 53561, U	IS	STATE: WISCONSIN COUNTRY: UNITED STATES		
		,				
		On Duty Crash		Safety Equipment		
	Sat	fety Equipment		Calety Equipment		
		Seat Position		SHOULDER & LAP BELT		
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY				
		Helmet Use		Helmet Compliance		
		Eye Protection		Tint Compliance		
۸,	7	Injury Se	everity	Airbag		
02	005		PARENT INJURY	DEPLOYED-FRONT		
		Ejected	Ejection Path		Trapped/Extricated	
		NOT EJECTED	NOT EJECTED/NOT APPL		NOT TRAPPED	
		Medical Transport		EMS Agency Identifier	EMS Run #	
		NOT TRANSPORTED		Date of Dooth	Time of Death	
		Hospital		Date of Death	Time of Death	

6TL0BGSFDF 19-03962

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 04/08/2019

Crash Time 07:19 AM

		Distracted By	Distracted By Source NOT APPLICABL	E (NOT DISTRAC	CTED)			
		Distracted By Action NOT DISTRACTE						
		Non Motorist	Striking Unit #	Location				
		Prior Action						
		Action						
	JAL							
UNIT	INDIVIDUAL							
	N							
		Action Other						To/From School
	1	Drug & Alcohol	Suspected Alcohol U NO	se	Suspected Drug Use NO			•
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
02	005	Drug Type						
		Individual Condition						
		APPEARED NORI	MAL					