

6TL09QKRDK
19-05627

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON MAPLE ST 214 FT W OF WALNUT ST IN THE VILLAGE OF WEST BARABOO IN SAUK COUNTY	Latitude 43.473865662	Longitude -89.766070193
	X Coordinate 276277.71875	Y Coordinate 4817156
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event OTHER OBJECT - NOT FIXED	First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/UNLIT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 25	Total Lanes 2
	Most Harmful Event: Collision With OTHER OBJECT - NOT FIXED	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT	Vehicle				
	01	License Plate Number TASTES	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 1ZVBP8EM7C5257112	Make FORD	Year 2012	Model MUSTANG
	VEHICLE	Color BLK - BLACK	Body Style CV - CONVERTIBLE		Bus Use NOT A BUS
		Initial Contact Point 1--RIGHT FRONT CORNER	Vehicle Damage		
Extent Of Damage DISABLING DAMAGE		1--RIGHT FRONT CORNER, 2--RIGHT SIDE FRONT, 3--RIGHT SIDE MIDDLE, 4--RIGHT SIDE REAR, 12--FRONT, UNDERCARRIAGE			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By CRAIGS TOWING	
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions OPERATED MOTOR VEHICLE IN INATTENTIVE, CARELESS OR ERRATIC MANNER			
01	Owner Name ANTHONY SCOTT GREEN (608) 495-0140		Owner Address 313 KRISTA CT BARABOO, WI 53913 , US	
	Sequence Of Events			
01	01	Event OTHER OBJECT - NOT FIXED		
	02	Event		
	03	Event		
	04	Event		
UNIT	Policy Holder			
	Insurance Company PROGRESSIVE-CLASSIC-INS-CO		Individual ANTHONY GREEN	
UNIT INDIVIDUAL	Individual			
	Driver ANTHONY SCOTT GREEN (608) 495-0140		Citations Issued 0	Sex MALE
	Address 313 KRISTA CT BARABOO, WI 53913 , US		Date of Birth	Race WHITE
	Driver License Number		STATE: WISCONSIN COUNTRY: UNITED STATES	
01	Safety Equipment		On Duty Crash	
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag DEPLOYED-COMBINATION
	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				

