## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document #	Agency Crash Number 19-05688	Investigating Officer/Diperverse DEPUTY W. VERTI					
34	Crash Date <b>05/17/2019</b>	Crash Time 12:00 AM	Date Arrived <b>05/17/2019</b>	Time Arrived 09:42 AM					
61L0BC3B34	Date Notified <b>05/17/2019</b>	Time Notified 09:26 AM	Total Units <b>01</b>	Total Injured Total 00 00	al Killed				
<u>ო</u>	On Emergency Hi	t and Run Lane Clo		Trailer or Towe	Reporting Threshold				
	Government Property	Active School Zone	School Bus Related NO	Tags					
	Reportable	Crash Type DT4000 (STANDARD CRA	SH)	Amended	Secondary Crash				
	Description								
	Diagram			Photos E	ruction By				
	Non-reportable			Additiona	al Information				
	I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.								
	ON THE DESCRIBED DATE, TIME, AND LOCATION, UNIT 1 WAS TRAVELING WESTBOUND. THE OPERATOR STATED WHILE TRAVELING WESTBOUND, HE SWERVED TO MISS A COUPLE OF DEER AND UNIT 1 ENTERED THE DITCH. THE OPERATOR WAS ABLE TO REMOVE UNIT 1 FROM THE DITCH AND BEGAN DRIVING HOME. HE ADVISED THE RIGHT FRONT TIRE ENDED UP COMING OFF SO HE PULLED OFF THE ROADWAY AND HIS SPOUSE PICKED HIM UP. NO REPORTED INJURIES.								

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/17/2019

Crash Time 12:00 AM

Control HV War	Lo	cation									
OF TOWN HALL RD   IN THE TOWN OF DELLONA IN SAUK COUNTY	OI	N CTHH WB					Longitude	Longitude			
N SAUK COUNTY  N SAUK COUNTY  Siructure Type  First Harmful Event							43.592893784			-89.920982624	
Result Country    Result Country							X Coordinate			nate	
Crash Scene  First Hamful Event Location DITCH  Manner of Collision NO COLLISION WVEHICLE IN TRANSPORT  Road Surface Condition(s) DRY  Weather Condition(s) CLOUDY  Weather Condition(s) CLOUDY  Weather Condition(s) CCANDIDATE  Annual Type Relation To Trafficway TRAFFICWAY - ON ROAD TRAFFICWAY - ON ROAD  TRAF							264212.3125 4830804				
First Harmful Event Location DTCH DTCH DTCH DTCH DTCH DTCH DTCH DTCH					Structure 7	Туре					
First Hamful Event Location DTCH DTCH DTCH DTCH DTCH DTCH DTCH DTCH	C	ach Saana									
DITCH Manner of Collision NO COLLSION W/VEHICLE IN TRANSPORT NO COLLSION W/VEHICLE IN TRANSPORT DARKUNULIT Road Surface Condition(s) DRY Environment Factor(s) NONE  Weather Condition(s) CLOUDY  Acrise I Classification - Lucation PUBLIC PROPERTY NO SPECIAL JURISDICTION Access Control NON-JURISDICTION Within Interchange Area NO-JURISDICTION  Within Interchange Area Non-JURISDICTION  NON-JURISDICTION  Unit Summary  Unit Status In TRANST D CLASS Vehicle Operating As Classification Unit Type Train/Bus # Recorded 1						Lectur					
Manner of Collision   Light Condition   DARKUNLIT								ocation			
NO COLLISION WVEHICLE IN TRANSPORT  Road Surface Condition(s) DRY  Environment Factor(s)  NONE  Weather Condition(s) CLOUDY  Animal Type Relation To Trailicway TRAFFICWAY - ON ROAD TRANSPICWAY - ON ROAD  Cresh Classification - Location PUBLIC PROPERTY  Tribial Land Access Control NO SPECIAL JURISDICTION  Within Interchange Area Junction Location NO CONTROL  Within Interchange Area Junction Location NO NON-JUNCTION  Within Interchange Area Junction Location NO NON-JUNCTION  Unit Summary  Unit Status In TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Unit Type IN TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Unit Type IN TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Unit Type IN TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Unit Type IN TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Unit Type IN TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Unit Type IN TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Intersection Type Unit Status In TRANSIT D CLASS TRUCK  Vehicle Operating As Classification NO SPECIAL FUNCTION  Intersection Type Unit Status In TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Unit Type In TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Intersection Type In TRANSIT D CLASS TRUCK  Vehicle Operating As Classification Intersection Type Intersection Type Intersection Truck Intersection Type Inters		-									
Readway Factor(s)  DRY  Environment Factor(s)  NONE  Weather Condition(s)  CLOUDY  Animal Type  Relation To Trafficway  TRAFFICWAY - ON ROAD  Crash Classification - Location  PUBLIC PROPERTY  Within Interchange Area NO SPECIAL JURISDICTION  NON-JUNCTION  Intersection Type NOT AN INTERSECTION  Unit Summary  Vehicle Type  UILITY TRUCK/PICKUP TRUCK  Total Ocos  Train/Bus # Recorded 1 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N E IN TRANSPORT								
Environment Factor(s)  NONE  Weather Condition(s)  CLOUDY  Animal Type  Relation To Trafficway TRAFFICWAY - ON ROAD TCRIS Classification - Location PUBLIC PROPERTY  Tribal Land  NO SPECIAL JURISDICTION  NOS SPECIAL JURISDICTION  NO CONTROL  Within Interchange Area NO NON-JUNCTION  Within Interchange Area NON-JUNCTION  Intersection Type NOT AN INTERSECTION  Unit Status  Vehicle Operating As Classification IN TRANSIT  D CLASS  TRUCK  Total Trailers  UTILITY TRUCK/PICKUP TRUCK  Total Occs  Train/Bus # Recorded  Total # Citations Issued  Total Trailers  Total HazMat Types  UTILITY TRUCK/PICKUP TRUCK  Total Trainers  Vehicle Operating As Classification Insurance?  Direction Of Travel  No Per CrashTire No Per CrashTi			LE IN TRANSPORT								
Environment Factor(s)   NONE						Roadway	Factor(s)				
NONE   Weather Condition(s)	DF	RY									
Westher Condition(s)   CLOUDY	En	vironment Factor(s)									
CLOUDY  Animal Type  Relation To Trafficway TRAFFICWAY - OR ROAD  Crash Classification - Location PUBLIC PROPERTY  Tribal Land  Access Control NO SPECIAL JURISDICTION  Within Interchange Area No Not An INTERSECTION  Unit Summary  Unit Status  Vehicle Operating As Classification In TRANSIT  D CLASS  TRUCK  Vehicle Type  UTILITY TRUCK/PICKUP TRUCK  Total Cocs  Train/Bus # Recorded  1	N	ONE				NONE					
Animal Type  Relation To Trafficway TRAFFICWAY - ON ROAD  Crash Classification - Jurisdiction PUBLIC PROPERTY  Tribal Land  Access Control NO CONTROL  Within Interchange Area NO SPECIAL JURISDICTION  Access Control NO CONTROL  Within Interchange Area NO Horder NO CONTROL  Within Interchange Area NO SPECIAL JURISDICTION  Special Study NO CONTROL  Within Interchange Area NO Horder NO CONTROL  Unit Summary  Unit Status Vehicle Operating As Classification Unit Type NOT AN INTERSECTION  Unit TRUCK/  Vehicle Type UTILITY TRUCK/PICKUP TRUCK  Total Cocs Train/Bus # Recorded Total # Cliations Issued Total Trailers Total Arabitat Types Total Cocs Train/Bus # Recorded Total # Cliations Issued Total Trailers Total Lanes YES WESTBOUND Pre CrashTire Mark S5 2  Most Harmful Event: Collision With NO SPECIAL FUNCTION NO CONTROL	We	eather Condition(s)				1					
TRAFFICWAY - ON ROAD  Crash Classification - Jurisdiction PUBLIC PROPERTY  Tribal Land  Access Control NO CONTROL  Within Interchange Area NO SPECIAL JURISDICTION  Access Control NO CONTROL  Within Interchange Area NON-JUNCTION  Intersection Type NOT AN INTERSECTION  Unit Summary  Unit Status Vehicle Operating As Classification Unit Type Train/Bus # Recorded Total # Citations Issued Total Trailers Total Access Train/Bus # Recorded Total # Citations Issued Total Trailers Total Access Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total Lanes  YeS WESTBOUND Pre CrashTire Speed Limit Total Lanes YES WESTBOUND Pre CrashTire Speed Limit Total Lanes YES WESTBOUND NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO FUNCTION NO FUNCTION NO CONTROL NO CONTROL NO CONTROL NO SURface Type BLACKTOP (BITUMINOUS) Track Bus or Haz/Mat NO  Vehicle License Plate Number LD2791 LTK - LIGHT TRUCK UNITED STATES Welbice Identification Number Make Year Make Year Model LEVEL  LICH PURPLE PIST Type Bus Use NOT A BUS NOTA BUS NOTA BUS  NOTA BUS  Haid Contact Point  Vehicle Damage	CI	LOUDY									
TRAFFICWAY - ON ROAD  Crash Classification - Jurisdiction PUBLIC PROPERTY  Tribal Land  Access Control NO CONTROL  Within Interchange Area NO SPECIAL JURISDICTION  Access Control NO CONTROL  Within Interchange Area NON-JUNCTION  Intersection Type NOT AN INTERSECTION  Unit Summary  Unit Status Vehicle Operating As Classification Unit Type Train/Bus # Recorded Total # Citations Issued Total Trailers Total Access Train/Bus # Recorded Total # Citations Issued Total Trailers Total Access Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total Lanes  YeS WESTBOUND Pre CrashTire Speed Limit Total Lanes YES WESTBOUND Pre CrashTire Speed Limit Total Lanes YES WESTBOUND NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO FUNCTION NO FUNCTION NO CONTROL NO CONTROL NO CONTROL NO SURface Type BLACKTOP (BITUMINOUS) Track Bus or Haz/Mat NO  Vehicle License Plate Number LD2791 LTK - LIGHT TRUCK UNITED STATES Welbice Identification Number Make Year Make Year Model LEVEL  LICH PURPLE PIST Type Bus Use NOT A BUS NOTA BUS NOTA BUS  NOTA BUS  Haid Contact Point  Vehicle Damage	An	imal Type				Relation T	o Trafficwa	av			
PUBLIC PROPERTY								•			
Tribal Land  Access Control NO CONTROL  Within Interchange Area Junction Location NO NON-JUNCTION  NON-JUNCTION  NON-JUNCTION  NOT AN INTERSECTION  Unit Summary  Unit Status IN TRANSIT  Unit Status IN TRANSIT  Unit Type UTILITY TRUCK/PICKUP TRUCK  Total Cocs Train/Bus # Recorded 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Cr	ash Classification - Location	า			Crash Clas	ssification -	- Jurisdiction			
Within Interchange Area   Junction Location   Intersection Type   NOT AN INTERSECTION    Unit Summary	Pι	JBLIC PROPERTY				NO SPE	CIAL JUF	RISDICTION			
Within Interchange Area NO NON-JUNCTION Intersection Type NOT AN INTERSECTION  Unit Summary  Unit Status Vehicle Operating As Classification Unit Type TRUCK  IN TRANSIT D CLASS TRUCK  Operating As Endorsements  UTILITY TRUCK/PICKUP TRUCK  Total Occs Train/Bus # Recorded O O O O O O O O O O O O O O O O O O	Tri	bal Land				Access Control Special Study				Special Study	
Unit Summary  Unit Status IN TRANSIT							TROL				
Unit Summary  Unit Status IN TRANSIT D CLASS TRUCK  Vehicle Type UTILITY TRUCK/PICKUP TRUCK  Total Occs Train/Bus # Recorded Insurance? Direction Of Travel WESTBOUND Most Harmful Event: Collision With DITCH NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO APPLICABLE  Traffic Way Truck Way Truck Way NOT APPLICABLE  Truck Bus or Haz/Mat NO  Vehicle  License Plate Number LD2791 Vehicle Identification Number 3B7HF13Y9XG180819 DODGE DITCH DITCH DITCH Plate Type LTK - LIGHT TRUCK Will Initial Contact Point Wake NOT A BUS Bus Use NOT A BUS NOT A BUS  Bus Use NOT A BUS  Bus Use NOT A BUS  Bus Use NOT A BUS		•				••					
Unit Status IN TRANSIT  Vehicle Operating As Classification D CLASS TRUCK  Operating As Endorsements  Unit Type TRUCK  Total Occs Train/Bus # Recorded O Total # Citations Issued O Total Trailers Total HazMat Types Operating As Endorsements  Total HazMat Types Operating As Endorsements  Total HazMat Types Operating As Endorsements  Total Trailers Total HazMat Types Operating As Endorsements  Total HazMat Types Operating As Endorsements  Total Trailers Total HazMat Types Operating As Endorsements  Total Trailers Total HazMat Types Operating As Endorsements  Total Trailers Total HazMat Types Operating As Endorsements  Total HazMat T			NON-JUNCTION		NOT AN	NINTERSECTION					
IN TRANSIT  Vehicle Type  UTILITY TRUCK/PICKUP TRUCK  Total Occs  Train/Bus # Recorded  Insurance?  Direction Of Travel  YES  Most Harmful Event: Collision With  DITCH  Traffic Way  Traffic Way  Traffic Control  Traffic Control  Surface Type  BLACKTOP (BITUMINOUS)  Truck Bus or HazMat  NO  DITCH  DITCH  DITCH  Road Curvature  BLACKTOP (BITUMINOUS)  Truck Bus or HazMat  NO  DITCH  License Plate Number  LD2791  LTK - LIGHT TRUCK  Make  Pear Model  DOGE  Body Style  PK - PICKUP  NOT A BUS  NOTA BUS  Bus Use  NOTA BUS  NOTA BUS  NOTA BUS  NOTA BUS  NOTA BUS  NOTA BUS  DECIAL FUNCK  Total Traillers  Total HazMat Types  Operating As Endorsements  Total HazMat Types  Total HazMat Types  Operating As Endorsements  Total HazMat Types  Operating As Endorsements  Total HazMat Types  Operating As Endorsements  Total HazMat Types  D NO A Speed Limit  Total Trailers  Total HazMat Types  D NO A PPLICABLE  Emergency Motor Vehicle Use  NOT A BUS											
Vehicle Type  UTILITY TRUCK/PICKUP TRUCK  Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total HazMat Types Total HazMat Types Total Trailers Total HazMat Types Total HazMat Types Total Trailers Total HazMat Types To	Ur	it Status		· ·	erating As C	2 2 21					
UTILITY TRUCK/PICKUP TRUCK  Total Occs				D CLASS							
Total Occs  Train/Bus # Recorded  Total # Citations Issued  Total Trailers  Total HazMat Types  Total HazMat Types  Total Trailers  Total HazMat Types  Total HazMat Types  Total Trailers  Total HazMat Types  Total Trailers  Total HazMat Types  Total Trailers  Total HazMat Types  Total HazMat Types  Total Trailers  Total Trailers  Total HazMat Types  Speed Limit  Total Lanes  Speed Limit  Total Trailers  Total Trailers  Total HazMat Types  Total HazMat Types  Total Trailers  Total HazMat Types  Speed Limit  Total Lanes  Speed Limit  Total Trailers  Total HazMat Types  Total HazMat Types  Total Trailers  Total HazMat Types  Speed Limit  Total Trailers  Total HazMat Types  Total Trailers  Total HazMat Types  Speed Limit  Total Lanes  Speed Limit  Total Trailers  Total Traile		••				Operating As Endorsements					
1				T-4-1 # 0'4-	Transport I		Takal Takilana		Total HarMat Types		
Insurance? YES    Direction Of Travel   WESTBOUND		1								viat Types	
YES			Direction Of Travel			10 111				200	
Most Harmful Event: Collision With DITCH Special Function NO SPECIAL FUNCTION Traffic Control NO SPECIAL FUNCTION Traffic Control Inoperative/Missing NO CONTROL NO Surface Type Road Curvature Road Grade BLACKTOP (BITUMINOUS) STRAIGHT LEVEL  Truck Bus or HazMat NO  Vehicle  License Plate Number Plate Type St Country of Issuance LD2791 LTK - LIGHT TRUCK WI UNITED STATES  Vehicle Identification Number Make Year Model SB7HF13Y9XG180819 DODGE 1999 RAM 1500 Q  Color Body Style PK - PICKUP NOT A BUS  Initial Contact Point Vehicle Damage				Pre				iiiit		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
DITCH Traffic Way Traffic Control Traffic Control NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number LD2791 Vehicle Identification Number 3B7HF13Y9XG180819 DODGE DOGGE DITCH NO SPECIAL FUNCTION NOT APPLICABLE Traffic Control NO				Special Fun						cle Use	
Traffic Way TWO-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number LD2791 Vehicle Identification Number 3B7HF13Y9XG180819 Color PLE - PURPLE Initial Contact Point  Traffic Control NO  Road Curvature Road Grade LEVEL  Road Grade LEVEL  Truck Bus or HazMat NO  Vehicle Identification Number Bake PYear Model St. Country of Issuance UNITED STATES Will UNITED STATES  Bus Use NOT A BUS  Vehicle Damage		a i			•						
TWO-WAY, NOT DIVIDED  Surface Type  BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Vehicle  License Plate Number LD2791  Vehicle Identification Number 3B7HF13Y9XG180819  Color PLE - PURPLE  Initial Contact Point  NO  Road Curvature Road Grade LEVEL  Road Grade LEVEL  Road Grade LEVEL  Country of Issuance UNITED STATES  WI UNITED STATES  Bus Use NOT A BUS					affic Control			Traffic Control Inoperative/Missing			
Surface Type BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Vehicle  License Plate Number LD2791  Vehicle Identification Number 3B7HF13Y9XG180819  Color PLE - PURPLE  Initial Contact Point  Road Curvature STRAIGHT  Road Grade LEVEL  Road Grade LEVEL  Country of Issuance UNITED STATES  Will UNITED STATES  Bus Use NOT A BUS	TV	VO-WAY, NOT DIVIDE		NO CONT	ROL						
Truck Bus or HazMat  NO  Vehicle  License Plate Number LD2791  Vehicle Identification Number 3B7HF13Y9XG180819  Color PLE - PURPLE  Initial Contact Point  Vehicle Damage  St Country of Issuance UNITED STATES  WI UNITED STATES  Wake Year Model 1999 RAM 1500 Q  Body Style PK - PICKUP  Vehicle Damage								Road Grade			
Vehicle  License Plate Number LD2791 Vehicle Identification Number 387HF13Y9XG180819 Color PLE - PURPLE Initial Contact Point  Vehicle Identification Number Body Style PK - PICKUP  Vehicle Damage  St Country of Issuance WI UNITED STATES  Wake Year Model 1999 RAM 1500 Q  Bus Use NOT A BUS	ВІ	ACKTOP (BITUMINOL	JS)	STRAIGH				LEVEL			
Vehicle  License Plate Number LD2791  Vehicle Identification Number 3B7HF13Y9XG180819  Color PLE - PURPLE  Initial Contact Point  Plate Type St Country of Issuance UNITED STATES  WI UNITED STATES  Make Year Model 1999 RAM 1500 Q  Body Style PK - PICKUP  Vehicle Damage								•			
License Plate Number LD2791  Vehicle Identification Number 3B7HF13Y9XG180819  Color PLE - PURPLE  Initial Contact Point  LTK - LIGHT TRUCK  WI UNITED STATES  Windle UNITED STATES  Make Year Model 1999 RAM 1500 Q  Body Style PK - PICKUP  Vehicle Damage	N										
LD2791				Diote Turne		ı	St	Country of lo	SHance		
Vehicle Identification Number  3B7HF13Y9XG180819  DODGE  1999  RAM 1500 Q  Body Style PLE - PURPLE  PK - PICKUP  Initial Contact Point  Vehicle Damage				1							
3B7HF13Y9XG180819   DODGE   1999   RAM 1500 Q											
Color PLE - PURPLE PK - PICKUP  Bus Use NOT A BUS  Vehicle Damage	71	- 1									
PLE - PURPLE PK - PICKUP NOT A BUS  Unitial Contact Point Vehicle Damage							1000				
Initial Contact Point  1RIGHT FRONT CORNER  Extent Of Damage FUNCTIONAL DAMAGE  Vehicle Damage  1RIGHT FRONT CORNER, 2RIGHT SIDE FRONT					NOT A DUC			S			
1RIGHT FRONT CORNER  Extent Of Damage FUNCTIONAL DAMAGE  1RIGHT FRONT CORNER, 2RIGHT SIDE FRONT		Initial Contact Point		Vehicle Da							
Extent Of Damage FUNCTIONAL DAMAGE  1RIGHT FRONT CORNER, 2RIGHT SIDE FRONT	ш	1RIGHT FRONT CORNER		I							
FUNCTIONAL DAMAGE		1RIGHT FRONT CO	URNER								(
	HICLE	Extent Of Damage		1RIGHT	FRONT	CORNER,	2RIGHT	SIDE FROM	IT		

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage		hicle Removed By					
		TOWED BUT NOT DUE TO DISABLING DAMAG What Driver Was Doing		EVES AUTO SERVICE					
				hicle Factors					
		GOING STRAIGHT	N/	OT APPLICABLE					
		Driver Prior Action Other	INC.	71 APPLICABLE					
		Driver Actions							
		Driver Actions RAN OFF ROADWAY							
l ∟	٣	KAN OIT KOADWAT							
L	≌								
<b> </b>	VEHICLE								
	>								
		Owner Name		Owner Address					
		AMANDA L MATHIS		111 S EAST ST					
5	5			LAVALLE, WI 53941 , U	JS				
		Common of France							
		Sequence Of Events Event							
	2	RUN OFF ROADWAY RIGHT							
		Event							
	02	Event DITCH							
		Event							
	03	Lvont							
		Event							
	04								
١.		Policy Holder							
LIND	· '	Insurance Company		Individual					
5		PERMANENT-GENERAL-ASSURANCE-CO		JASON MATHIS					
		Individual	1	Oitetiene Jesus d					
	INDIVIDUAL	Driver  JASON S MATHIS  (608) 415-9670		Citations Issued	Sex				
				0	MALE Race				
١.		,		Date of Birth	WHITE				
LNO	₹	Address		Driver License Number					
5	ND N	111 S EAST ST LAVALLE, WI 53941 , US  On Duty Crash		STATE: WISCONSIN COUNTRY: UNITED STATES					
	Sa			Safety Equipment					
				Curaty Equipment					
		Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		SHOULDER & LAP BELT					
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
2	001	Injury Severity		Airbag					
0	ŏ	Injury NO APPARENT INJURY	<b>'</b>	NON DEPLOYED					
		Ejected Ejection Path			Trapped/Extricated				
		NOT EJECTED NOT EJECTED/			NOT TRAPPED				
		Medical Transport		EMS Agency Identifier	EMS Run #				
		NOT TRANSPORTED							
		Hospital		Date of Death	Time of Death				
		Bi-tra-tra-15 C							
		Distracted By Source							
		Distracted By Action							
	UNKNOWN								

Crash Time 12:00 AM

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motor	Striking Unit #	Location					
		Prior Action		l					
		Action							
	AL								
UNIT	/IDU								
ר	INDIVIDUAL								
	=								
		Action Other						To/From School	
			Suspected Alcohol U	se	Suspected Drug Use				
	L	Orug & Alcoh			NO				
		Alcohol Test Giver		Alcohol Test Type			Alcohol Test Results		
		Drug Test Given TEST NOT GIV	EN	Drug Test Type		Drug Test Results			
10	001	Drug Type							
	Individual Condition								
		NOT OBSERVE	ED						
Property Owner									
10	Government TOWNSHIP OF DELLONA				Address E8062 CTH H REEDSBURG, WI 53959 , US				
PROP OWNER									
	Fixe	ed Objects St	ruck						
	5	Striking Unit <b>01</b>	Struck Object DITCH					Damage Tag Number <b>NA</b>	