

6TL0B3P3F9  
19-07870

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

6TL0B3P3F9

Document Number Override		Primary Crash Document #	Agency Crash Number <b>19-07870</b>	Investigating Officer/Deputy <b>DEPUTY S. PARKHURST</b>	
Crash Date <b>06/29/2019</b>		Crash Time <b>10:58 PM</b>	Date Arrived <b>06/29/2019</b>	Time Arrived <b>11:21 PM</b>	
Date Notified <b>06/29/2019</b>		Time Notified <b>11:02 PM</b>	Total Units <b>01</b>	Total Injured <b>01</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input checked="" type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>	Tags	
<input checked="" type="checkbox"/> Reportable	Crash Type <b>DT4000 (STANDARD CRASH)</b>		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash	

Description

<p>Diagram</p>	Reconstruction By
	Photos By
	Additional Information <b>NONE</b>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

OPERATOR OF UNIT 1 STATED SHE SWERVED TO MISS A DEER. THE VEHICLE LEFT THE ROADWAY AND STRUCK A CULVERT. THE VEHICLE CONTINUED IN THE DITCH STRIKING A SECOND CULVERT. THE VEHICLE THEN STRUCK A SIGN POST. THE VEHICLE STRUCK A FENCE AND CAME TO REST ALONG THE FENCE.

Location

<b>ON 371 CTHG SB 0.43 MI N OF MAGRUDER RD (FIRE 371)</b>  <b>IN THE TOWN OF WOODLAND IN SAUK COUNTY</b>	Latitude <b>43.63204787</b>	Longitude <b>-90.228364059</b>
	X Coordinate <b>239567.796875</b>	Y Coordinate <b>4836072</b>
	Structure Type <b>FIRE</b>	

6TL0B3P3F9

19-07870

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Crash Scene

Table with crash scene details including: First Harmful Event (DITCH), First Harmful Event Location (SHOULDER RIGHT), Manner of Collision (NO COLLISION W/VEHICLE IN TRANSPORT), Light Condition (DARK/UNLIT), Road Surface Condition (DRY), Environment Factor (NONE), Weather Condition (CLEAR), Relation To Trafficway (TRAFFICWAY - ON ROAD), Crash Classification - Location (PUBLIC PROPERTY), Crash Classification - Jurisdiction (NO SPECIAL JURISDICTION), Access Control (NO CONTROL), Special Study, Within Interchange Area (NO), Junction Location (NON-JUNCTION), Intersection Type (NOT AN INTERSECTION).

Unit Summary

Table with unit summary details including: Unit Status (IN TRANSIT), Vehicle Operating As Classification (D CLASS), Unit Type (TRUCK), Vehicle Type (UTILITY TRUCK/PICKUP TRUCK), Operating As Endorsements, Total Occs (1), Train/Bus # Recorded, Total # Citations Issued (2), Total Trailers (0), Total HazMat Types (0), Insurance? (YES), Direction Of Travel (WESTBOUND), Pre Crash Tire Mark, Speed Limit (55), Total Lanes (2), Most Harmful Event: Collision With (CULVERT), Special Function (NO SPECIAL FUNCTION), Emergency Motor Vehicle Use (NOT APPLICABLE), Traffic Way (TWO-WAY, NOT DIVIDED), Traffic Control (NO CONTROL), Traffic Control Inoperative/Missing (NO), Surface Type (BLACKTOP (BITUMINOUS)), Road Curvature (CURVE LEFT), Road Grade (LEVEL), Truck Bus or HazMat (NO).

Vehicle

Table with vehicle details including: License Plate Number (PF8509), Plate Type (LTK - LIGHT TRUCK), St (WI), Country of Issuance (UNITED STATES), Vehicle Identification Number (1B7FL26X5XS271958), Make (DODGE), Year (1999), Model (DAKOTA), Color (BLK - BLACK), Body Style (PK - PICKUP), Bus Use (NOT A BUS), Initial Contact Point (1--RIGHT FRONT CORNER), Vehicle Damage (1--RIGHT FRONT CORNER, 2--RIGHT SIDE FRONT, 3--RIGHT SIDE MIDDLE, 4--RIGHT SIDE REAR, 5--RIGHT REAR CORNER, 6--REAR, 11--LEFT FRONT CORNER), Extent Of Damage (DISABLING DAMAGE), Towed Due To Damage (TOWED DUE TO DISABLING DAMAGE), Vehicle Removed By (STEVES AUTO SERVICE), What Driver Was Doing (NEGOTIATING CURVE), Vehicle Factors, Driver Prior Action Other (NOT APPLICABLE).

6TL0B3P3F9

19-07870

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

UNIT	VEHICLE	Driver Actions <b>FAILURE TO CONTROL</b>			
		Owner Name <b>DANYELLE LYNN FRY (608) 415-2029</b>	Owner Address <b>209 CENTER ST #1 PO BOX 417 WONEWOC, WI 53968 , US</b>		
UNIT	01	<b>Sequence Of Events</b>			
		01	Event <b>DITCH</b>		
		02	Event <b>CULVERT</b>		
		03	Event <b>TRAFFIC SIGN POST</b>		
UNIT	01	04	Event <b>FENCE</b>		
		<b>Policy Holder</b>			
		Insurance Company <b>PROGRESSIVE-ADVANCED-INSURANCE-CO</b>	Individual <b>DANYELLE FRY</b>		
		<b>Individual</b>			
UNIT	INDIVIDUAL	Driver <b>DANYELLE LYNN FRY (608) 415-2029</b>	Citations Issued <b>2</b>	Sex <b>FEMALE</b>	
			Date of Birth	Race <b>WHITE</b>	
		Address <b>209 CENTER ST #1 PO BOX 417 WONEWOC, WI 53968 , US</b>	Driver License Number <b>STATE: WISCONSIN COUNTRY: UNITED STATES</b>		
		<b>Safety Equipment</b>			
UNIT	01	On Duty Crash	Safety Equipment		
		Seat Position <b>1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY</b>	<b>SHOULDER &amp; LAP BELT</b>		
		Helmet Use	Helmet Compliance		
		Eye Protection	Tint Compliance		
		<b>Injury</b>	Injury Severity <b>POSSIBLE INJURY</b>	Airbag <b>DEPLOYED-FRONT</b>	
		Ejected <b>NOT EJECTED</b>	Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	Trapped/Extricated <b>NOT TRAPPED</b>	
		Medical Transport <b>NOT TRANSPORTED</b>	EMS Agency Identifier	EMS Run #	
		Hospital	Date of Death	Time of Death	
<b>Distracted By</b>		Distracted By Source <b>NOT APPLICABLE (NOT DISTRACTED)</b>			
Distracted By Action <b>NOT DISTRACTED</b>					
<b>Non Motorist</b>		Striking Unit #	Location		
Prior Action					

6TL0B3P3F9

19-07870

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

<b>UNIT</b>	<b>INDIVIDUAL</b>	Action				
		Action Other			To/From School	
	<b>01</b>	<b>001</b>	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>
			Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results
			Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results
			Drug Type			
			Individual Condition <b>APPEARED NORMAL</b>			
			<b>Violations</b>			
	<b>02</b>	<b>01</b>	UTC Number <b>BB338174</b>	Issue To? <b>001</b>	Statute Number <b>343.05(3)(a)</b>	Description <b>OPERATE W/O VALID LICENSE (EXP W/IN 3 MTHS)</b>
			UTC Number <b>BB331875</b>	Issue To? <b>001</b>	Statute Number <b>346.57(2)</b>	Description <b>FAILURE TO KEEP VEHICLE UNDER CONTROL</b>

### Property Owner

<b>PROP OWNER</b>	<b>01</b>	Government <b>TOWNSHIP OF WOODLAND</b> (608) 464-3290	Address <b>E2326 CRANDALL DR</b> <b>WONEWOC, WI 53968 , US</b>
-------------------	-----------	---	--

### Fixed Objects Struck

<b>01</b>	Striking Unit <b>01</b>	Struck Object <b>TRAFFIC SIGN POST</b>	Structure Number	Damage Tag Number <b>322940</b>
-----------	----------------------------	---	------------------	------------------------------------

### Property Owner

<b>PROP OWNER</b>	<b>02</b>	Individual <b>LEAH I RACHUJ</b> (608) 462-3857	Address <b>S371 COUNTY ROAD G</b> <b>WONEWOC, WI 53968 , US</b>
-------------------	-----------	--	---

### Fixed Objects Struck

<b>02</b>	Striking Unit <b>01</b>	Struck Object <b>FENCE</b>	Structure Number	Damage Tag Number <b>0000000</b>
-----------	----------------------------	-------------------------------	------------------	-------------------------------------