6TL0B1716R

19-08284

WISCONSIN MOTOR VEHICLE **CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

D	ocument Number Override	Primary Crash	Document #	Agency 19-082	r Crash Number 284	Investigatin DEPUTY		icer/Deputy		
	rash Date 7/06/2019	Crash Time 99:99		Date Arrived 07/07/2019			Time Arrived 07:20 AM			
	ate Notified 7/07/2019	Time Notified 07:08 AM		Total U 02	nits	Total Injure 00	Total Injured T		Total Killed 00	
	On Emergency	and Run			Work Zone		er or	Towed	Reporting Threshold	
	Government Property		hool Zone	School NO	Bus Related	Tags				
	Reportable	Crash Type DT4000 (STA	NDARD CRASH	H)		Amen	ded		Secondary Crash	
_	escription						Re	econstruction	Ву	
							Ph	otos By		
								ditional Info	mation	
							N	ONE		
	1	NON REPOR	TABLE							
_	✓ I, a sworn law enforcement	nt officer agr	a that I have no		l any C IIS data in	this report				
U		RKING LOT OF	CHRISTMAS MOU	JNTAIN P	RO SHOP AREA BE	TWEEN 2:30PM A				
	EHICLE ON 07-06-19 AFTER GC SUSPECT VEHICLE INFORMATIC			SIDE HA	ND A LARGE DEN⊺1	FOUT BY ONE FO		IN THE QUA	KIEK PANEL. NU	
	ocation									
	RIVATE PROPERTY HRISTMAS MOUNTAIN RD				Latitude 43.6103	05786		Longitu -89.86	de 1282349	
	N THE TOWN OF DELLONA N SAUK COUNTY				X Coordin 269098.	nate		Y Coord 48325	dinate	
					Structure			+0020		
L										
ons	in Motor Vehicle Crash		This report d	loes not i	nclude any CJIS data			Crash Dat	e 07/06/2019	

19-08284

WISCONSIN MOTOR VEHICLE CRASH REPORT

Crash Scene

]	First Harmful Event					First Harmful Event Location					
	PARKED MOTOR VEHICLE					IN PARKING LANE OR ZONE					
						Light Condition					
						DAYLIGHT					
	Road Surface Condition(s)					Roadway Factor(s)					
	DRY										
	Envii	ronment Factor(s)									
	NOM	IE				NONE					
	Wea	ther Condition(s)									
	CLEAR										
	Anim	al Type					o Trafficway AFFICWA	, Y - PARKIN	G LOT		
		h Classification - Location					sification -				
								SDICTION			
	l riba	I Land			Acce NO					Special Study	
	Withi	n Interchange Area	Junction Location		Intersectio	n Type				L	
	NO	-	NON-JUNCTION		NOT AN INTERS						
i	Unit	Summary									
		Status		Vehicle Ope	erating As C	lassification		Unit Type			
				D CLASS		AUTOMOBILE					
2		cle Type SENGER CAR						Operating As Endorsements			
	Tota	Occs	Train/Bus # Recorded	Total # Citat	Total # Citations Issued		Total Trailers		Total HazMat Types		
	1			0	0		0		0		
	Insurance? Direction Of Travel UNKNOWN UNKNOWN			Pre	Pre CrashTire		Speed Limit		Total Lanes		
UNIT	-	(NOWN		Mark				0 Matar Vahiala Llaa			
5		Harmful Event: Collision		Special Function UNKNOWN			Emergency Motor Vehicle Use				
		ic Way (NOWN		Traffic Control			Traffic Control Inoperative/Missing UNKNOWN				
	-	ace Type		Road Curvature			Road Grade				
		NOWN						UNKNOWN			
	Truck Bus or HazMat										
	NO										
		/ehicle					•				
		License Plate Number		Plate Type		St		Country of Issuance			
2	01	Vehicle Identification Nur	nber	Make	Make		Year		Model		
-	•	Color		Body Style	Body Style			Bus Use			
		Initial Contact Daint		Vahiala Da	NOT A BUS						
UNIT				venicie Da	Vehicle Damage						
5	Extent Of Damage Towed Due To Damage NOT TOWED Vehicle Removed By OPERATOR										
					,						
		What Driver Was Doing		Vehicle Fac							
	UNKNOWN										
	Driver Prior Action Other UNKNOWN										

19-08284

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Driver Actions							
È	<u></u>								
LINU	VEHICLE								
	N S								
		Owner Name		Owner Address					
2	01								
0	0			, ,					
		Sequence Of Events							
	01	Event PARKED MOTOR VEI	HICI E						
	02	Event							
	03	Event							
	J								
	04	Event							
		Individual							
		Driver		Citations Issued	Sex				
	Ļ			0					
	J N			Date of Birth	Race				
탘ㅣ	9								
	INDIVIDUAL	Address		Driver License Number					
	Z	3 3							
		, , ,							
		0n	Duty Crash	Safety Equipment					
	Saf	fety Equipment	Duty Crash	Safety Equipment					
		Seat Position		RESTRAINT USE UNKNOWN					
			T SIDE (DRIVER/MOTORCY						
		Helmet Use		Helmet Compliance					
		Themilet Use							
		Eye Protection		Tint Compliance					
~	5	Inju	ury Severity	Airbag					
2	001	Injury NO	D APPARENT INJURY	NOT APPLICABLE					
		Ejected	Ejection Path	Trapped/Extricated					
		NOT APPLICABLE	NOT EJECTED/NOT APPL	-ICABLE	NOT APPLICABLE				
		Medical Transport	•	EMS Agency Identifier	EMS Run #				
		NOT TRANSPORTED	·						
		Hospital		Date of Death	Time of Death				
		Distracted By Source							
		Distracted By Action							
	Striking Unit # Location								
		Prior Action							
		1							

19-08284

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Action								
	Ļ									
E	7 N C									
	ND									
	Action Other To/From Scho									To/From School
	,	Susp Drug & Alcohol	pected Alcohol U	lse	Suspected Drug Use					
	-	Alcohol Test Given						Alcohol Tes	Results	
		TEST NOT GIVEN			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				recound	
		Drug Test Given TEST NOT GIVEN	Drug Test Ty			Drug Test	Results			
	-	Drug Type								
9	001									
		Individual Condition								
		NOT OBSERVED								
·		t Summary Status			ehicle Operating As Classi	fication		Linit True a		
				v	enicle Operating As Classi	lication		Unit Type AUTOMOBILE		
02	Vehi	cle Type			<u> </u>			Operating As Endorsements		
0	_	SENGER CAR	Tasia (Dus # Ds						Tetellien	A-4 T
	1 ota 0	Occs	Train/Bus # Recorded		Total # Citations Issued 0		Total Trailers 0		Total HazMat Types	
	-	ance?	Direction Of Travel		Pre CrashTire Speed Lin		eed Limit	imit Total Lanes		S
UNIT	YES NOT ON ROADWAY				Mark pecial Function	05		Emergency	0	
5	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT				NO SPECIAL FUNCTION			NOT APPI		
		ic Way			Traffic Control			Traffic Control Inoperative/Missing		
	PARKING LOT OR PRIVATE PROPERTY Surface Type				NO CONTROL Road Curvature			NO Road Grade		
	BLACKTOP (BITUMINOUS)				STRAIGHT					
	Truck Bus or HazMat									
	NO									
		Vehicle License Plate Number		l r	Plate Type	St		Country of Is	suance	
		V788092			AUT - AUTOMOBILE	IL		UNITED STATES		
02	02	Vehicle Identification Number			Make	Yea		Model		
	0	3C3CFFAR0ET183197 Color			FIAT 2014 Body Style			Bus Use		
		BLK - BLACK			2H - HATCHBACK 2 DOOR			NOT A BUS		
	Щ	Initial Contact Point		١	/ehicle Damage					
UNIT	VEHICLE	1RIGHT FRONT COR Extent Of Damage	NER	1	1RIGHT FRONT CORNER					
	< N	MINOR DAMAGE								
		Towed Due To Damage			Vehicle Removed By OWNER					
		NOT TOWED What Driver Was Doing			/ehicle Factors					
	LEGALLY PARKED									
		Driver Prior Action Other		ſ	NOT APPLICABLE					

6TL0B1716R

19-08284

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Driver Actions NO CONTRIBUTING ACTION						
UNIT	VEHICLE							
	VEF							
		Owner Name	Owner Address					
02	02	FORREST E THRAWL (847) 651-8113	35589 N POPLAR AVE INGLESIDE, IL 60041 ,US					
		Sequence Of Events						
	01	Event PARKED MOTOR VEHICLE						
	02	Event Event						
	03							
	04	Event						
⊨	I	Policy Holder						
UNIT		Insurance Company	ASSOC,-THE FORREST THRAWL					
		FARMERS-AUTOMOBILE-INS-ASSOC,-THE						