19-09932

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	Primary Crash	Document #	Agency 19-099	Crash Number 32		Officer/Deputy	
Crash Date 08/09/2019	Crash Time 05:34 PM		Date Arr 08/09/2		Time Arrived	ł	
Date Notified	Time Notified		Total Un		Total Injured	Total Kille	ed
08/09/2019	05:36 PM		03		01	00	•
On Emergency	Hit and Run	Lane Closu	_			or Towed	Reporting Threshold
Government Property		chool Zone	NO	Bus Related	Tags		
Reportable	Crash Type PRIVATE PR	OPERTY/PARK	ING LOT		Ameno	led	Secondary Crash
Description						Reconstruction	a By
Ho-C	Chunk casino par on #1		unit 2			Photos By Additional Info	
drawing not to scale							
I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report. UNIT 1 WAS LEAVING THE CASINO, VEHICLE WAS IN REVERSE GEAR WHEN THE DRIVER DROPPED HIS HAT, REACHED OUT TO GET IT, AND FELL OUT OF THE TRUCK. UNIT 1 ROLLED BACKWARDS OVER DRIVER'S FOOT STRIKING THE UNOCCUPIED, LEGALLY PARKED UNIT 2 AND UNIT 3 CAUSING DAMAGE TO BOTH VEHICLES. DRIVER FROM UNIT 1 DID HAVE MINOR INJURIES AND REFUSED EMS. SURVEILLANCE FOOTAGE WAS RETRIEVED FROM HO-CHUNK CASINO.							
Location Arrowski Lot				Latitude		Longitu	ide
CTHBD NB LOT	N1			43.529245	5717	•	7282936
IN THE TOWN OF DELTO IN SAUK COUNTY	N			X Coordinat 275576.18 Structure Ty	375	Y Coor 48233	
onsin Motor Vehicle Crash DT4000		This report d	oes not in 1 of	clude any CJIS data. 6		Crash Da Crash Tin	

19-09932

Crash	Scene
-------	-------

	First	Harmful Event	First Harmful Event Location								
	PARKED MOTOR VEHICLE						OFF ROADWAY, LOCATION UNKNOWN				
	Manner of Collision						Light Condition				
	04	REAR TO REAR	DAYLIGHT								
	Road Surface Condition(s)						Factor(s)				
	DR۱	,									
	Envi	ronment Factor(s)									
	NOM	NE				NONE					
	Wea	ther Condition(s)									
	CLE										
	Anim	al Type					o Trafficwa AFFICWA	y Y - PARKIN	G LOT		
		h Classification - Location						Jurisdiction			
							E PROPE	RTY			
	I LIDS	I Land				Access Co NO CON				Special Study	
	With	n Interchange Area	Junction Location		Intersectio						
	NO	in interentinge / i eu	NON-JUNCTION			INTERSE	CTION				
	Uni	Summary									
	Unit	Status		Vehicle Ope	erating As C	lassification		Unit Type			
	ΙΝ Τ	RANSIT		D CLASS		TRUCK					
01		cle Type				Operating As Endorsements					
0		ITY TRUCK/PICKUP									
		Occs	Train/Bus # Recorded		Total # Citations Issued					Mat Types	
	01	2222	Direction Of Travel	0			0 Speed Lim		0 Total Land	00	
L	Insurance? Direction Of Travel YES NOT ON ROADWAY		Pre CrashTire		1	N/A			5		
UNIT		Harmful Event: Collision		Special Fun	iction		-	Emergency			
			LE		NO SPECIAL FUNCTION			NOT APPLICABLE Traffic Control Inoperative/Missing			
		ic Way K KING LOT OR PRIVA	TE PROPERTY	Traffic Cont	NO CONTROL			NO	roi inoperat	tive/missing	
		ace Type			Road Curvature			Road Grade			
		CKTOP (BITUMINOU	S)		STRAIGHT			LEVEL	LEVEL		
		k Bus or HazMat									
	NO										
	١	Vehicle									
		License Plate Number			Plate Type		St	Country of Issuance			
		EZ6500			SHT TRUC	κ	WI	UNITED STATES			
2	5	Vehicle Identification Nul 2GCEK19J88125052		Make CHEVRO	LET		Year 2008	Model SILVERADO			
	-	Color		Body Style				Bus Use			
		GRY - GRAY		PK - PICI				NOT A BU	S		
∟	Щ	Initial Contact Point 6REAR		Vehicle Da	image						
UNIT	P	6REAR Extent Of Damage	6RFAR	, 7LEFT	REAR CO	RNFR					
>	VEHICL	MINOR DAMAGE		V-NEAN	, / בבו ו						
		Towed Due To Damage	Vehicle Re	moved By							
		NOT TOWED		OWNER							
		What Driver Was Doing	POSITION	Vehicle Fa	ctors						
		LEAVING A PARKED POSITION Driver Prior Action Other			NOT APPLICABLE						

19-09932

		Driver Actions								
	ш	OTHER CONTRIBU	JTING .	ACTION						
нI	VEHICLE									
UNIT	2									
5	I									
-	Ш									
	>									
		Owner Name				Owner Address				
		CHAD M STAUFFA	ACHER			2560 NEW TOWN DR #	308			
2	01	(608) 279-9475	-			SUN PRAIRIE, WI 5359				
0	0	(000) = 0 0 0 0 0				,	• , • •			
		Sequence Of Ev	/ents							
	_	Event								
	01	PARKED MOTOR	VEHICI	LE						
	02	Event								
	0									
		Event								
	03	Event								
	0									
		Event								
	04									
.		Policy Holder								
UNIT						1				
Ξ		Insurance Company				Individual				
		PROGRESSIVE-UI	NIVERS	SAL-INSUR	ANCE-COMP	CHAD STAUFFACHER				
		ndividual								
		Driver				Citations Issued	Sex			
		CHAD M STAUFFA	ACHER			0	MALE			
		(608) 279-9475								
						Date of Birth	Race			
ΗI	ā						WHITE			
	INDIVIDUAL	Address				Driver License Number				
	δ		DR # 30	าย						
	Z	2 2560 NEW TOWN DR # 308 SUN PRAIRIE, WI 53590 , US				STATE: WISCONSIN COUNTRY: UNITED STATES				
	-									
			On Duty	Crash		Safety Equipment				
	Saf	ety Equipment	On Duty	orasir		Salety Equipment				
	Our	cty Equipment								
		Seat Position				NONE USED - VEHICLE OCCUPANT				
		1FRONT SEAT-L			P/MOTOPCV					
		Helmet Use				Helmet Compliance				
		Eye Protection				Tint Compliance				
						Tint Compliance				
-	Σ		Injury Se	everity		Airbag				
2	001	Injury	SUSPE	ECTED MIN	IOR INJURY	NON DEPLOYED				
	1	Ejected		Ejection Pa			Trapped/Extricated			
		NOT EJECTED		NOT EJE	CTED/NOT APP	LICABLE	NOT TRAPPED			
		Medical Transport				EMS Agency Identifier	EMS Run #			
		NOT TRANSPORT	FD			U .				
			20							
		Hospital				Date of Death	Time of Death			
			Distract	ed By Source	2		I			
		Distracted By	OTHE			FOOD, GROOMING)				
		Distracted By Action		-						
		OTHER ACTION (L	OOKIN	IG AWAY	FROM TASK ET	C)				
						*				
		Non Motorist	Striking	Unit #	Location					
		non motorist								
		Prior Action			-					

19-09932

UNIT	INDIVIDUAL	Action									
		Action Other	To/From School								
	L	Drug & Alcohol NO	pected Alcohol L	lse	Suspected Drug Use NO						
		Alcohol Test Given Alcohol Test Ty		e		Alcohol Tes	t Results				
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Res	sults				
01	001	Drug Type									
		Individual Condition									
		APPEARED NORMAL									
	Uni	t Summary									
	Unit				Vehicle Operating As Class D CLASS	sification	Unit Type	Unit Type AUTOMOBILE			
2		cle Type			DCLASS		S Endorsem	ents			
02	-	SENGER CAR			Total # Citations Issued Total Trailers Total HazMat Types						
	Tota 0	Occs	Train/Bus # Re		Total # Citations Issued 0	railers	Total Haziv	lat Types			
Т	Insur YES	ance?	Direction Of Tra NOT ON RO		Pre CrashTire Mark	Limit	mit Total Lanes				
UNIT		: Harmful Event: Collision Wi FOR VEH IN TRANSPOI			Special Function NO SPECIAL FUNCTI	Emergency NOT APP	Motor Vehic	ie Use			
		ic Way KING LOT OR PRIVATI	E PROPERTY		Traffic Control NO CONTROL	Traffic Con NO	Traffic Control Inoperative/Missing NO				
					Road Curvature		Road Grade				
		CKTOP (BITUMINOUS) k Bus or HazMat)	•	STRAIGHT						
	NO										
		Vehicle				St	Country of L				
		License Plate Number 180WXA			Plate Type AUT - AUTOMOBILE	-	Country of Issuance UNITED STATES				
02	02	Vehicle Identification Numb			Make LEXUS	Year 2016	Model ES	Model			
	0	JTHBK1GG2G2219812 Color			Body Style	Bus Use	Bus Use				
	ш	GRY - GRAY Initial Contact Point			SD - SEDAN Vehicle Damage		NOT A BU	NOT A BUS			
UNIT		6REAR			venicie Daniage						
5	VEHICL	Extent Of Damage MINOR DAMAGE			6REAR, 7LEFT REAR CORNER						
		Towed Due To Damage NOT TOWED			Vehicle Removed By OWNER						
		What Driver Was Doing			Vehicle Factors						
		LEGALLY PARKED Driver Prior Action Other			NOT APPLICABLE						

19-09932

UNIT	VEHICLE	Driver Actions NO CONTRIBUTING ACTION								
	ΛEł									
02	02	Owner Name CONNOR P BREHM (262) 930-2535			Owner Address 5146 CYNTHIA LN RACINE, WI 53406 , US					
	ę	Sequence Of Events								
	2	Event MOTOR VEH IN TRANSPORT								
	02	Event								
	03	Event								
		Event								
	04									
⊨	I	Policy Holder								
UNIT		Insurance Company KEMPER-INDEPENDE	NCE-INS-CO		ndividual CONNOR BREHM					
1		t Summary								
		Status			cle Operating As Classificati	on	Unit Type AUTOMOBILE			
6		cle Type					As Endorsements			
03	-	SENGER CAR	Tasia (Dua # Dagandad	1= .		Tatal Tas	1	Tatal HanMat Turan		
	Total Occs Train/Bus # Recorded				Total # Citations Issued Total Traile			Total HazMat Types 0		
		rance?	Direction Of Travel		Pre CrashTire	Speed Lir	mit	Total Lanes		
UNIT	YES Most	Harmful Event: Collision Wi	NOT ON ROADWAY		Mark N/A Special Function			Emergency Motor Vehicle Use		
			RT							
		ic Way R KING LOT OR PRIVAT I	E PROPERTY		Traffic Control NO CONTROL			Traffic Control Inoperative/Missing NO		
		ace Type			Road Curvature			Road Grade		
		ACKTOP (BITUMINOUS) k Bus or HazMat		STF	STRAIGHT LEVEL					
	NO	K Bus of Hazivial								
		Vehicle								
		License Plate Number 616KKB			te Type I T - AUTOMOBILE	St WI	Country of Is			
_	~	Vehicle Identification Numb	ber	Mal		Year	Model			
33	03	1FADP3F22EL234658			RD	2014	FOCUS SE	E		
		Color RED - RED			dy Style - 4DR		Bus Use NOT A BUS			
.	Щ	Initial Contact Point		Veł	nicle Damage					
UNIT	VEHICLE	6REAR Extent Of Damage		6	REAR					
	ΥĒ	FUNCTIONAL DAMAG	E							
		Towed Due To Damage NOT TOWED			nicle Removed By VNER					
		What Driver Was Doing			nicle Factors					
		Driver Prior Action Other			AFFLIGADLE					

19-09932

L	Ľ	NO CONTRIBUTING ACTION						
UNIT	VEHICL							
D	/Eŀ							
	-							
		Owner Name	Owner Address					
03	03	RAFAEL NMI SANTA MARIA BELTRAN (608) 320-9011	627 W LAKESIDE ST MADISON, WI 53715 , US					
0	0	(008) 320-9011	MADISON, WI 53715 , 05					
		Sequence Of Events						
	01	Event MOTOR VEH IN TRANSPORT						
	0							
	02	Event						
	•	-						
	03	Event						
	•							
	04	Event						
F		Policy Holder						
UNIT		Insurance Company	Individual					
		GEICO-GENERAL-INS-CO	RAFAEL SANTA MARIA BELTRAN					