WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

~	Crash Date		Cr
8M7VR	08/20/2019		01
17	Date Notified		Tir
<u>\$</u>	08/20/2019		02
0B8	On Emergency	Hit	an
3TL	Government Property		
•			

Document Number Override		I		Agency Crash Number 19-10427		Investigating Officer/Deputy DEPUTY B. MEARS		
Gradii Bate		Date Arrived 08/20/2019		Time Arrived 02:23 PM				
Date Notified 08/20/2019		Time Notified 02:08 PM		Total Units 02		Total Injured 00	Total Killed 00	
On Emergency Hit and Run Lane Clos		Lane Closu	sure Work Zone		Trailer or	Towed	Reporting Threshold	
Government Property Active School Zone		School Bus Related NO		Tags				
Crash Type PRIVATE PROPERTY/PARK				NG LO	Г	Amended		Secondary Crash

Description



Reconstruction By

Photos By
DEPUTY MEARS

Additional Information **PHOTOS**

UNIT 1 WAS OPERATOR WAS BACKING UP OUT OF A PARKING SPACE WHEN SHE STRUCK UNIT 2 WHICH WAS LEGALLY PARKED AND UNOCCUPIED. UNIT 1 STRUCK UNIT 2 WITH THE REAR RT CORNER OF UNIT 1 STRIKING REAR LEFT CORNER OF UNIT 2. THERE WERE NO INJURIES. BOTH UNITS HAD MINOR DAMAGE AND WERE DRIVEN FROM THE SCENE BY THE OWNER/OPERATORS.

Location

PARKING LOT WACHTER AVE/ STH23 EB LOT 825 MAIN (HOUSE/BUILDING 825 MAIN)

IN THE VILLAGE OF PLAIN IN SAUK COUNTY

Latitude Longitude 43.278417 -90.042947 X Coordinate Y Coordinate 253090.0625 4796230.5 Structure Type HOUSE/BUILDING

WISCONSIN MOTOR VEHICLE CRASH REPORT

First Harmful Event Location

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Scene First Harmful Event

Traffic Control Traffic Control Inoperative/Missing PARKING LOT OR PRIVATE PROPERTY PARKING LOT OR PRIVATE PROPERTY NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AFX1245 Vehicle Identification Number 1G1ZB5ST9JF229807 Color Body Style SD - SEDAN Initial Contact Point 6REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Traffic Control Inoperative/Missing NO Road Curvature Road Grade LEVEL Traffic Control Inoperative/Missing NO NO NO NO STRAIGHT LEVEL St Country of Issuance UNITED STATES Vehicle Identification Number Make Vear Model NOT A BUS NOT A BUS Final Contact Point NO NO NO STRAIGHT LEVEL Fraffic Control Inoperative/Missing NO NO NO STRAIGHT LEVEL Fraffic Control Inoperative/Missing NO Road Grade LEVEL Vehicle Velle St Country of Issuance UNITED STATES Will UNITED STATES Welled Note Indicate No ABUS Fraffic Control Inoperative/Missing NO Road Grade Road Grade Road Grade Road Grade Road Grade Road Grade R			TOR VEH IN TRANSI	PORT	IN PARKING LANE OR ZONE							
Road Surface Condition(s) DRY						~						
DRY Environment Factor(s) NONE NONE												
Environment Factor(s) NONE Weather Candition(s) CLOUDY Animal Type Crash Classification - Location PRIVATE PROPERTY Tribal Land NO CONTROL Within Interchange Area NON-JUNCTION Unit Summary Intersection Type NON-JUNCTION Vehicle Operating As Classification Intersection Of 1 On On Roadway PASSENGER CAR Total Cocs Of 1 On On Roadway Most Partful Event: Collision With Total Hazimal Types Of 1 On On Roadway Most Partful Event: Collision With Travel Trific Way PARKED MOTOR VEHICLE Traffic Way PARKED MOTOR VEHICLE Traffic Control Traffic Control NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NOT APPLICABLE Traffic Control NO SURGe Type PARKED MOTOR VEHICLE Traffic Way PARKED MOTOR VEHICLE Traffic Control NO SURGe Type PARKED MOTOR Type PARKED MOTOR Type PARKED MOTOR PA		Road	d Surface Condition(s)		Roadway Factor(s)							
NONE Weather Condition(s) CLOUDY Animal Type Animal Type Crash Classification - Location PRIVATE PROPERTY Tribal Land NO NONTROL Within Inferchange Area Junction Location NO NON-JUNCTION NOT AN INTERSECTION Unit Summary IN TRANSIT D CLASS AUTOMOBILE Operating As Classification Operating As Endorsements AutoMobile Verbide Operating As Classification Operating As Endorsements Total Packet Operating As Endorsements Total Packet Not On Roadway Mark NA Most Harmful Evert Collision With PARKED MOTOR VEHICLE Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL NO SUrface Type PARKED MOTOR VEHICLE Traffic Control NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO APPLICABLE Traffic Control NO SUrface Type PARKED MOTOR PRIVATE PROPERTY NO CONTROL NO Vehicle Ucense Plate Number APT-1245 AUT - AUTOMOBILE Vehicle Identification Number Globary Syle SIT-AGE APT-1245 AUT - AUTOMOBILE Vehicle Ucense Plate Number APT-1245 AUT - AUTOMOBILE Vehicle Identification Number Globary Syle SIT-AGE Vehicle Ucense Plate Number APT-1245 AUT - AUTOMOBILE Vehicle Identification Number Globary Syle SIT-AGE Vehicle Ucense Plate Number APT-1245 AUT - AUTOMOBILE Vehicle Identification Number Globary Syle SIT-AGE Vehicle Ucense Plate Number APT-1245 AUT - AUTOMOBILE Vehicle Identification Number Globary Syle SIT-AGE Vehicle Ucense Plate Number APT-1245 AUT - AUTOMOBILE Vehicle Identification Number Globary Syle SIT-AGE Vehicle Identification Number Vehicle Ucense Plate Number APT-1245 AUT - AUTOMOBILE Vehicle Removed By NOT A BUS Vehicle Removed By NOT A BUS Vehicle Removed By Vehicle Part AVID Removed By Vehicle Removed By Vehicle Damage William Traffic Control By Vehicle Damage William Traffic Control By Vehicle Damage William Traffic Control By Vehicle Removed By Vehic		DRY	•									
Weather Condition(s) CLOUDY Animal Type		Envi	ronment Factor(s)									
CLOUDY Animal Type Relation To Trafficway Access Control No CONTROL Within Interchange Area Junction Location No Non-Junction No Non-Junction		МОИ	NE		NONE							
Animal Type Animal Type Relation To Trafficway NON TRAFFICWAY - PARKING LOT Crash Classification - Jurisdiction PRIVATE PROPERTY Tribal Land Access Control NO CONTROL Within Interchange Area NON-JUNCTION Unit Summary Unit Status PASSENGER CAR Total Cocs I Train/Bus # Recorded I Insurance? Direction Of Travel PRE PROPERTY Pre CrashTire NOT ON ROADWAY Mark NA NOT ON ROADWAY PRIVATE PROPERTY Interchange Area NOT ON ROADWAY PRAYED FOR PROPERTY Total HazMat Types Operating As Classeffication O		Wea	ther Condition(s)									
NON TRAFFICWAY - PARKING LOT Crash Classification - Location PRIVATE PROPERTY PRIVATE PROPERTY												
PRIVATE PROPERTY Tribal Land Access Control NO CONTROL Within Interchange Area NON-JUNCTION NON-		Anim	al Type				-	G LOT				
Tribal Land Access Control NO CONTROL				n								
Within Interchange Area Junction Location Non-Junction Intersection Type Not An Intersection Type Operating As Classification Unit Type AutoMobile Operating As Classification Unit Type AutoMobile Operating As Classification Operating As Classificatio									RTY		I o	
Within Interchange Area Junction Location Non-Junction Non		I riba	ıı Land								Special Study	
Unit Summary Unit Status IN TRANSIT I Vehicle Operating As Classification IN TRANSIT I Vehicle Type PASSENGER CAR Total Occs O1 Insurance? Direction Of Travel PARKING LOT OR PRIVATE PROPERTY IT Vehicle IT Taffic Control INO SURface Type BLACKTOP (BITUMINOUS) IT TUCK Bus or HazMat INO Vehicle United State It Country of Issuance It Country Of It Country Of Issuance It Country Of Issuance It Country Of Is		With	n Interchange Area	Junction Location		Intersectio					1	
Unit Status		NO		NON-JUNCTION		NOT AN	INTERSE	CTION				
IN TRANSIT	Ī	Unit Summary										
Vehicle Type PASSENGER CAR Total Occs Of Insurance? YES Most Harmful Event: Collision With PARKED MOTOR VEHICLE Traffic Way PARKING LOT OR PRIVATE PROPERTY Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle Vehicle Identification Number AFX1245 Vehicle Identification Number Initial Contact Point SD - SEDAN Initial Contact Po					<u> </u>	erating As Cl	assification		Unit Type			
PASSENGER CAR Total Occs O1 O1 O2 O3 O4 O5 O4 O5 O5 O1 O5				D CLASS	D CLASS							
Total Cocs O1	2		**						Operating A	s Endorser	nents	
Discrimination of the control of t				Total # Citat	tions lecued		Total Trai	ilers	Total Haz	Mat Types		
Insurance? Direction Of Travel NOT ON ROADWAY Mark N/A			0003	Train, Suo # Nooolueu							1,500	
VES											es	
Traffic Control Traffic Control Inoperative/Missing PARKING LOT OR PRIVATE PROPERTY PARKING LOT OR PRIVATE PROPERTY Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AFX1245 Vehicle Identification Number 1G1ZB5ST9JF229807 Color Body Style SD - SEDAN Initial Contact Point 6REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Traffic Control Inoperative/Missing NO Traffic Control Inoperative/Missing NO Road Curvature Road Grade LEVEL Traffic Control Inoperative/Missing NO NO NO STRAIGHT LEVEL St Country of Issuance UNITED STATES Will UNITED STATES Model UNITED STATES Model MALIBU Vehicle Damage NOT A BUS Finitial Contact Point 6REAR Extent Of Damage NOT A BUS Vehicle Removed By OPERATOR	⊑ l					☐ Mark						
Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AFX1245 Vehicle Identification Number 1G1ZB5ST9JF229807 Color Body Style SD - SEDAN Initial Contact Point 6REAR MINOR DAMAGE Towed Due To Damage NOT TOWED Traffic Control NO Road Curvature Road Grade LEVEL Road Grade LEVEL Country of Issuance WI UNITED STATES Vehicle Identification Number Body Style SD - SEDAN NOT A BUS Vehicle Damage NOT A BUS Vehicle Damage Vehicle Removed By OPERATOR	S											
PARKING LOT OR PRIVATE PROPERTY Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Plate Type AFX1245 Vehicle License Plate Number AFX1245 Vehicle Identification Number 1G1ZB5ST9JF229807 Color Body Style SD - SEDAN Initial Contact Point 6-REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Road Curvature Road Grade LEVEL Road Grade Road Grade Road Curvature Road Grade Road Road Road Road Road Road Road Road												
BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Technic Bus Use NOT A BUS Technic Bus U			•					· · · · · · · · · · · · · · · · · · ·				
Truck Bus or HazMat NO Vehicle License Plate Number AFX1245 Vehicle Identification Number 1G1ZB5ST9JF229807 Color Body Style SD - SEDAN Initial Contact Point 6REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Vehicle Identification Number Body Style SD - SEDAN Vehicle Damage 6REAR Vehicle Damage Vehicle Removed By OPERATOR									Road Grade			
Vehicle License Plate Number AFX1245 AUT - AUTOMOBILE WI UNITED STATES Vehicle Identification Number Make Year Model 1G1ZB5ST9JF229807 CHEVROLET 2018 MALIBU Color Body Style SD - SEDAN NOT A BUS Initial Contact Point 6-REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Vehicle Removed By OPERATOR				US)	STRAIGH	STRAIGHT			LEVEL			
Vehicle License Plate Number AFX1245 Vehicle Identification Number 1G1ZB5ST9JF229807 Color Initial Contact Point 6REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Plate Type AUT - AUTOMOBILE WI UNITED STATES Whodel UNITED STATES WINOR DAMAGE Plate Type AUT - AUTOMOBILE WI UNITED STATES WINOR DAMAGE File Type AUT - AUTOMOBILE WI UNITED STATES Bus Use NOT A BUS Vehicle Damage FREAR Vehicle Removed By OPERATOR			k Bus or HazMat									
License Plate Number			, , , ,									
AFX1245 Vehicle Identification Number 1G1ZB5ST9JF229807 Color Body Style SD - SEDAN Initial Contact Point 6REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED AUT - AUTOMOBILE WI UNITED STATES Waddet Year Model Year Model Sus Use NOT A BUS Bus Use NOT A BUS Vehicle Damage 6REAR 6REAR Vehicle Removed By OPERATOR					15: -			C4	LOguerte C			
Vehicle Identification Number 1G1ZB5ST9JF229807 Color Body Style SD - SEDAN Initial Contact Point 6REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Wake CHEVROLET 2018 MALIBU Bus Use NOT A BUS Bus Use NOT A BUS C-REAR Vehicle Damage 6REAR Forwar Model ALIBU Bus Use NOT A BUS Vehicle Damage OREAR OREAR Vehicle Removed By OPERATOR									1 '			
Towed Due To Damage Not Towed Due Towed Du									AIES			
Initial Contact Point Vehicle Damage	5	2										
Initial Contact Point 6REAR Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Vehicle Damage 6REAR Vehicle Damage Vehicle Removed By OPERATOR			Color		1							
Sample S		ш	Initial Contact Point					1101 A 200				
Towed Due To Damage Vehicle Removed By NOT TOWED OPERATOR	╘╽			. Sillolo Da	Tomore Damage							
Towed Due To Damage Vehicle Removed By NOT TOWED OPERATOR	<u>z</u>	Ĭ		6REAR								
NOT TOWED OPERATOR		VE	MINOR DAMAGE									
			•	9		1						
What Driver Was Doing Vehicle Factors BACKING			What Driver Was Doing		Vehicle Fac	ctors						
Driver Prior Action Other NOT APPLICABLE				er	NOT APP	NOT APPLICABLE						
		Driver Prior Action Other										
					<u>J</u>							

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

LIND	VEHICLE	Driver Actions UNSAFE BACKING, OPERATED MOTOR VEHICLE IN INATTENTIVE, CARELESS OR ERRATIC MANNER, LOOKED BUT DID NOT SEE									
10	01	Owner Name SUSAN ANNETTE (608) 588-4022	RING			Owner Address 1675 HONEY CREEK CIR PLAIN, WI 53577 , US					
	,	Sequence Of Ev	/ents								
	01	PARKED MOTOR	VEHIC	LE							
	02	Event									
	03	Event									
	04	Event									
<u>⊢</u>		Policy Holder									
TIN D		Insurance Company				Individual					
		ALL-AMERICA-INS	S-CO			SUSAN RING					
		Individual Driver				Citations Issued	Sex				
	_	SUSAN ANNETTE RING				0	FEMALE				
_	DUA	(608) 588-4022				Date of Birth	Race WHITE				
LIND	INDIVIDUAL	Address 1675 HONEY CREEK CIR PLAIN, WI 53577 , US				Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES					
	Sat	ety Equipment	On Duty	/ Crash		Safety Equipment					
	Gai	Seat Position				SHOULDER & LAP BELT					
		1FRONT SEAT-L	EFT SI	DE (DRIVER	/MOTORCY		•				
		Helmet Use				Helmet Compliance					
		Eye Protection				Tint Compliance					
7	001	Inium	Injury S	everity		Airbag					
0	ŏ		NO AF	PARENT IN		NON DEPLOYED	T				
		Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT AP				ICARI F	Trapped/Extrice NOT TRAPE				
		NOT EJECTED NOT EJECTED/NOT API Medical Transport				EMS Agency Identifier	EMS Run #				
		NOT TRANSPORTED									
		Hospital				Date of Death	Time of Death				
		Distracted By OTHER DISTRACTION (ANIMAL, FOOD, GROOMING)									
		Distracted By Action OTHER ACTION (L				()					
		Non Motorist	Striking	Unit #	Location						
		Prior Action									

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		_									
LIND	INDIVIDUAL	Action									
		Action Other								To/Erom Cohool	
		Action Other								To/From School	
	1	Drug & Alcohol NO	pected Alcohol U	Jse	Suspected Drug Use NO						
•		Alcohol Test Given		Alcohol Test Ty	уре			Alcohol Tes	t Results		
		TEST NOT GIVEN									
		Drug Test Given TEST NOT GIVEN		Drug Test Type	•	Drug	Test Results	.			
9	00	Drug Type									
•		Individual Condition									
		APPEARED NORMAL									
I	l Ini	t Summary									
		Status			Vehicle Operating As Class	sification	1	Unit Type			_
	LEG	BALLY PARKED			D CLASS			TRUCK			
05		cle Type						Operating A	s Endorsem	nents	
0		LITY TRUCK/PICKUP TI									
		I Occs	Train/Bus # Re	ecorded	Total # Citations Issued Total Traile			ers	Total HazN	Mat Types	
	_	0 Direction Of Travel			0 0 Speed Lim			imit Total Lanes		oe .	
_				ADWAY	Pre CrashTire N/A		I .	iit	Total Lanc		
L N O	Mos	Most Harmful Event: Collision With			Special Function Emergency Mote NO SPECIAL FUNCTION NOT APPLICATION				cle Use		
_		TOR VEH IN TRANSPO	RT		NO SPECIAL FUNCTION						
		ic Way R KING LOT OR PRIVATI	E DDODEDTV	,	Traffic Control NO CONTROL			Traffic Control Inoperative/Missing NO			
		ace Type	EFROPERIT		Road Curvature			Road Grade			
		BLACKTOP (BITUMINOUS)			STRAIGHT			LEVEL			
	Truc	k Bus or HazMat									
	NO										_
	,	Vehicle									
	License Plate Number				Plate Type		St	Country of Is			
		DX7770 Vehicle Identification Numb	nor.		LTK - LIGHT TRUCK Make		WI UNITED STATES Year Model		IAIES		
02	02	5TFAW5F1XGX531725			TOYOTA		2016	Model TUNDRA			
•		Color			Body Style		Bus Use				
		GRY - GRAY Initial Contact Point 6REAR Extent Of Damage FUNCTIONAL DAMAGE			PK - PICKUP			NOT A BUS			
_	빌				Vehicle Damage						
LNO	$\stackrel{\circ}{=}$				6REAR						
⊃	Ē	FUNCTIONAL DAMAGE			V-REAK						
		Towed Due To Damage		Vehicle Removed By							
	NOT TOWED				OPERATOR						
		What Driver Was Doing			Vehicle Factors						
		LEGALLY PARKED Driver Prior Action Other			NOT APPLICABLE						
Sitted A Michael Curici											
l					1						

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Driver Actions							
NO CONTRIBUTING ACTION							
Owner Name	Owner Address						
JOHN S KOSCIELNIAK	S144 OLD HWY 12						
(608) 963-9595	WISCONSIN DELLS, WI 53965, US						
Sequence Of Events							
Event							
MOTOR VEH IN TRANSPORT							
Event							
Event							
Frank							
Event							
Event							
Policy Holder							
Insurance Company	Organization/Company						
AMERICAN-FAMILY-INS-CO	MARQUIS INN						
	Owner Name JOHN S KOSCIELNIAK (608) 963-9595 Sequence Of Events Event MOTOR VEH IN TRANSPORT Event Event Event Policy Holder Insurance Company						