

6TL097RB3Q
19-10951

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL097RB3Q

Document Number Override		Primary Crash Document #	Agency Crash Number 19-10951	Investigating Officer/Deputy DEPUTY L. GJORGJIEV	
Crash Date 09/01/2019		Crash Time 07:12 PM	Date Arrived 09/01/2019	Time Arrived 07:24 PM	
Date Notified 09/01/2019		Time Notified 07:13 PM	Total Units 01	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input checked="" type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p>	Reconstruction By
	Photos By 9188
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS DRIVING SOUTHBOUND ON HWY 58. THE DRIVER SAID A DEER JUMPED OUT ON THE ROADWAY. THE DRIVER TOLD ME HE SWERVED TO THE RIGHT TO TRY TO AVOID THE DEER BUT WAS UNSUCCESSFUL. THE DRIVER SAID HE HIT THE DEER AND LOST CONTROL OF THE VEHICLE. THE VEHICLE WENT IN THE DITCH AND STRUCK A BARBWIRE FENCE. THE VEHICLE WENT THROUGH THE FENCE AND CAME TO REST IN THE FIELD.

Location

ON STH58 SB 281 FT S OF WILKE RD IN THE TOWN OF LA VALLE IN SAUK COUNTY	Latitude 43.604185039	Longitude -90.124315963
	X Coordinate 247845.25	Y Coordinate 4832656
	Structure Type NO STRUCTURE	

6TL097RB3Q

19-10951

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Crash Scene

First Harmful Event NON DOMESTICATED ANIMAL (ALIVE)		First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) ANIMAL (S) IN ROADWAY			
Weather Condition(s) CLEAR			
Animal Type DEER		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	
Closure Type OTHER CLOSURE		Reasons for Closure	
Date Initial Lane/Rd Closed 09/01/2019	Time Initial Lane/Rd Closed 08:00 PM	TOW TRUCK	
Date All Lanes Open 09/01/2019	Time All Lanes Open 08:20 PM	Date Scene Cleared 09/01/2019	Time Scene Cleared 08:30 PM

Unit Summary

01 UNIT	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel SOUTHBOUND	<input checked="" type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With NON DOMESTICATED ANIMAL (ALIVE)		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

01 VEHICLE	Vehicle				
	License Plate Number 392XDS		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number KNAGD126145326860		Make KIA MOTORS CORPORA	Year 2004	Model OPTIMA LX/
	Color BLU - BLUE		Body Style 4D - 4DR		Bus Use NOT A BUS
	Initial Contact Point 12--FRONT		Vehicle Damage		
	Extent Of Damage FUNCTIONAL DAMAGE		1--RIGHT FRONT CORNER, 2--RIGHT SIDE FRONT, 10--LEFT SIDE FRONT, 11--LEFT FRONT CORNER, 12--FRONT, TOP		
	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing GOING STRAIGHT				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Driver Prior Action Other		Vehicle Factors		
			NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
01	Owner Name LINA M PALIONIS (608) 425-0614		Owner Address 30718 MOSS HOLLOW LN LONE ROCK, WI 53556 , US		
	Sequence Of Events				
01	01	Event NON DOMESTICATED ANIMAL (ALIVE)			
	02	Event RUN OFF ROADWAY RIGHT			
	03	Event DITCH			
	04	Event FENCE			
UNIT	Policy Holder				
	Insurance Company STATE-FARM-GENERAL-INS-CO		Individual OSSIAN SHARP		
UNIT INDIVIDUAL	Individual				
	Driver OSSIAN GINTARAS SHARP (608) 583-2910		Citations Issued 0	Sex MALE	
	Address 30718 MOSS HOLLOW LN LONE ROCK, WI 53556 , US		Date of Birth	Race WHITE	
			Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES		
01	Safety Equipment		On Duty Crash		
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
001	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		
	Trapped/Extricated NOT TRAPPED		Medical Transport NOT TRANSPORTED		
	Hospital		EMS Agency Identifier	EMS Run #	
			Date of Death	Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action NOT DISTRACTED					
Non Motorist		Striking Unit #	Location		
Prior Action					

6TL097RB3Q

19-10951

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	INDIVIDUAL	Action				
		Action Other			To/From School	
	01	001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
			Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
			Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
			Drug Type			
			Individual Condition			
			APPEARED NORMAL			

Property Owner

PROP OWNER	01	Individual KAREN GEITZ (608) 393-4915	Address S1078 HWY 58 LAVALLE, WI 53941 , US
-------------------	-----------	--	---

Fixed Objects Struck

01	Striking Unit 01	Struck Object FENCE	Structure Number	Damage Tag Number
-----------	----------------------------	-------------------------------	------------------	-------------------