

6TL09N3P7R
19-13560

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL09N3P7R

Document Number Override		Primary Crash Document #	Agency Crash Number 19-13560	Investigating Officer/Deputy DEPUTY C. FRANK	
Crash Date 10/31/2019		Crash Time 09:30 AM	Date Arrived 10/31/2019	Time Arrived 01:21 PM	
Date Notified 10/31/2019		Time Notified 12:03 PM	Total Units 01	Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable	Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash	

Description

Diagram		Reconstruction By
		Photos By CRAIG'S TOWING
		Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON THE ABOVE DATE AND TIME UNIT 1 WAS NORTHBOUND ON HERWIG RD AT WHITETAILED DR. UNIT 1 ENCOUNTERED ICE, SNOW AND SLUSH ON THE ROADWAY. UNIT 1 OPERATOR LOST CONTROL OF UNIT 1. UNIT 1 SLID ON THE ICE INTO THE WEST DITCH, STRUCK A TREE AND CAME TO A REST. UNIT 1 OPERATOR CONTACTED HER PARENTS WHO CALLED FOR A TOW. I MET WITH OPERATOR AND PARENTS TO GATHER CRASH INFO.

Location

ON HERWIG RD 402 FT S OF SOUTH AVE IN THE TOWN OF DELLONA IN SAUK COUNTY	Latitude 43.574911239	Longitude -89.837156482
	X Coordinate 270910.96875	Y Coordinate 4828572.5
	Structure Type NO STRUCTURE	

6TL09N3P7R
19-13560

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Crash Scene

First Harmful Event TREE		First Harmful Event Location ROADSIDE	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT		Light Condition DAWN	
Road Surface Condition(s) WET, SNOW, SLUSH, ICE		Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS			
Weather Condition(s) SNOW			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	

Unit Summary

UNIT 01	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type (SPORT) UTILITY VEHICLE				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 45	Total Lanes 2	
	Most Harmful Event: Collision With TREE		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade UPHILL	
	Truck Bus or HazMat NO					

Vehicle

UNIT 01 VEHICLE	License Plate Number ABK2642		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
	Vehicle Identification Number 5UXFA53533LV83581		Make BMW	Year 2003	Model X5	
	Color BLK - BLACK		Body Style UT - SPORT UTILITY VEHICLE		Bus Use NOT A BUS	
	Initial Contact Point 12--FRONT		Vehicle Damage			
	Extent Of Damage DISABLING DAMAGE		12--FRONT			
	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By CRAIGS TOWING			
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors			
	Driver Prior Action Other		NOT APPLICABLE			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	VEHICLE	Driver Actions SPEED TOO FAST/COND, FAILURE TO CONTROL	
		Owner Name CARLA L BEYER (608) 448-9712	Owner Address S1592 HERWIG RD WISCONSIN DELLS, WI 53965 , US
01	01	Sequence Of Events	
	01	Event TREE	
	02	Event	
	03	Event	
	04	Event	
UNIT	INDIVIDUAL	Policy Holder	
		Insurance Company WISCONSIN-MUTUAL-INS-CO	Individual CARLA BEYER
UNIT	INDIVIDUAL	Individual	
		Driver ISABELLA FAY VEDRO (608) 566-4183	Citations Issued 0
		Date of Birth	Sex FEMALE
		Race WHITE	
		Address 617 BASCOM HILL DR BARABOO, WI 53913 , US	Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES
UNIT	001	Safety Equipment	
		On Duty Crash	Safety Equipment SHOULDER & LAP BELT
		Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY	
		Helmet Use	Helmet Compliance
		Eye Protection	Tint Compliance
		Injury Injury Severity POSSIBLE INJURY	Airbag DEPLOYED-FRONT
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE
		Trapped/Extricated NOT TRAPPED	
		Medical Transport NOT TRANSPORTED	EMS Agency Identifier
		EMS Run #	
		Hospital	Date of Death
		Time of Death	
		Distracted By Distracted By Source NOT APPLICABLE (NOT DISTRACTED)	
		Distracted By Action NOT DISTRACTED	
		Striking Unit #	Location
		Non Motorist	
		Prior Action	

6TL09N3P7R

19-13560

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	INDIVIDUAL	Action				
		Action Other		To/From School		
	01	001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
			Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
			Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
			Drug Type			
			Individual Condition APPEARED NORMAL			