19-13810

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	Primary Crash I	Primary Crash Document # Crash Time 08:00 AM Time Notified		Agency Crash Number 19-13810 Date Arrived 11/06/2019 Total Units		Investigating Officer/Deputy DEPUTY H. VOLZ Time Arrived 08:32 AM		
Crash Date 11/06/2019								
Date Notified	Time Notified					Total Injured Total Killed		
11/06/2019	08:06 AM	1	01		00	00		
On Emergency	Hit and Run	Lane Closu		Work Zone		or Towed	Reporting Threshold	
Government Property		chool Zone	School NO	Bus Related	Tags			
Reportable	Crash Type DT4000 (STA	H)		Amended		Secondary Crash		
Description								
Diagram Reconstruction By								
					_			
			1		92/	Photos By		
- AND	- Tak	//	1	T.		Additional Infor	mation	
		All				NONE		
		All.			11			
	-		1		and the second			
Not to scale	10 -	and the						
1		1		12 32				
	X 1	11		wh				
		1//	//	Highwas	a set a			
an and a start			county	HIGTMENT				
a state of	- ///	///25		mile				
	111	16-10-						
✓ I, a sworn law enforce								
UNIT 1 WAS TRAVELING EB NEGOTIATE A RIGHT CURVE UNIT 1 CROSSED THE CENT	DOWN A HILL. UN	IT 1 STRUCK A PA	TCH OF	SNOW AND SLUSH AND	THE VEHICLE \	NAS SPUN AR		
Location								
ON E73444 CTHH EB				Latitude		Longitu		
542 FT E OF D AND W RD				43.5881515	61	-89.952		
(FIRE E73444)				X Coordinate 261672.265		Y Coord 483030		
IN THE TOWN OF DELLOI IN SAUK COUNTY	NA			Structure Type	9			

This report does not include any CJIS data. 1 of 4

19-13810

WISCONSIN MOTOR VEHICLE CRASH REPORT

Crash Scene

	First	Harmful Event	First Harmful Event Location								
	EME	BANKMENT	ON ROADWAY								
	Man	ner of Collision	Light Condition								
	NO	COLLISION W/VEHIC	DAYLIGHT								
	Road	oad Surface Condition(s)				Roadway Factor(s)					
	WE.	ET, SNOW, SLUSH									
	Envi	ronment Factor(s)									
	WEATHER CONDITIONS N						NONE				
	Wea	ther Condition(s)									
	CLC	OUDY, RAIN, SNOW									
	Anim	nal Type				Relation To Trafficway TRAFFICWAY - NOT ON ROAD					
		h Classification - Location						Jurisdiction			
	-							ISDICTION			
	I rida	al Land					Access Control NO CONTROL			Special Study	
	\\/ith	in Interchange Aree	Junction Location		Intersectio		IKOL				
	NO	in Interchange Area	NON-JUNCTION			INTERSE	CTION				
	_	-	Non-concrict								
		t Summary		Vakiala Ora							
		Unit Status Vehicle Operating As C IN TRANSIT D CLASS					lassification Unit Type AUTOMOBILE				
		cle Type		DCLASS		Operating As Endorsements			ments		
01		ORT) UTILITY VEHICL	E								
	•		Train/Bus # Recorded	Total # Cita	Total # Citations Issued		Total Trailers T		Total HazMat Types		
	1			0	0		0		0		
	Insurance? Direction Of Travel		Pre	Pre CrashTire		Speed Limit		Total Lanes			
F	YES EASTBOUND				Mark		55			2	
UNIT					Special Function NO SPECIAL FUNCTION		-	Emergency Motor Vehicle Use NOT APPLICABLE			
		ic Way		Traffic Cont	ffic Control Traffic Control Inoperative/Missing				tive/Missing		
	тwo	D-WAY, NOT DIVIDED	NO CONT	NO CONTROL			NO				
	Surfa	асе Туре	Road Curva	Road Curvature			Road Grade				
	BLA	CKTOP (BITUMINOU	CURVE R	CURVE RIGHT			DOWNHILL				
		k Bus or HazMat									
	NO										
		Vehicle									
	License Plate Number			Plate Type	•		St	Country of Issuance			
	895RSV				AUT - AUTOMOBILE		WI	UNITED STATES			
2	5	Vehicle Identification Number			Make		Year				
	0				JEEP Body Style		2018	GRAND CHER Bus Use			
	Color RED - RED			, ,	UT - SPORT UTILITY VEHICLE		F	NOT A BUS			
					Vehicle Damage						
F	С										
UNIT	Ĭ	NON-COLLISION Extent Of Damage			1RIGHT FRONT CORNER, 5RIGHT REAR CORNER, 11LEFT FRONT CORNER, 12FRONT						
				CONNEN							
	Towed Due To Damage				Vehicle Removed By						
	TOWED DUE TO DISABLING DAMAGE				REEDSBURG SALVAGE						
	What Driver Was Doing V. NEGOTIATING CURVE				Vehicle Factors						
					NOT APPLICABLE						

19-13810

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Driver Actions										
	ш	NO CONTRIBUTING ACT										
нI	Ľ.											
UNIT	VEHICL											
5	표											
	2											
		Owner Name			Owner Address							
		KRISTI ANN SEIDL			1820 BADGER LN							
2	01	(608) 393-4937			REEDSBURG, WI 53959	, US						
- I	-											
		Sequence Of Events										
	_	Event										
	01	CROSS CENTERLINE										
		Event										
	02	EMBANKMENT										
	•											
	03	Event										
	0											
	+	Event										
	04											
LINU	1	Policy Holder										
Ξ		Insurance Company			Individual							
		WEST-BEND-MUTUAL-II	NS-CO		KRISTI SEIDL							
	i i	ndividual										
					Citations Issued	0						
		Driver KRISTI ANN SEIDL				Sex						
	1	(608) 393-4937			0	FEMALE						
	٩ſ	(008) 595-4957			Date of Birth	Race						
нI	D					WHITE						
	INDIVIDUAL	Address			Driver License Number							
2		1820 BADGER LN										
	Z	REEDSBURG, WI 53959	, US		STATE: WISCONSIN COUNTRY: UNITED STATES							
			y Crash		Osfatu Esuismont							
	Saf	ety Equipment	y Clash		Safety Equipment							
	Uu.											
		Seat Position			SHOULDER & LAP BELT							
		1FRONT SEAT-LEFT S	IDE (DRIVE	R/MOTORCY								
		Helmet Use			Helmet Compliance							
		Eye Protection			Tint Compliance							
		,										
	_ !	Injury S	Severity		Airbag							
2	001		PPARENT I		-							
-	0				NON DEPLOYED							
		Ejected	Ejection Pa			Trapped/Extricated						
		NOT EJECTED	NOT EJE	CTED/NOT APP	LICABLE	NOT TRAPPED						
		Medical Transport	-		EMS Agency Identifier	EMS Run #						
		NOT TRANSPORTED										
		Hospital			Date of Death	Time of Death						
	Distracted By Source											
	Distracted By Source NOT APPLICABLE (NOT DISTRACTED)											
	Distracted By Action											
		NOT DISTRACTED										
		Striking	g Unit #	Location								
		Non Motorist										
		Prior Action										

19-13810

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT	INDIVIDUAL	Action					
		Action Other Suspected Alcohol U NO	lse	Suspected Drug Use			To/From School
	[Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results		
2	001	Drug Type					
		Individual Condition APPEARED NORMAL					