

6TL09CGFCW
19-15907

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL09CGFCW

Document Number Override		Primary Crash Document #	Agency Crash Number 19-15907	Investigating Officer/Deputy DEPUTY K. MUELLER	
Crash Date 12/30/2019		Crash Time 05:23 PM	Date Arrived 12/30/2019	Time Arrived 05:32 PM	
Date Notified 12/30/2019		Time Notified 05:23 PM	Total Units 02	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input type="checkbox"/> Reportable	Crash Type DT4000 (STANDARD CRASH)			<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram	Reconstruction By
	Photos By
	Additional Information NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS BACKING OUT OF A PARKING STALL AND STRUCK UNIT 2 WHICH WAS LEGALLY PARKED. THE ACCIDENT WAS IN THE PARKING LOT OF KWIK TRIP, 617 W PINE ST BARABOO WI. THE DRIVER OF UNIT 1 WAS AT FAULT. THE DRIVER OF UNIT 1 HAD A INSTRUCTORS PERMIT ONLY AND WAS NOT WITHIN THE GUIDELINES OF THE PERMIT RESTRICTIONS.

Location

PARKING LOT CTHBD NB LOT 617 (HOUSE/BUILDING 617) IN THE VILLAGE OF WEST BARABOO IN SAUK COUNTY	Latitude 43.476049495	Longitude -89.769490218
	X Coordinate 276009.15625	Y Coordinate 4817407.5
	Structure Type HOUSE/BUILDING	

Crash Scene

First Harmful Event PARKED MOTOR VEHICLE	First Harmful Event Location IN PARKING LANE OR ZONE	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/LIGHTED	
Road Surface Condition(s) WET, SNOW	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway NON TRAFFICWAY - PARKING LOT	
Crash Classification - Location PRIVATE PROPERTY	Crash Classification - Jurisdiction PRIVATE PROPERTY	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type TRUCK	
	Vehicle Type UTILITY TRUCK/PICKUP TRUCK	Operating As Endorsements			
	Total Occs 2	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? NO	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit N/A	Total Lanes
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way PARKING LOT OR PRIVATE PROPERTY	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature		Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT	Vehicle				
	01	License Plate Number NK9790	Plate Type LTK - LIGHT TRUCK	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 1GCVKREC1FZ404761	Make CHEVROLET	Year 2015	Model SILVERADO
	VEHICLE	Color	Body Style PK - PICKUP		Bus Use
		Initial Contact Point 06 - REAR	Vehicle Damage		
		Extent Of Damage NO DAMAGE	00 - NO DAMAGE		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OWNER		
	What Driver Was Doing BACKING		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions UNSAFE BACKING				
01 01	Owner Name EVA L LITTLEGEORGE (608) 432-6850		Owner Address N7231 7TH AVE NEW LISBON, WI 53950 , US		
	Sequence Of Events				
01 01	01	Event PARKED MOTOR VEHICLE			
	02	Event			
	03	Event			
	04	Event			
UNIT INDIVIDUAL	Individual				
	01 001	Passenger EVA LYNN LITTLEGEORGE (608) 432-6850		Citations Issued 0	Sex FEMALE
		Date of Birth		Race INDIAN	
	Address N7231 7TH AVE NEW LISBON, WI 53950 , US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES		
Safety Equipment		On Duty Crash	Safety Equipment		
01 001	Row 01 - FRONT ROW	Seat Position 09 - RIGHT	RESTRAINT USE UNKNOWN		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
01 001	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
	Hospital		Date of Death	Time of Death	
	Distracted By		Distracted By Source		
Distracted By Action					
Non Motorist		Striking Unit #	Location		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Prior Action			
		Action			
		Action Other		To/From School	
01	001	Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO	
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
		Drug Type			
		Individual Condition APPEARED NORMAL			
		Individual			
		Driver MARLENE MORNINGSTAR DECORAH (608) 432-6850		Citations Issued 0	Sex FEMALE
		Address W1903 DOMBEK RD LYNDON STATION, WI 53944 , US		Date of Birth	Race INDIAN
		Driver License Number		STATE: WISCONSIN COUNTRY: UNITED STATES	
		01	002	Safety Equipment	On Duty Crash
Row 01 - FRONT ROW	Seat Position 07 - LEFT			RESTRAINT USE UNKNOWN	
Helmet Use				Helmet Compliance	
Eye Protection				Tint Compliance	
Injury	Injury Severity NO APPARENT INJURY			Airbag NON DEPLOYED	
Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE			Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED				EMS Agency Identifier	EMS Run #
Hospital				Date of Death	Time of Death
Distracted By	Distracted By Source UNKNOWN				
Distracted By Action UNKNOWN					
01	002	Non Motorist	Striking Unit #	Location	
		Prior Action			

UNIT	INDIVIDUAL	Action				
		Action Other		To/From School		
	01	002	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
			Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
			Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
			Drug Type			
			Individual Condition APPEARED NORMAL			

Unit Summary

UNIT	02	Unit Status LEGALLY PARKED		Vehicle Operating As Classification		Unit Type AUTOMOBILE		
		Vehicle Type PASSENGER CAR				Operating As Endorsements		
		Total Occs 0	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0		
		Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit N/A	Total Lanes		
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT			Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way PARKING LOT OR PRIVATE PROPERTY			Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature		Road Grade LEVEL	
		Truck Bus or HazMat NO						

UNIT	VEHICLE	Vehicle			
		License Plate Number 426XSU	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 3N1AB51A53L736204	Make NISSAN	Year 2003	Model SENTRA SE-
		Color BLK - BLACK	Body Style 4D - 4DR		Bus Use
		Initial Contact Point 01 - RIGHT FRONT CORNER	Vehicle Damage		
		Extent Of Damage MINOR DAMAGE	01 - RIGHT FRONT CORNER		
		Towed Due To Damage NOT TOWED	Vehicle Removed By OWNER		
		What Driver Was Doing LEGALLY PARKED			

6TL09CGFCW

19-15907

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	VEHICLE	Vehicle Factors	
		Driver Prior Action Other	NOT APPLICABLE
		Driver Actions NO CONTRIBUTING ACTION	
UNIT	02	Owner Name	Owner Address
		PRESTON S SCHROEDER (608) 477-9166	407 CHESTNUT ST BARABOO, WI 53913 , US
		Sequence Of Events	
		01	Event
02	Event		
03	Event		
04	Event		
UNIT	04	Policy Holder	
		Insurance Company	Individual
		PROGRESSIVE-CASUALTY-INS-CO	PRESTON SCHROEDER