## 6TL0B8M7WF

#### 20-00022

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



OPERATOR JERATOR WAS ED ON CEMETERY RD AT DECKER RD NEGOTIATING A CORVE, WHEN SHE FAILED TO GO AROUND THE CORVE TO THE RIGHT. OPERATOR DROVE UNIT ACROSS THE WB LANE INTO THE NORTH SIDE DITCH JUST EAST OF DECKER RD. UNIT CONTINUED NE DOWN AN EMBANKMENT ABOUT 30 FEET WHERE IT STUCK A BARB WIRE FENCE AND CAME TO REST ON TOP OF A ROCK FACING NE. OPERATOR LEFT THE SCENE AND DID NOT REPORT IT TO LAW ENFORCEMENT. OPERATOR LATER ADVISED WHEN CONTACTED THAT SHE HAD A BUMP ON HER HEAD. UNIT HAD MINOR DAMAGE AND WAS TOWED BY STEVES TOWING. OPERATOR WAS CITED FOR FAILURE TO NOTFY POLICE, NO INSURANCE AND TOO FAST FOR CONDITIONS. 20-00022

## WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

l	<u>_0c</u>	ation		<u> </u>	_	_	_		_		
ſ	ON	CEMETERY RD		Latitude Longitude				le			
	58 FT E					43.547035374			-90.093	752775	
	-		X Coordinate Y Coordin			inate					
		HE TOWN OF IRONT	UN			250075.546875			482621	6	
			Structure Type								
(	Cra	sh Scene 📃									
Ī	First	Harmful Event				First Harm	nful Event Lo	ocation			
	DIT	СН				SHOULD	DER LEFT				
ľ	Man	ner of Collision				Light Cond	dition				
	00 -	00 - NO COLLISION W/VEHICLE IN TRANSPORT					NLIT				
Ī	Road	Surface Condition(s)				Roadway Factor(s)					
	SNC	W, SLUSH, ICE									
F	Envi	ronment Factor(s)									
	NOM	IE				ROAD S ETC)	URFACE	CONDITION	(WET, IC	CY, SNOW, SLUSH,	
ŀ	Wea	ther Condition(s)									
	CLE	AR									
ŀ	Animal Type					Relation T	o Trafficway	1			
						TRAFFICWAY - ON ROAD					
		Crash Classification - Location					ssification -				
		PUBLIC PROPERTY       Fribal Land       Within Interchange Area     Junction Location       NO     NON-JUNCTION				NO SPECIAL JURISDICTION           Access Control         Special Study					
	THE					NO CONTROL				Special Study	
	Withi					ion Type N INTERSECTION					
Ļ	-		Non vono non		NOT AN		onen				
_		t Summary		Vehicle Op	orating As C	lassification		Linit Turno			
		RANSIT		D CLASS	•	Classification Unit Type AUTOMOBILE					
-		cle Type		DCLASS		Operating As Endorsements					
;	PASSENGER CAR							oporating		nonto	
ŀ	-	Occs	Total # Cita	tions Issued	Total Traile		ers	Total Haz	Mat Types		
	01			03		0		0			
F	Insu	ance?	Direction Of Travel	Pre CrashTire		e Speed Lin		nit	Total Lan	es	
	NO EASTBOUND				Mark	45		02			
ŀ	Most				Special Function			Emergency Motor Vehicle Use			
		FENCE NO SPECIAL FU									
ſ		ic Way		raffic Control			Traffic Control Inoperative/Missing				
		D-WAY, NOT DIVIDED		WARNING SIGN			NO Decid Canda				
	Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat				Road Curvature CURVE RIGHT			Road Grade DOWNHILL			
╞											
	NO	The sub of Flazivial									
1	ľ	Vehicle									
	License Plate Number 275ZHW				Plate Type AUT - AUTOMOBILE		St		Country of Issuance		
							WI				
5	01	Vehicle Identification Nur	Make BUICK			Year 1000	Model PARK AVENU				
	0	1G4CW52K4X46495									
		Color		Body Style Bus Use							
		RED - RED		4D - 4DR							
	ш	RED - RED Initial Contact Point		4D - 4DR Vehicle Da							
	/EHICLE	Initial Contact Point		Vehicle Da		NDERCAI	RRIAGE				

20-00022

## WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG			Vehicle Removed By STEVES AUTO SERVICE					
		What Driver Was Doing			Vehicle Factors					
		NEGOTIATING CURVE			NOT APPLICABLE					
		Driver Prior Action Other								
		Driver Actions								
	щ	SPEED TOO FAST/CONE	D, FAILURE TO CONTRO	DL, R	AN OFF ROADWAY, FAILED TO KE	EP IN DESIGNATED LANE				
F	VEHICL									
UNIT	Ξ									
_	2									
	-									
		Owner Name SHEILA LOUISE KERKMAN (608) 475-9156			Owner Address					
-	~				E4991 COUNTY ROAD K REEDSBURG, WI 53959 ,US					
5	6									
	ę	Sequence Of Events								
	5	Event								
	0	CROSS CENTERLINE								
	02	Event RUN OFF ROADWAY LE	FT							
		Event								
	03	DITCH								
	04	Event								
	0	FENCE								
	l l	Individual								
		Driver			Citations Issued	Sex				
		SHEILA LOUISE KERKM	AN		03	FEMALE				
	<b>NDIVIDUAL</b>	(608) 475-9156			Date of Birth	Race				
F	ē					WHITE				
UNIT	$\geq$	Address			Driver License Number					
-	Z	E4991 COUNTY ROAD K REEDSBURG, WI 53959, US On Duty Crash			STATE: WISCONSIN COUNTRY: UNITED STATES					
	_									
					Safety Equipment					
	Sat									
		Row Seat Position			SHOULDER & LAP BELT					
		01 - FRONT ROW	07 - LEFT							
		Helmet Use	I		Helmet Compliance					
		Eye Protection			Tint Compliance Airbag					
	_									
9	00	1 ·	ECTED MINOR INJURY		NON DEPLOYED					
		Ejected Ejection Path		Trapped/Extricated						
	NOT EJECTED NOT EJECTED/NOT APPL			PPLI	CABLE	NOT TRAPPED				
		Medical Transport			EMS Agency Identifier	EMS Run #				
		NOT TRANSPORTED								
	Hospital				Date of Death	Time of Death				
			ted By Source							
		Distracted By NOT APPLICABLE (NOT DISTRACTED)								
		NOT DISTRACTED								
		Non Motorist	Unit # Location							
	NON MOTORIST									

#### 6TL0B8M7WF

20-00022

# WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action								
		Action								
	Ļ									
╘	INDIVIDUAL									
UNIT	N									
	Z									
		Action Other		To/From School						
		Suspected Alcohol Use			Suspected Drug Use					
	1	Drug & Alcohol YES NO								
		Alcohol Test Given		Alcohol Test Type	Alcohol Test Type			Alcohol Test Results		
		TEST NOT GIVEN								
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results				
2	001	Drug Type				ł				
0	0									
	Individual Condition									
	NOT OBSERVED									
Violations										
	UTC Number AD981003         Issue To?         Statute Number 346.70(1)         Description FAILURE OF OCCUPANT TO NOTIFY POLICE OF ACCIDENT									
	02	UTC Number AD981004	Issue To? 001	Statute Number 344.62(1)	Description OPERATE MOTOR VEHICLE W/O INSURANCE					
	03	UTC Number AD981005	Issue To? 001	Statute Number 346.57(3)	Description DRIVING TOO FAST	FOR CONDITIC	INS			