6TL0B3P3FS 19-15890

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	Primary Crash Document # Crash Time 01:00 AM		Agency Crash Number 19-15890 Date Arrived 12/30/2019		Investigating Officer/Deputy DEPUTY S. PARKHURST Time Arrived 01:09 AM		
Crash Date 12/30/2019							
12/30/2019 Date Notified 12/30/2019 On Emergency Hit Government Property	Time Notified 01:09 AM		Total U	nits	Total Injured 00	Total Kille	ed
On Emergency Hit	and Run	Lane Closu		☐ Work Zone	Trailer	or Towed	Reporting Threshold
Government Property	Active Scl	hool Zone	School NO	Bus Related	Tags		
✓ Reportable	Crash Type DT4000 (STAI	NDARD CRASH	l)		Amend	ed	Secondary Crash
Description Diagram							
\$				#1		Photos By 40	
		#1) 			Additional Info	ormation NTOS
#1			STI	160			
				Not to Scale			
J, a sworn law enforcemen							
UNIT 1 WAS EASTBOUND ON STH PASSENGER SIDE.	60. THE OPERATO	OR LOST CONTRO	L OF TH	E VEH AND ENTERED TH	E NORTHERN DI	TCH. THE VEH	CAME TO REST ON THE

6TL0B3P3FS 19-15890

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/30/2019

Crash Time 01:00 AM

	422	STH60 EB FT S			Latitude 43.254131707			Longitude -89.814844226		
	IN T	SKUNK VALLEY RD THE TOWN OF PRAIRIE SAUK COUNTY	DU SAC			X Coordinate Y Coo 271508.78125 4792				
		SAUR GOORT I			Structure	Туре		•		
(Cra	sh Scene			'					
	First	: Harmful Event			First Harr	mful Event	Location			
	DIT	СН			ROADS	IDE				
	Man	ner of Collision			Light Cor	ndition				
	00 -	NO COLLISION W/VEH	IICLE IN TRANSPORT		DARK/UNLIT					
	Roa	d Surface Condition(s)			Roadway	Roadway Factor(s)				
	WE.	т								
	Envi	ronment Factor(s)								
	NOI	NE			NONE					
	Wea	ather Condition(s)								
	RAI	* *								
	Anin	nal Type			Relation :	To Trafficw	av.			
						TRAFFICWAY - NOT ON ROAD				
	Cras	sh Classification - Location			Crash Cla	Crash Classification - Jurisdiction				
	PUE	BLIC PROPERTY			NO SPE	NO SPECIAL JURISDICTION				
	Triba	al Land				Access Control		Special Study		
	\A/:4b	in Interchange Area	lunction Location	Intersection Type		NIKUL				
	NO	· ·	Junction Location NON-JUNCTION		ot an intersi	ECTION				
		t Summary								
,							11.27			
	Unit	Status		I Vehicle Operati	ng As Classification	n	I Unit I vne			
		Status FRANSIT		Vehicle Operati	ng As Classification	n	Unit Type AUTOMO	BILE		
	IN T			·	ng As Classification	n			ments	
01	Vehi	TRANSIT icle Type SSENGER CAR		·	ng As Classification		AUTOMO Operating A	As Endorser		
	Vehi PAS	TRANSIT icle Type	Train/Bus # Recorded	D CLASS Total # Citations		Total Tra	AUTOMO Operating A	As Endorser	ments Mat Types	
	Vehi PAS Tota 1	TRANSIT icle Type SSENGER CAR		D CLASS Total # Citations 2	s Issued	Total Tra	AUTOMO Operating A	As Endorser Total Haz 0	Mat Types	
01	Vehi PAS Tota 1	TRANSIT icle Type SSENGER CAR Il Occs	Direction Of Travel	Total # Citations 2 Pre Cra	s Issued	Total Tra 0 Speed L	AUTOMO Operating A	Total Haz Total Lane	Mat Types	
01	Vehi PAS Tota 1 Insur	TRANSIT icle Type SSENGER CAR Il Occs	Direction Of Travel EASTBOUND	D CLASS Total # Citations 2	s Issued	Total Tra	AUTOMO Operating A	Total Haz Total Land	Mat Types es	
	Vehi PAS Tota 1 Insur	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision W	Direction Of Travel EASTBOUND	Total # Citations 2 Pre Cra Ma	s Issued ashTire urk	Total Tra 0 Speed L	AUTOMO Operating A ailers	Total Haz 0 Total Land 2 Motor Vehi	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insu YES Mos: DIT	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision W CH fic Way	Direction Of Travel EASTBOUND	Total # Citations 2 Pre Cra Ma Special Functio	s Issued ashTire urk	Total Tra 0 Speed L	AUTOMO Operating A ailers .imit	Total Haz 0 Total Lan 2 Motor Vehi	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insu YES Mos: DIT Traff	TRANSIT icle Type SSENGER CAR Il Occs rance? S It Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED	Direction Of Travel EASTBOUND	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO	s Issued ashTire irk n FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz 0 Total Land 2 Motor VehicliCABLE	Mat Types es icle Use	
01	Vehi PAS Tota 1 Insu YES Moss DITC Traff TWC	TRANSIT icle Type SSENGER CAR Il Occs rance? S It Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type	Direction Of Travel EASTBOUND Tith	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature	s Issued ashTire ashTire ashTire bruk n FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor VehicliCABLE	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insur YES Mos DIT Traff TWO Surfa BLA	TRANSIT icle Type SSENGER CAR Il Occs rance? S It Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Direction Of Travel EASTBOUND Tith	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO	s Issued ashTire ashTire ashTire bruk n FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz 0 Total Land 2 Motor VehicliCABLE	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insur YES Mos DIT Traff TWO Surfa BLA	TRANSIT icle Type SSENGER CAR II Occs rance? It Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Direction Of Travel EASTBOUND Tith	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature	s Issued ashTire ashTire ashTire bruk n FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor VehicliCABLE	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insu YES Moss DIT Traff TWO Surfa BLA Truc NO	TRANSIT icle Type SSENGER CAR II Occs rance? It Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Direction Of Travel EASTBOUND Tith	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature	s Issued ashTire ashTire ashTire bruk n FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor VehicliCABLE	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insu YES Moss DIT Traff TWO Surfa BLA Truc NO	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ek Bus or HazMat	Direction Of Travel EASTBOUND Tith	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature	s Issued ashTire ashTire ashTire bruk n FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insu YES Moss DIT Traff TWO Surfa BLA Truc NO	TRANSIT icle Type SSENGER CAR II Occs rance? S It Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ek Bus or HazMat	Direction Of Travel EASTBOUND Tith	Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT	s Issued ashTire ark n FUNCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz 0 Total Lan 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
UNIT 01	IN T Vehi PAS Tota 1 Insury YES DITO Traff TWO Surfa BLA Truc NO	TRANSIT icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number 308JPV Vehicle Identification Number	Direction Of Travel EASTBOUND ith	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make	s Issued ashTire ark n FUNCTION DL	Total Tra 0 Speed L 55 St WI Year	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model	Total Haz O Total Lan 2 Motor Vehi CLICABLE trol Inoperat e ssuance TATES	Mat Types es icle Use	
01	IN T Vehi PAS Tota 1 Insu YES Moss DIT Traff TWO Surfa BLA Truc NO	TRANSIT Icle Type SSENGER CAR ICOCCS Trance? St Harmful Event: Collision W CH Icc Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 308JPV Vehicle Identification Numl 1G1ZH57B194227183	Direction Of Travel EASTBOUND ith	Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make CHEVROLE	s Issued ashTire ark n FUNCTION DL	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MALIBU 11	Total Haz O Total Lan 2 Motor Vehi CLICABLE trol Inoperat e ssuance TATES	Mat Types es icle Use	
UNIT 01	IN T Vehi PAS Tota 1 Insury YES DITO Traff TWO Surfa BLA Truc NO	TRANSIT icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number 308JPV Vehicle Identification Number	Direction Of Travel EASTBOUND ith	D CLASS Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make	s Issued ashTire ark n FUNCTION DL	Total Tra 0 Speed L 55 St WI Year	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model	Total Haz O Total Lan 2 Motor Vehi CLICABLE trol Inoperat e ssuance TATES	Mat Types es icle Use	
01 UNIT 01	IN T Vehi PAS Tota 1 Insury YES DITO Traff TWO Surfa BLA Truc NO	TRANSIT Icle Type SSENGER CAR ICOCCS Trance? St Harmful Event: Collision W CH Icc Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 308JPV Vehicle Identification Numl 1G1ZH57B194227183 Color	Direction Of Travel EASTBOUND ith	Total # Citations 2 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make CHEVROLE Body Style	s Issued ashTire ark FUNCTION DL Gr DMOBILE	Total Tra 0 Speed L 55 St WI Year	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MALIBU 11	Total Haz O Total Lan 2 Motor Vehi CLICABLE trol Inoperat e ssuance TATES	Mat Types es icle Use	
01 UNIT 01	IN T Vehi PAS Tota 1 Insur YES DITC Traff TWO Surfa BLA Truc NO	TRANSIT Icle Type SSENGER CAR ICOCCS Trance? St Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 308JPV Vehicle Identification Numl 1G1ZH57B194227183 Color WHI - WHITE	Direction Of Travel EASTBOUND ith	Total # Citations 2 Pre Cra Ma Special Functio NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make CHEVROLE Body Style 4D - 4DR Vehicle Damage	s Issued ashTire ark n FUNCTION DL G OMOBILE T	Total Tra 0 Speed L 55 St WI Year 2009	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MALIBU 1 Bus Use	Total Haz 0 Total Land 2 Motor Vehi LICABLE trol Inoperate	es icle Use tive/Missing	
UNIT 01	IN T Vehi PAS Tota 1 Insur YES DITC Traff TWO Surfa BLA Truc NO	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number 308JPV Vehicle Identification Numl 1G1ZH57B194227183 Color WHI - WHITE Initial Contact Point 00 - NON-COLLISION Extent Of Damage	Direction Of Travel EASTBOUND Ith	Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make CHEVROLE Body Style 4D - 4DR Vehicle Damag 01 - RIGHT F	s Issued ashTire ark n FUNCTION L T MOBILE T	St WI Year 2009	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MALIBU 11 Bus Use	Total Haz O Total Lan- 2 Motor Vehi LICABLE trol Inoperate E SSUANCE TATES LT	es icle Use tive/Missing - RIGHT SIDE	
01 UNIT 01	IN T Vehi PAS Tota 1 Insur YES Moss DITO Traff TWO Surfa BLA Truc	TRANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision W CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number 308JPV Vehicle Identification Numl 1G1ZH57B194227183 Color WHI - WHITE Initial Contact Point 00 - NON-COLLISION	Direction Of Travel EASTBOUND Ith	Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make CHEVROLE Body Style 4D - 4DR Vehicle Damag 01 - RIGHT F	s Issued ashTire ark n FUNCTION DL G OMOBILE T	St WI Year 2009	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MALIBU 11 Bus Use	Total Haz O Total Lan- 2 Motor Vehi LICABLE trol Inoperate E SSUANCE TATES LT	es icle Use tive/Missing - RIGHT SIDE	

6TL0B3P3FS 19-15890

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage		Vehicle Removed By						
TOWED BUT NOT DUE TO DISABLING DAMAG			DISABLING DAMAG	EVERETTS TOWING						
		What Driver Was Doing		Vehicle Factors						
		NEGOTIATING CURVE								
		Driver Prior Action Other		NOT APPLICABLE						
		Driver Actions								
	ш	FAILURE TO CONTROL, OTHER CONTRIBUTING ACTION								
⊢	VEHICLE									
LNO	¥									
–	Ē									
	>									
		Owner Name		Owner Address						
		PENNY S BRUMMEL		2109 HANKSFIELD PL						
2	01			PRAIRIE DU SAC, WI	53578 , US					
		Saguenes Of Events								
		Sequence Of Events Event								
	01	DITCH								
		Event								
	02	OVERTURN/ROLLOVER								
		Event								
	03	270								
		Event								
	04									
		Policy Holder								
		Insurance Company								
5		AMERICAN-FAMILY-INS-0	20	Individual PENNY BRUMMEL						
	ı	Individual		10%						
		Driver		Citations Issued	Sex					
		_			======					
	۱L	ALEXI JANE BRUMMEL		2	FEMALE					
	UAL	_			Race					
=	/IDUAL	ALEXI JANE BRUMMEL (608) 214-9818		2 Date of Birth						
LINO	DIVIDUAL	ALEXI JANE BRUMMEL (608) 214-9818		2	Race					
LIND	INDIVIDUAL	Address N3247 CTH U	s	Date of Birth Driver License Number	Race					
LINO	INDIVIDUAL	ALEXI JANE BRUMMEL (608) 214-9818	s	Date of Birth Driver License Number	Race WHITE					
LINO	INDIVIDUAL	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561, U		Date of Birth Driver License Number STATE: WISCONSIN CO	Race WHITE					
NIII		Address N3247 CTH U		Date of Birth Driver License Number	Race WHITE					
TINO		Address N3247 CTH U MERRIMAC, WI 53561 , U fety Equipment	Crash	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment	Race WHITE DUNTRY: UNITED STATES					
LIND		Address N3247 CTH U MERRIMAC, WI 53561 , U fety Equipment Row	Crash Seat Position	Date of Birth Driver License Number STATE: WISCONSIN CO	Race WHITE DUNTRY: UNITED STATES					
LIND		ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW	Crash	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL	Race WHITE DUNTRY: UNITED STATES					
TINO		Address N3247 CTH U MERRIMAC, WI 53561 , U fety Equipment Row	Crash Seat Position	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment	Race WHITE DUNTRY: UNITED STATES					
TINO		ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U fety Equipment Row 01 - FRONT ROW Helmet Use	Crash Seat Position	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance	Race WHITE DUNTRY: UNITED STATES					
TINO		ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW	Crash Seat Position	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL	Race WHITE DUNTRY: UNITED STATES					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection	Crash Seat Position 07 - LEFT	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance	Race WHITE DUNTRY: UNITED STATES					
UNIT UNIT		ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Se	Crash Seat Position 07 - LEFT	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance	Race WHITE DUNTRY: UNITED STATES					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Injury Injury Se	Seat Position 07 - LEFT	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance	Race WHITE DUNTRY: UNITED STATES					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Se NO AP	Seat Position 07 - LEFT everity PARENT INJURY	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED	Race WHITE DUNTRY: UNITED STATES					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Se NO AP	Seat Position 07 - LEFT Everity PARENT INJURY Ejection Path	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED	Race WHITE DUNTRY: UNITED STATES T					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Figure 1 Injury Service 1 NO API	Seat Position 07 - LEFT Everity PARENT INJURY Ejection Path	2 Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED	Race WHITE DUNTRY: UNITED STATES T Trapped/Extricated TRAPPED/EXTRICATED					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport	Seat Position 07 - LEFT Everity PARENT INJURY Ejection Path	2 Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED	Race WHITE DUNTRY: UNITED STATES T Trapped/Extricated TRAPPED/EXTRICATED					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Se NO API Ejected NOT EJECTED Medical Transport NOT TRANSPORTED	Seat Position 07 - LEFT Everity PARENT INJURY Ejection Path	2 Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identifier	Race WHITE DUNTRY: UNITED STATES T Trapped/Extricated TRAPPED/EXTRICATED EMS Run #					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT Everity PARENT INJURY Ejection Path NOT EJECTED/NOT AP	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identifier Date of Death	Race WHITE DUNTRY: UNITED STATES T Trapped/Extricated TRAPPED/EXTRICATED EMS Run #					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Injury NO API Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital Distracted By Distracte NOT AI	Seat Position 07 - LEFT Everity PARENT INJURY Ejection Path NOT EJECTED/NOT AP	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identifier Date of Death	Race WHITE DUNTRY: UNITED STATES T Trapped/Extricated TRAPPED/EXTRICATED EMS Run #					
	Sat	ALEXI JANE BRUMMEL (608) 214-9818 Address N3247 CTH U MERRIMAC, WI 53561 , U Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT Everity PARENT INJURY Ejection Path NOT EJECTED/NOT AP	Date of Birth Driver License Number STATE: WISCONSIN CO Safety Equipment SHOULDER & LAP BEL Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identifier Date of Death	Race WHITE DUNTRY: UNITED STATES T Trapped/Extricated TRAPPED/EXTRICATED EMS Run #					

6TL0B3P3FS 19-15890

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motorist	Striking Unit #	Location				
		Prior Action						
LINO	INDIVIDUAL	Action						
		Action Other Drug & Alcohol	Suspected Alco YES	hol Use	Suspected Drug Use			To/From School
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results	
		TEST GIVEN		BLOOD			PENDING	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
2	001	Drug Type						
		Individual Condition						
		PHYSICALLY IMP	AIRED					
	,	Violations						
	5	UTC Number BB338311	Issue To? 001	Statute Number 346.63(1)(a)	Description OPERATING WHILE	UNDER THE IN	FLUENCE	
	07	UTC Number BB338312	Issue To? 001	Statute Number 346.05(1)	Description OPERATING LEFT C	OF CENTER		