6TL09XQZ15

19-15956

WISCONSIN MOTOR VEHICLE CRASH REPORT

ſ	Document Number Override	Primary Crash Document #		Agency Crash Number 19-15956		Investigating Officer/Deputy DEPUTY I. GALVAN			
47	Crash Date 12/31/2019	Crash Time 07:11 PM		Date Arrived 12/31/2019		Time Arrived 07:29 PM			
2	Date Notified 12/31/2019	Time Notified 07:13 PM		Total Units 01		Total Injured	Total Kil	tal Killed	
(60-	On Emergency	t and Run				Trailer or Towe		red Reporting Threshold	
<u>6</u>	Government Property	Active Sch	ool Zone	School Bus Related NO		Tags			
	Reportable	Crash Type DT4000 (STAN	IDARD CRASH)		Ameno	ded	Secondary Crash	
-	escription								
	Diagram						Reconstruction	л <i>Бу</i>	
				F	RANK ROAD		Additional Inf NONE	ormation	
						1			
]			
					NOT TO SC	CALE			
	I, a sworn law enforceme	nt officer, agree	e that I have no	ot addec	l any CJIS data in thi	s report.			
	UNIT 1 WAS TRAVELING EASTBOL AND ROLLED HIS VEHICLE ONCE WITH THE REGISTERED OWNER/C THE VEHICLE THE NEXT DAY. A C	ONTO THE THE RI	GHT SHOULDER / T 1. OPERATOR S	AND DOV STATED H	IN A EMBANKMENT. UNI E DID NOT NOTIFY LAW	T 1 WAS UNOCO ENFORCEMENT	CUPIED AT MY	ARRIVAL. I MADE CONTACT NG A PLAN TO REMOVE	

19-15956

2

UNIT

5

UNIT

WISCONSIN MOTOR VEHICLE CRASH REPORT

Loc	ation								
-	FRANK RD			Latitude		Longitud			
-	FT W LA RUE RD		43.502398566			0926425			
-	HE TOWN OF IRONT	ON		X Coordinate			dinate		
IN S	AUK COUNTY			246885.609375 4821371					
			Structure Type NO STRUCTURE						
Cra	sh Scene 📃								
_	Harmful Event			First H	armful Event	Location			
	ERTURN/ROLLOVER				JLDER RIG				
	ner of Collision			Light C	ondition				
00 -	NO COLLISION W/VE	EHICLE IN TRANSPORT		DARK	/UNLIT				
Road	d Surface Condition(s)			Roadw	ay Factor(s)				
SNC	w								
Envi	ronment Factor(s)								
NO	NE			ROAD ETC)	SURFACE		I (WET, IC	CY, SNOW, SLUSH,	
Wea	ther Condition(s)								
CLC	DUDY								
Anim	nal Type			Relatio	Relation To Trafficway				
				TRAF	FICWAY - C	ON ROAD			
	h Classification - Location	1		Crash (Classification	- Jurisdiction			
-	BLIC PROPERTY					RISDICTION			
Triba	al Land				Access Control Special Study NO CONTROL			Special Study	
With	in Interchange Area	Junction Location		Intersection Type					
NO		NON-JUNCTION		NOT AN INTER	SECTION				
_	t Summary	NON-JUNCTION		NOT AN INTER	SECTION				
Uni	t Summary	NON-JUNCTION	Vehicle Ope	NOT AN INTER		Unit Type			
Unit Unit	Status RANSIT	NON-JUNCTION	Vehicle Ope D CLASS			TRUCK			
Unit Unit IN T Vehi	Status RANSIT cle Type						s Endorse	ments	
Unit Unit IN T Vehi UTI	Status RANSIT cle Type LITY TRUCK/PICKUP	TRUCK	D CLASS	I erating As Classificat	tion	TRUCK Operating A			
Unit Unit IN T Vehi UTI	Status RANSIT cle Type		D CLASS			TRUCK Operating A		ments zMat Types	
Unit Unit IN T Vehi UTII Tota 1	Status RANSIT cle Type LITY TRUCK/PICKUP	TRUCK	D CLASS	I erating As Classificat	tion Total Tra	TRUCK Operating A ailers	Total Haz	zMat Types	
Unit Unit IN T Vehi UTII Tota 1	Status RANSIT Cle Type LITY TRUCK/PICKUP Occs rance?	TRUCK	D CLASS	arating As Classificat	tion Total Tra 0	TRUCK Operating A ailers	Total Haz 0	zMat Types	
Unit Unit IN T Vehi UTII Tota 1 Insu YES	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Harmful Event: Collision	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	erating As Classificat tions Issued CrashTire Mark	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency	Total Haz 0 Total Lan 2 Motor Veh	zMat Types les icle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Harmful Event: Collision ERTURN/ROLLOVER	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	erating As Classificat tions Issued CrashTire Mark ICTION IAL FUNCTION	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes iicle Use	
Unit IN T Vehi UTII Tota 1 Insu YES Most OVE Traff	Status RANSIT Cle Type LITY TRUCK/PICKUP OCCS rance? Harmful Event: Collision ERTURN/ROLLOVER ic Way	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	erating As Classificat tions Issued CrashTire Mark iction IAL FUNCTION rol	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types les icle Use	
Unit Unit IN T Vehi UTII Tota 1 Insuu YES Most OVE Traff	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Harmful Event: Collision ERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IIAL FUNCTION rol ROL	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit IN T Vehi UTII Tota 1 Insu YES OVE Traff TWC Surfa	Status RANSIT Cle Type LITY TRUCK/PICKUP Occs rance? Harmful Event: Collision ERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNCTION Tol IROL	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insu YES OVE Traff TWC Surfa BLA	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Harmful Event: Collision ERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNCTION Tol IROL	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insu YES OVE Traff TWC Surfa BLA	Status RANSIT Cle Type LITY TRUCK/PICKUP Occs rance? Rance? Rance? RTURN/ROLLOVER CRURN/ROLLOVER COMPAY, NOT DIVIDED ace Type CKTOP (BITUMINOU	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNCTION Tol IROL	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most OVE Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP Occs rance? Rance? Rance? RTURN/ROLLOVER CRURN/ROLLOVER COMPAY, NOT DIVIDED ace Type CKTOP (BITUMINOU	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNCTION Tol IROL	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most OVE Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP OCCS Tance? Harmful Event: Collision ERTURN/ROLLOVER To Way C-WAY, NOT DIVIDED Tace Type CKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Itions IAL FUNCTION rol ROL ture T	tion Total Tra 0 Speed L 45	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most OVE Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP OCCS Tance? Harmful Event: Collision ERTURN/ROLLOVER To Way D-WAY, NOT DIVIDED Tace Type CKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number MN1907	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S (S)	D CLASS	tions Issued CrashTire Mark Iction IIAL FUNCTION rol ROL ture T	tion Total Tra 0 Speed L 45	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most OVE Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP OCCS rance? Harmful Event: Collision ERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type CKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number MN1907 Vehicle Identification Num	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S IS	D CLASS	tions Issued CrashTire Mark IAL FUNCTION Tol ROL Iture T	tion Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S Model	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most OVE Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP OCcs Tance? Tance? Tance? THARMful Event: Collision ERTURN/ROLLOVER To Way D-WAY, NOT DIVIDED Tace Type CKTOP (BITUMINOU K Bus or HazMat Vehicle License Plate Number MN1907 Vehicle Identification Nuu 1GTHK24184E21230	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S IS	D CLASS	tions Issued CrashTire Mark ction IAL FUNCTION rol ROL ature T GHT TRUCK	tion Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S [*] Model SIERRA K	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most OVE Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP OCCS rance? Harmful Event: Collision ERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type CKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number MN1907 Vehicle Identification Num	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S IS	D CLASS	tions Issued CrashTire Mark cction IAL FUNCTION rol ROL ature T SHT TRUCK L MOTORS COR	tion Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S Model	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insuu YES Most OVE Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP COCcs Tance? Tance? Tharmful Event: Collision ERTURN/ROLLOVER To Way D-WAY, NOT DIVIDED Tace Type CCKTOP (BITUMINOU K Bus or HazMat Vehicle License Plate Number MN1907 Vehicle Identification Nut 1GTHK24184E21230 Color	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S IS	D CLASS	tions Issued CrashTire Mark IAL FUNCTION rol ROL Ature T GHT TRUCK L MOTORS COR	tion Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S [*] Model SIERRA K	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	
Unit Unit IN T Vehi UTII Tota 1 Insur YES Most OVE Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP Cocs Tance? Harmful Event: Collision ETURN/ROLLOVER CWay CWAY, NOT DIVIDED CCKTOP (BITUMINOU K Bus or HazMat Vehicle License Plate Number MN1907 Vehicle Identification Num 1GTHK24184E21230 Color WHI - WHITE	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With INITIAL INPORTMENTION INITIAL INPORTMENTION INITIAL INPORTMENTION INITIAL INFORMATION INITIAL INITIAL INFORMATION INITIAL INITIALISIA INITIALISI	D CLASS	arating As Classificat tions Issued CrashTire Mark IAL FUNCTION rol ROL ture T GHT TRUCK L MOTORS COR KUP mage	tion Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S [*] Model SIERRA K	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes iicle Use	

19-15956

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage			icle Removed By				
		TOWED DUE TO DISABLING	G DAMAGE		SHIELDS TOWING				
		What Driver Was Doing		Veh	icle Factors				
		GOING STRAIGHT							
		Driver Prior Action Other		NOT APPLICABLE					
		Driver Actions							
	ш	NO CONTRIBUTING ACTIO	N						
F	2								
UNIT	Ξ								
	VEHICLE								
	-								
		Owner Name			Owner Address				
2	2	JOSEPH PETER VOSEN (608) 963-2843			E3485A FRANK RD LA VALLE, WI 53941 , US				
0	0				,,,,,,				
		Sequence Of Events Event							
	0	OVERTURN/ROLLOVER							
	~	Event							
	02								
	03	Event							
	0								
	04	Event							
Ē		Policy Holder							
UNIT		Insurance Company ALLSTATE-INS-CO			Individual JOSEPH VOSEN				
	l	Individual Citations Issued Sex							
		JOSEPH PETER VOSEN (608) 963-2843		1		MALE			
	AL				Date of Birth	Race			
⊢	INDIVIDUAL					WHITE			
UNIT	Σ	Address		C	Priver License Number				
	Z	E3485A FRANK RD LA VALLE, WI 53941 , US		STATE: WISCONSIN COUNTRY: UNITED STATES					
		,, ,							
		On Duty Cr	ash	S	afety Equipment				
	Sat	fety Equipment							
		Row	Seat Position	s	HOULDER & LAP BELT				
		01 - FRONT ROW	07 - LEFT						
		Helmet Use		Helmet Compliance					
		Eve Protostion		Tint Compliance					
		Eye Protection			Tint Compliance				
_	~	Injury Seve	rity	A	irbag				
2	001	Injury NO APPA	RENT INJURY	N	ION DEPLOYED				
		Ejected Ejection Path				Trapped/Extricated			
						NOT TRAPPED			
	Medical Transport NOT TRANSPORTED Hospital		E	MS Agency Identifier	EMS Run #				
				Date of Death	Time of Death				
	Hospital								
		Distracted	By Source						
		Distracted By NOT APP	LICABLE (NOT DISTR	RACT	ED)				
		Distracted By Action							
		NOT DISTRACTED							

6TL09XQZ15

19-15956

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Non Motorist	Striking Unit #	Location				
		Prior Action						
		Action						
	AL							
UNIT	IDU							
Б	INDIVIDUAL							
	Z							
		Action Other						To/From School
	L	Drug & Alcohol	Suspected Alcol	nol Use	Suspected Drug Use			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given		Drug Test Type		Drug Test Results		
	7	Drug Type						
0	001	2.09.70						
		Individual Condition						
		NOT OBSERVED						
		Violations						
		UTC Number	Issue To?	Statute Number	Description			
	6	AE757647	001	346.70(1)	FAILURE OF OPERA	ATOR TO NOTIF		VEN I