

6TL0B4X4MQ
20-00015

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0B4X4MQ

Document Number Override		Primary Crash Document #		Agency Crash Number 20-00015		Investigating Officer/Deputy DEPUTY E. KNULL	
Crash Date 01/01/2020		Crash Time 99:99		Date Arrived 01/01/2020		Time Arrived 09:12 AM	
Date Notified 01/01/2020		Time Notified 08:53 AM		Total Units 01		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input checked="" type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed		<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

Diagram		Reconstruction By	
		Photos By	
		Additional Information NONE	
		<input checked="" type="checkbox"/> I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.	
<p>VEHICLE NB ON LYNDON RD JUST SOUTH OF OAK HILL RD LEFT THE SNOW COVERED ROAD ON THE WEST SIDE AND WENT THROUGH THE DITCH AND STRUCK SMALL TREES. VEHICLE SUSTAINED DISABLING DAMAGE AND WAS REMOVED BY INTERSTATE BP. UNKNOWN WHO THE DRIVER WAS AS NO ONE WAS AROUND. CONTACT WAS MADE WITH REGISTERED OWNER AND THEY ADVISED THEY SOLD THE CAR TO SOMEONE ELSE. THAT SUBJECT DID NOT RETURN CALLS. UNKNOWN IF ANYONE WAS INJURED BUT NO OBVIOUS SIGNS OF INJURIES WERE OBSERVED.</p>			

6TL0B4X4MQ

20-00015

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

Table with location details: ON LYNDON RD 196 FT S OF OAK HILL RD IN THE TOWN OF DELLONA IN SAUK COUNTY. Includes Latitude (43.63382606), Longitude (-89.866110801), X Coordinate (268798.875), Y Coordinate (4835196), and Structure Type (NO STRUCTURE).

Crash Scene

Table with crash scene details: First Harmful Event (DITCH), First Harmful Event Location (SHOULDER LEFT), Manner of Collision (00 - NO COLLISION W/VEHICLE IN TRANSPORT), Light Condition (UNKNOWN), Road Surface Condition(s) (SNOW), Roadway Factor(s) (ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)), Environment Factor(s) (WEATHER CONDITIONS), Weather Condition(s) (CLEAR), Animal Type, Relation To Trafficway (TRAFFICWAY - NOT ON ROAD), Crash Classification - Location (PUBLIC PROPERTY), Crash Classification - Jurisdiction (NO SPECIAL JURISDICTION), Tribal Land, Access Control (NO CONTROL), Special Study, Within Interchange Area (NO), Junction Location (NON-JUNCTION), Intersection Type (NOT AN INTERSECTION).

Unit Summary

Table with unit summary details: Unit Status (HIT AND RUN), Vehicle Operating As Classification (D CLASS), Unit Type (AUTOMOBILE), Vehicle Type (PASSENGER CAR), Operating As Endorsements, Total Occs (1), Train/Bus # Recorded, Total # Citations Issued (0), Total Trailers (0), Total HazMat Types (0), Insurance? (UNKNOWN), Direction Of Travel (NORTHBOUND), Pre Crash Tire Mark (checked), Speed Limit (45), Total Lanes (2), Most Harmful Event: Collision With (TREE), Special Function (NO SPECIAL FUNCTION), Emergency Motor Vehicle Use (NOT APPLICABLE), Traffic Way (TWO-WAY, NOT DIVIDED), Traffic Control (NO CONTROL), Traffic Control Inoperative/Missing (NO), Surface Type (BLACKTOP (BITUMINOUS)), Road Curvature (STRAIGHT), Road Grade (DOWNHILL), Truck Bus or HazMat (NO).

Table with vehicle details: Vehicle (AAW7768), License Plate Number (AAW7768), Plate Type (AUT - AUTOMOBILE), St (WI), Country of Issuance (UNITED STATES), Vehicle Identification Number (2C3AA53G45H127896), Make (CHRYSLER), Year (2005), Model (300), Color, Body Style (SD - SEDAN), Bus Use, Initial Contact Point (00 - NON-COLLISION), Vehicle Damage (15 - ALL AREAS), Extent Of Damage (DISABLING DAMAGE).

6TL0B4X4MQ

20-00015

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By INTERSTATE BP	
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors UNKNOWN	
	Driver Prior Action Other			
	Driver Actions SPEED TOO FAST/COND, FAILURE TO CONTROL			
01 01	Owner Name JENNIFER J DOMINGUEZ (608) 790-3889		Owner Address 1019 OAK ST BARABOO, WI 53913 , US	
	Sequence Of Events			
01 01	01	Event DITCH		
	02	Event TREE		
	03	Event		
	04	Event		
UNIT INDIVIDUAL	Individual			
	Driver		Citations Issued 0	Sex
			Date of Birth	Race
	Address		Driver License Number	
01 001	Safety Equipment		On Duty Crash	
			Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	RESTRAINT USE UNKNOWN	
	Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance		
Injury		Injury Severity NO APPARENT INJURY	Airbag NOT APPLICABLE	
Ejected NOT APPLICABLE		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT APPLICABLE
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source		
Distracted By Action				
Non Motorist		Striking Unit #	Location	

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Prior Action		
	Action		
	Action Other		To/From School
	Drug & Alcohol		
	Suspected Alcohol Use		Suspected Drug Use
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results
	Drug Type		
	Individual Condition NOT OBSERVED		
	01	001	